## PLANNING & ENGINEERING RESOURCES, INC.

225 Stewart Drive Merritt Island; Fl. 32952

April 6, 2021

Mr. Pete Hodges Marion County MSTU 2710 E. Silver Springs Blvd Ocala, Fl. 34470

**RE**; Inspection Services for Leonardo Estates

Dear Mr. Hodges,

We have inspected the above road-construction project and consider the project to be complete and constructed according to plan.

Asphalt should be monitored throughout the warranty period to ensure raveling, or repair failure dues not occur. The asphalt should be examined at the release of warranty inspection and the contractor shall remediate any areas as required. Additionally, irrigation of sod should be monitored and maintained to ensure it is fully established at the time of warranty.

Sincerely,

MA

Sheikh M. Hasan, PhD, PE Planning and Engineering Resources, Inc.

Planning - Engineering - Permitting