
X35
AIRFIELD PAVEMENT
CONDITION INDEX EXHIBIT
Statewide Airfield Pavement
Management Program
MARION COUNTY AIRPORT
FDOT
2021
RECONSTRUCT 300
X 100 LF OF
RUNWAY 5-23
PAVEMENT
REHABILITATE
4,300 X 100 LF OF
RUNWAY 5-23
PAVEMENT
NORTH
LEGEND
TYPICAL RUNWAY BRANCH ID
TYPICAL TAXIWAY BRANCH ID
TYPICAL APRON BRANCH ID
2020 PAVEMENT CONDITION INDEX
PCI 85-100 Good
PCI 71-85 Satisfactory
PCI 56-70 Fair
PCI 41-55 Poor
PCI 26-40 Very Poor
PCI 11-25 Serious
PCI 0-10 Failed
"SECTION ID"
"PCI VALUE"
RUNWAY LENGTHS DEPICTED IN THIS DRAWING ARE FOR PAVEMENT MANAGEMENT PURPOSES ONLY AND MAY NOT MATCH PUBLISHED RUNWAY LENGTHS. DRAWING NOT TO SCALE
6210
PCI = 75
6105
PCI = 68
4165
PCI = 57
4240
PCI = 85
4365
PCI = 82
110
PCI = 91
115
PCI = 32
6105
10
23