

Marion County License Review Board Meeting Agenda

Tuesday, April 9, 2024	5:30 PM	Marion County Main Training Room

"MEMBERS OF THE PUBLIC ARE ADVISED THAT THIS MEETING / HEARING IS A PUBLIC PROCEEDING, AND THE CLERK TO THE BOARD IS MAKING AN AUDIO RECORDING OF THE PROCEEDINGS, AND ALL STATEMENTS MADE DURING THE PROCEEDINGS, WHICH RECORDING WILL BE A PUBLIC RECORD, SUBJECT TO DISCLOSURE UNDER THE PUBLIC RECORDS LAW OF FLORIDA. BE AWARE, HOWEVER, THAT THE AUDIO RECORDING MAY NOT SATISFY THE REQUIREMENT FOR A VERBATIM TRANSCRIPT OF THE PROCEEDINGS, DESCRIBED IN THE NOTICE OF THIS MEETING, IN THE EVENT YOU DESIRE TO APPEAL ANY DECISION ADOPTED IN THIS PROCEEDING."

- 1. Invocation
- 2. Pledge of Allegiance
- 3. Roll Call
- 4. Adoption of Minutes of Previous Meeting
 - **4.1.** Marion County License Review Board Minutes March 12, 2024
- 5. License Review Contractors Incoming Exam & Reciprocity
 - **5.1.** Locksley Beckford Exam Carpentry
 - **5.2.** Charles Martin Exam Journeyman Electrician
 - **5.3.** Sean Adair Reciprocity Registered Electric
 - **5.4.** Sheldon Carroll Reciprocity Registered Plumbing
 - **5.5.** Joseph Frank Cotroneo III Reciprocity Irrigation
 - **5.6.** Dustin Matthews Reciprocity Registered Electric
- 6. Unlicensed & Licensed Contractors Liens
- 7. Old Business
 - **7.1.** LRB 2023-9 Bert Wampler v. Victor Lee Lecouris / A & R Heating and Air Inc

Licen	se Review E	Board Meeting Agenda April 9, 2024
	7.2.	LRB 2024-3 Ana Ortiz v. George M. Beck / Ecoview Windows & Doors of North Florida
8.	New Bus	siness
	8.1.	LRB 2024-4 Marion County Building Dept. v. Rickie Earl Glass / Ecoview Construction LLC
	8.2.	LRB 2024-5 Marion County Building Dept. v. Mark Clifton Norman / Mark Norman Construction Inc.
	8.3.	LRB 2024-6 Marion County Building Dept. v. Rickie Earl Glass / Ecoview Construction LLC
	8.4.	LRB 2024-7 Marion County Building Dept. v. Philip Thomas Dolfi / Custom Vinyl Systems Inc.
9.	Other	
10.	NOTATI	ON FOR RECORD

11. PUBLIC COMMENT



License Review Board

Agenda Item

File No.: 2024-14572

Agenda Date: 4/9/2024

Agenda No.: 4.1.

SUBJECT: Marion County License Review Board Minutes - March 12, 2024



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

Marion County License Review Board Minutes March 12, 2024

The monthly meeting of the Marion County License Review Board was held at the Growth Management Building, 2710 E. Silver Springs Blvd., Ocala, FL 34470.

The Vice Chairman called the meeting to order at 5:30 pm. An official recording of the meeting was made by the Marion County Building Safety Department with BIS recording software.

1. INVOCATION

2. PLEDGE OF ALLEGIANCE

3. <u>ROLL CALL</u>:

Board members present were: Jeremiah Bennett – 1st Chair, James Duryea, Fawn Singletary, Roger Sandor, John "Mike" Gartner, Jr., Zachary Curry Alternates – Alan O'Cull

Board members absent were: Lee Kitzmiller and Charles Stokes

Also attending: Antoinette Hernandez - Board Secretary; Ryan Arbuckle, Supervisor of Investigations/Licensing for Marion County Building Department; Michael Savage-Marion County Building Official; Michael Biganzoli – Manager – Inspections, Marion County Building Department; Valdoson Shealey, Assistant County Attorney for Marion County.

4. ADOPTION OF MINUTES FROM PREVIOUS MEETING:

James Duryea moved to adopt February 13, 2024 Minutes. Roger Sandor seconds. All in favor. Motion passed unanimously.

5. *LICENSE REVIEW OF CONTRACTORS*:

Incoming Contractors through Letter of Reciprocity: James Duryea moved and Roger Sandor seconds to approve the list as presented. Motion passed unanimously.

<u>Applicants to take G.I.T.S Exam</u>: James Duryea moved and Roger Sandor seconds to approve the list as presented. Motion passed unanimously.

6. <u>LIENS FOR UNLICENSED & LICENSED CONTRACTORS</u>: None.

Empowering Marion for Success

marionfl.org

7. OLD BUSINESS:

LRB 2023-9 Bert Wampler v. Victor Lecouris / A & R Heating and Air Inc.

Ryan Arbuckle – present - sworn, provides update. Complainant - Bert Wampler – present – sworn – provides update. Contractor – Victor Lecouris – not present.

Final not completed as of yet.

James Duryea motions to postpone final decision to the next License Review Board Hearing in April. Roger Sandor seconds the motion.

The motion passed unanimously.

Case postponed to April 9, 2024 License Review Board Docket.

8. <u>NEW BUSINESS:</u>

LRB 2024-3 Ana Ortiz v. George M. Beck / Ecoview Window and Doors of North Florida

Ryan Arbuckle present – sworn – presents case. Complainant – Ana Ortiz – present – sworn - provides testimony.

Contractor - George Beck – present – sworn – provides testimony Chris Monk – witness for contractor – sworn - provides testimony. Joseph Snowden – witness for contractor – sworn - provides testimony.

Complainant stated she will allow George Beck / Ecoview Window and Doors of North Florida to come back on her property to fix, have final inspections completed, and permit COED before the next License Review Board Meeting. Ana Ortiz states she does not want Joseph Snowden on her property.

Contractor stated that he will be able to meet with the Building Department for instruction on what is needed to be completed. In addition, will able to fix, have final inspections completed, and permit COED before the next License Review Board Meeting.

James Duryea moves to hold final decision for a period of 30 days to have contractor meet with the Building Department for direction, fix, have final inspections completed, and permit COED before the next License Review Board Hearing.

Roger Sandor seconds the motion.

The motion passed unanimously. The case is continued to the April 9, 2024 License Review Board Hearing.

9. OTHER BUSINESS:

Michael Savage – Building Official states for the record that Marion County will no longer be conducting RVI (Remote Video Inspections) Inspections for windows.

The meeting adjourned at approximately 6:58 P.M. The next scheduled meeting will be Tuesday, April 9th, 2024 at 5:30 p.m.

10. NOTATION FOR RECORD: None.

11. <u>PUBLIC COMMENT</u>: None.

Respectfully submitted,

Lee Kitzmiller / Chair

Antoinette Hernandez / Secretary

cc: Marion County Board of County Commissioners - Assistant County Attorney Marion County Board of County Commissioners Record Clerk



License Review Board

Agenda Item

File No.: 2024-14561

Agenda Date: 4/9/2024

Agenda No.: 5.1.

SUBJECT: Locksley Beckford - Exam - Carpentry



License Review Board

Agenda Item

File No.: 2024-14563

Agenda Date: 4/9/2024

Agenda No.: 5.2.

SUBJECT: Charles Martin - Exam - Journeyman Electrician



License Review Board

Agenda Item

File No.: 2024-14557

Agenda Date: 4/9/2024

Agenda No.: 5.3.

SUBJECT:

Sean Adair - Reciprocity - Registered Electric



License Review Board

Agenda Item

File No.: 2024-14559

Agenda Date: 4/9/2024

Agenda No.: 5.4.

SUBJECT: Sheldon Carroll - Reciprocity - Registered Plumbing



License Review Board

Agenda Item

File No.: 2024-14678

Agenda Date: 4/9/2024

Agenda No.: 5.5.

SUBJECT: Joseph Frank Cotroneo III - Reciprocity - Irrigation



License Review Board

Agenda Item

File No.: 2024-14558

Agenda Date: 4/9/2024

Agenda No.: 5.6.

SUBJECT: Dustin Matthews - Reciprocity - Registered Electric



License Review Board

Agenda Item

File No.: 2024-14565

Agenda Date: 4/9/2024

Agenda No.: 7.1.

SUBJECT:

LRB 2023-9 - Bert Wampler v. Victor Lee Lecouris / A & R Heating and Air Inc



License Review Board

Agenda Item

File No.: 2024-14567

Agenda Date: 4/9/2024

Agenda No.: 7.2.

SUBJECT: LRB 2024-3 Ana Ortiz v. George M. Beck / Ecoview Windows & Doors of North Florida



License Review Board

Agenda Item

File No.: 2024-14209	Agenda Date: 3/12/2024	Agenda No.: 8.1.	

SUBJECT:

LRB 2024-3 Ana Ortiz v. George Beck / Ecoview Windows and Doors of North Florida

LRB 2024-3

COMPLAINT

PACKAGE 10f1- Opening

Additional packages (3)

Filed by: Ana Ortiz 352-454-2300

NOT COUNTY, ALOR	Marion County Board of County Commi	issioners LRB 2024-3
	Building Safety - Licensing	
TA GOD WE TRUST	2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400	
Action Order	FOR OFFIC	CE USE: 2024-3 LRB Case #
Code Case #	·	
	COMPLAINT	FORM - PART I
/		
D Buildi	ng Code Issues/Permitting Issu	ues Fill out Part I
Contr	actor/Licensing Issues	Fill out Part I and Part II
	TANT INFORMATION: Ama Ortiz	11-21-23 DATE OF YOUR CALL or VISIT: 1530 (415)
		Ocala FL 34481
Daytime (8a	m-5pm) Phone Number:	Cell Phone Number: 352-454-2300
Email (if you	would prefer electronic corresp	pondence): 10 boyuma Baol.com
		efers to: J870 SW 1150 St Ocala FL 3448,
Complaint is	about: (circle)	
Mobile Home	e Building Addition	Department Staff Member
Shed	Contractor	Other:

.

SOL COUNTY, ALONE

Building Safety . Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400

NATURE OF COMPLAINT

NOTE: If the subject of your complaint is a contractor licensed by the State of Florida, a copy of this form will be sent to them, pursuant to 455.225(1) Florida Statutes.

Please provide the date(s) of occurrence and as much detail of the incident as you can. If applicable, provide <u>copies</u> of any quotes, invoices, or correspondence.

Please see attached complaint and supporting Documents aboto; and Centract

IF FILING A COMPLAINT AGAINST A LICENSED CONTRACTOR:

You must sign and date that you have read and understood the following statement:

<u>Florida Statute (837.06) False Official Statements</u>: Whoever knowingly makes a false statement, in writing, with the intent to mislead a public servant in the performance of his official duty shall be guilty of a misdemeanor of the second degree.

Signature (Required to file complaint)

11-23-23 Date

Page 4 of 7



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400

CONTRACTOR COMPLAINT FORM - PART II

SUBJECT OF COMPLAINT: (Fill in only if complaint is against a Licensed Contractor)

Name: Ecourew Windows and Doors of NFL (Chris Monk)
Business Name: 5105 Philips Huy #5
Address: JACKSMUILLE FL 32207
Phone: 904-281-0067
License Number:

In addition to your written statement in **PART I**, please document your contractual relationship with the Contractor and provide evidence of supporting allegations. Answer as many questions below as possible to assist us in investigating your complaint.

PROVIDE COPIES OF ANY OF THE FOLLOWING IF AVAILABLE:

- 1. Proof of the contract between you and the contractor
- Proof of payment to the contractor cancelled checks (front and back), receipts, closing statements, etc.
- Liens, judgments and notices to owner, including copies of related work orders, bills, and subcontracts Warranties.

I aph complaining in my capacity as the:

[1] Homeowner [1] Subcontractor [1] Building Department [1] Contractor

Check the category that best summarizes the work that was performed or what the contractor did for you:

[] Built house [] Remodeled house [] Built addition to a house [] Commercial roof work

[] Re-roofed the entire house [] Built a commercial structure

[] Remodeled or built/an addition to a commercial structure [] A/C or heating work at the residence

[] Installed a pool [V] other, please explain Wendows

Please circle the letter(s) for the category that best describes your basic complaint:

- A Poor workmanship by contractor
- B. Job finished, but contractor will not correct problems
- C. Roof leaks, and contractor will not repair
- D. Contractor failed to pay subcontractors/suppliers
- E. Contractor taking an unreasonably long time to do the job
- F. Contractor abandoned job
- G. Financial dishonesty/misconduct by contractor
- H. Contractor exceeded the scope of his/her license

Page 5 of 7

COUNT OD WE T

Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400

PLEASE ANSWER ALL OF THE FOLLOWING QUESTIONS IN THIS SECTION. IF A QUESTION DOES NOT APPLY TO YOUR COMPLAINT, WRITE "N/A".

BASIC BACKGROUND DATA:

BASIC BACKGROUND DATA:
1. Is the work site located inside [] City limits or [] County limits?
2. What is the street address and city of the work site? $\frac{PP70}{5W} \frac{5W}{115} \frac{115}{5W} \frac{115}{344P1}$
3. These questions may relate to the contractor's building code compliance:
Was the contract in writing? ['] YES [] NO
Contract Price: \$ <u>11 128 a</u> Date of Contract: <u>4-6-23</u>
Approximate Date that Work Began:
Approximate Date that Work Began: <u>6-16-23</u> Approximate Date that Work Ended: <u>Not funished</u>
 Was the permit obtained from the Marion County Building Department? [] YES [] NO If NO, was a permit required? [] YES [] NO
5. What was the name of the person who pulled the permit? <u>George M. Beek</u>
6. What was the permit number? 2023052164
7. Was the permit obtained on time? [\sim] YES [] NO
8. Was the Certificate of Occupancy issued? [] YES [] NO
9. If the Certificate of Occupancy was not issued, explain why.
10. Were any inspections missed or performed late? [] YES [] NO

11. Was the Final Inspection passed? [] YES [] NO



Building Safety . Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400

- What was the total price paid to the contractor? \$ Damp gyment 1500. 00 + 3 the method.
 If you hire another contractor what is the article stimates from the stimates
- 4. Were you obligated to pay any subcontractors or suppliers that the contractor was required to pay? []YES[/NO
- 5. Are there any unpaid bills owed to subcontractors or suppliers which the contractor was responsible to pay for? [] YES [] NO
- What is the total amount of the unpaid bills? \$_____
- 7. Did the contractor sign any statements stating that the bills had been paid? []YES [] NO
- 8. Has the contractor been terminated? []YES[]NO wotyet Legal matters
- 9. Has the job been finished by you or a new contractor? [] YES [\sqrt{NO}

WORKMANSHIP:

1. List the three (3) most serious items of your complaint and/or those which your contractor will not repair. Use a separate sheet of paper if necessary.

5122 Windows - Style winde manut Used Vrma Knonghip - Damage to my home Unyle

- 2. Has the contractor offered to repair any and all damage that was caused? [] YES [] NO
- 3. Has the contractor made an attempt to repair the damage? [VYES[]NO 7 + Imys If YES how many times? Keep getting worst If YES, how many times? _____
- 4. Have you had another licensed contractor, architect, or engineer inspect the work? IVIYES []NO If YES, list the name of the other licensed contractor, architect, or engineer who performed the Inspection: <u>See reports enclosed</u>

MARION COUNTY Building Safety Department BUILDING PERMIT

PERMIT TYPE: JOB DESCRIPTION:	952164 M18WDM18 WINDOW/DOOR REPLACING 12 WINDOWS 3 8870 SW 115TH ST	 EXPIRATION: 1	5-18-2023 1-14-2023 79.15	
OWNER INFORMATION: ORTIZ ANA 8870 SW 115TH ST OCALA FL 3448150	-	CONTRACTOR INE ECOVIEW WIND 5105 PHILIPS STE 5 JACKSONVILLE	DWS & DOORS (HWY	OF NORTH FLORIDA
PARCEL NUMBER: 7	008-005-008	SUBDIVISION:	OAK RUN NEIG	HBORHOOD 08B
LOT: 8 TOTAL SQFT: SETBACKS FRONT:	<u>block:</u> 5 <u>rear:</u>	RANGE-TOWNSHIE NOC: AFFIDAV LEFT:	<u>P-SECTION:</u> IT SUBMITTED	20 - 16 - 36 <u>RIGHT:</u>

This permit will become null and void if construction is not started and a passing inspection obtained within six (6) months.

Notice: Demolition Permits are active for only (60) sixty days from the date of issuance.

In addition to the requirements in this permit, there may be additional restrictions applicable to this property that may be found in the records of this county, and there may be additional permits required from other governmental entities such as water management districts, state agencies, or federal agencies. s:553.79(10),F.S.

It is the responsibility of the owner or Asbestos contractor to comply with the provisions of s.469.003 of the Florida Statutues and to notify the Department of Environmental Regulation of his/her intentions to remove asbestos, when applicable, in accordance with state and federal laws.

CALL BEFORE YOU DIG: 1-800-432-4770

WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. A NOTICE OF COMMENCEMENT MUST BE RECORDED AT THE MARION COUNTY CLERK OF COURTS AND A CERTIFIED COPY FILED AT THE BUILDING DEPARTMENT, BEFORE THE FIRST INSPECTION. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT. (F.S. 713.135)

ADDITIONAL PERMIT INFORMATION:

5/16/23 SENT PAYSLIP FOR DEPOSIT ONLY-AH

For Inspections schedule online: https://www.marioncountyfl.org/inspections or call (352) 438-2400

INSPECTION JOB CARD - MARION COUNTY, FLORIDA TO SCHEDULE AN INSPECTION, PLEASE VISIT OUR WEBSITE AT WWW.MARIONCOUNTYFL.ORG/INSPECTIONS

TO SCHEDULE A PARTIAL INSPECTION PLEASE CALL 352-438-2400 TO SPEAK WITH A PERMIT TECHNICIAN

PERMIT NBR:	2023052164	MASTER NBR:	2023052164	<u>ISSUED:</u> 5/18/	2023
JOB DESC.: JOB LOCATION:	REPLACING 12 WINDOWS SIZE FOR 8870 SW 115TH ST	R SIZE FL5167.1 ^P	ERMIT TYPE:	M18WDS M18 WINDOW C/O-REMODE	
SUBDIVISION: CONTACT NAME:	1332 OAK RUN NEIGHBORHO	OD 08B	LOT 8 PHON	<u>BLOCK</u> 5 E: 904-281-0067	
D.B.A.	ECOVIEW WINDOWS & DOORS OF NO	ORTH FLORIDA	NOC		
<u>SETBACKS</u> <u>FRONT:</u>	REAR:	LEFT:		RIGHT:	
SPECIAL: ELEC. UTIL:			FLOOD ZONE	<u>.</u> x	
REQ DESCRIPTI		REQ DESCI	RIPTION	RESULT	
108 108 FINA 113 113 FRAM	L STRUCTURAL				

CALL BEFORE YOU DIG: 1-800-432-4770

NOTICE: Your property may be subject to private deed restrictions which may affect construction WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. A NOTICE OF COMMENCEMENT MUST BE RECORDED AT THE MARION COUNTY CLERK OF COURTS AND A CERTIFIED COPY FILED AT THE BUILDING DEPARTMENT, BEFORE THE FIRST INSPECTION. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT. FS 713.135

MARION COUNTY

Transaction Number	Transaction Date	Posting Date	Payment Slip Number	Status
1200702	5/18/2023	5/18/2023	PT 2023052164	POSTED
Address: 8870 SW Owner: ORTIZ ANA			PAYOR :	
Applicant: GEORGE	DS Job Desc: REPLACIN M BECK DWS & DOORS OF NORTH FL		FOR SIZE FL5167.13/51	
Cust. WO#: Swr Meter: Wt.	r Meter:			

Fee Information

Fee Code	Description	GL Account	Amount Waived
BD20-48	BD20 PERMIT FEE (048)	EP318322-322010	\$48.00
DCAFEE	DCA SURCHARGE 2010	EP000000-208303	\$2.00
DPRFEE	DBPR SURCHARGE 2017	EP000000-208303	\$2.00
B093	PERMIT DEPOSIT CREDIT	EP318322-322010	\$-45.00
	······································		

Total Fees

\$7.00

Payment Information

Pay Code	Account / Check Number				Amount
MC	9841				\$7.00
			Total Cash		\$0.00
			Total Non Cash		\$7.00
			Grand Total		\$7.00
User:	c	ashier: BU341CM3	Location:	1	Station: DP20

Memo:

MARION COUNTY **INSPECTION HISTORY** SHEET

MASTER NBR VALID NBR TYPE FCC ISSUED APPROVED INSPECTOR 2023052164 PERMIT NBR M18WDS 434 5/18/2023 5/18/2023 BU341MB3 2023052164 164 JOB DESC: REPLACING 12 WINDOWS SIZE FOR SIZE FL5167.13/5179.15JOB PHONE: 904-281-0067 OWNER NAME: ORTIZ ANA \$3,925.00 JOB JOB VALUE: LOCATION: 8870 SW 115TH ST SUBDIVISION: 1332 OAK RUN NEIGHBORHOOD 085 BLOCK 5 CONTACT NAME: CONTACT PHONE: LOT 8 21872 DBA: ECOVIEW WINDOWS & DOORS OF NORTH FLORIDA 904-281-0067 CERT. NBR: TRS: X SEWER COA TAZ FLOOD ZONE WATER 408 4 SETBACKS 2,023,052,164 FRONT: REAR: LEFT: RIGHT: SPECIAL: NOTES: 5/16/23 SENT PAYSLIP FOR DEPOSIT ONLY-AH SUBCONTRACTORS CERT NBR SUB STATUS START DATE END DATE STATUS DBA SUBPERMITS STATUS TYPE CERT NBR PERMIT JOB DESC DBA 2023052164 INSPECT M18WDS 21672 ECOVIEW WINDOWS & DOORS OF NORTH FLORIDA AMOUNT REINSPECTION FEES AMOUNT PAID DATE PAID DUE FEE CODE DATE DUE DESCRIPTION/REMARKS PRI REQ DATE CODE RES DATE INSPECTOR REO CLASS STATUS 108 ST 108 FINAL STRUCTURAL 0 10/3/2023 See inspection info. 2 PM OR LATER Mike Biganzoli to perform this inspection. 0 10/3/2023 113 ST 113 FRAMING THIS IS A REINSPECTION 0 7/12/2023(81) 7/12/2023 BU341CC2 108 ST **108 FINAL STRUCTURAL** Order of inspections FBC 110.3 113 113 FRAMING 0 7/12/2023 (81) 7/12/2023 BU341CC2 ST Need to verify max window to frame gap does not exceed Product Approval. windows to small for opening owner very concered showed pictures windows not installed correctly 1/8 " gap around windows 0 8/28/2023 (81) 8/28/2023 BU341EV 113 ST 113 FRAMING See inspection info. MB3 Site visit completed on 8/25/23 FBC 609.3.1 Window installation. -over 1"gap around windows. Had contractor pull back outer flashing of front bay window and side.. Revealed no window bucks or shims. Solid foam around entire window. All windows need to have exterior flashing over flanges-to prevent water penetration. 9/28/2023(81) 9/28/2023 BU341JD1 113RVI ST 113-RVI FRAMING Ý 2023052164 NOTE: RAN OUT OF TIME AT THE END OF THE DAY. 1. WINDOWS INSTALLED WERE FIN-LESS REPLACEMENT WINDOWS HOWEVER, I WAS ABLE TO MAKE CERTAIN AMOUNTS OF VISUAL INSPECTIONS IN PERSON AND VIA FACETIME, THOUGH IT WAS REQUESTED AS AN RVI INSPECTION. 2. ALL WINDOWS INSTALLED WERE REMOVED AS INSTRUCTED BY MYSELF AND SELF ADHESIVE TAPE WAS The Sau INSTALLED ON THE BOTTOM OF THE WINDOWS I SAW AND AT LEAST 8 TO 12 INCHES ALONG THE BOTTOM OF THE FRAME ON BOTH SIDES COMING UP AS A FLASHING TO PROTECT THE EXPOSED WOOD. IT EXTENTED OUT TO THE BOTTOM 2X4 THAT THEY WERE USING AS A BORDER AROUND THE WINDOW THAT WAS TO BE COVERED WITH METAL FLASHING AS A TRIM PIECE AROUND THE ENTIRE WINDOW AND CHALKED AS PER INSTALLATION Ices wit act in a continue our of the arwant water mighting MARION COUNTY Printed on: 10/3/2023 12:30:20PM CD-Plus for Windows 95/NT CDPR2036 Page 1 of).~

سل مد

1 00 er 165 5 ・ズ



Ecoview Windows & Doors PRE-EXISTING CONDITIONS

This form must be signed by the customer

Customer Name: HOTTIZ Prosp#:_____ Sale Date: _____

The purpose of this form is to identify any conditions or damage to the customer's home or property that was existing PRIOR to the commencement of work.

- Inspect the driveway and any walls (exterior and interior) that will be impacted by the installation
- In each instance, list the location and description of the damage in the space below
- Record the results of the Lead Paint Tests in the space provided below

IDENTIFY DAMAGE & Photo With Company Cam			
DRIVEWAY	(Description of Damage; e.g. cracks, indentations, paint stains, etc.)		
·	N a		
	(Description of Demonstry on a broken or demond fightering point on foundation, etc.)		
EXTERIOR WALLS FOLIAGE	(Description of Damage; e.g. broken or damaged fixtures, paint on foundation, etc.)		
FOLIAGE			
INTERIOR WALLS	(Description of Damage; e.g. cracks, nail pops, water stains, etc.)		
	\mathcal{N}_{λ}		
	LEAD PAINT TESTING		
	r.		
	- <u>N</u>		
Test Kit Manu			
	if applicable (Window # / Specific area of home)		
Test Results: Is	Lead Present? YES NO		
	check appropriate box above		
Test Kit Manu			
	if applicable (Window # / Specific area of home)		
Test Results: Is	Lead Present? YES NO		
/	check appropriate bok acove		
Test Kit Manu	afacturer Test Kit Lot # Test Date Test Site if applicable (Window # / Specific area of home)		
Test Results: Is	Lead Present? YES NO		
	check appropriate to+ appring		
By my signature b	elow, I acknowledge that the conditions listed above existed prior to the commencement of		
my project.	4 -		
my project.	All the second as a second		
	Refuse this is a mass 6-16-23 CUSTOMER SIGNATURE DATE		
	CUSTOMER SIGNATURE DATE DATE		



5105 Philips Hwy, STE 5 Jacksonvite FL 32207

904-281-0067 Fax 904-374-1536 www.Eccl.ewNFL.com

Certificate of Completion

Please read before signing:

EcoView Windows & Doors of North Florida obligation after execution of this statement shall be limited to the terms of the labor and material warranty. After signing this completion statement, EcoView Windows will not make any cosmetic changes on this job. Do not sign unless the job is completed and cleaned to your satisfaction!!! This is to certify that all labor was completed satisfactory to the conditions of the contract at the residence of:

Homeowner: Ana Ortiz	Job #:	2012216
Address: 8870 SW 115th St Ocala, FL 34481	Contact #:	(352)454-2300

For Installs(s): Ariol Doku

	Were there any parts damage that needs to be ordered? [] Yes $\mathbf{k}\hat{\mathbf{j}}$ No			
	If yes, please take a picture of the sticker(s) and email it to: YourEcoViewTeam@EcoViewNFL.com			
	Were there any other issues during installation that we need to know about? 1000 Yes [] No			
	If yes, did you correct them? [x] Yes [] No			
	Did you take after completion pictures? [2] Yes [] No			
	Did you show the customer how their windows operate?			
	Job Contract: \$10,023.00 Deposit: \$1,000.00 Due at Completion: \$9,023.00			
	Payment of balance Due: [] Check [] Financed [] Cash \$			
	[] Credit Card on File. Verify Last 4:			
	[] Charge a different Card (Installer: Call the office with the card info and office will process.) Called Chris Owder - Goe install mgr said he was ok with This muss seen Customer Signature on Photos. Refused to some no draw of money unitil all demages are corrected from			
	Comments This jag is a mass damed France Ann 101+ cut cuin			
<u>.</u>	all's misalisned and churched over amounts - Thought of the men			

LRB 2024-3

COMPLAINT PAckage lof 3

From Cha Ortiz

357-454-2300

DATE: 11/22/23

COMPLAINANT: ANA ORTIZ WARGA 8870 SW 115TH ST OCALA FL, 34481 LOBOYUMA@AOL.COM 352-454-2300

DATE: 11/23/2023

COMPLAINT AGAINST: CHRIS MONK & DARYL PHILLIPS-ECOVIEW WINDOWS AND DOORS OF NFL 5105 PHILIPS HWY #5, JACKSONVILLE, FL 32207 904-281-0067 #PERMIT #2023052164 ISSUED: 05/18/23 LICENSE #L15000082633 ECOVIEW CONTRACT #2012216

Dear Consumer Complaint Division,

On April 18, 2023, I signed a contract to have (8) windows replaced in my home. My home originally had outside mount nail fin windows and the home has vinyl sided with J-Chanel and framed window exterior. ECOVIEW Windows & Doors, NFL, (Brandon) came to my home and measured the inside opening of my window and selected the window he pointed out as an upgrade FL 5167.13 & FL5179.15 and that would add to the home's esthetics and value. He stated that another employee would schedule a date and time and to conduct a confirmation measurement prior to windows being ordered. He gave me a time frame of 6-weeks to complete the project minus any delays with the ordering/receiving of the windows from their supplier and obtaining permits. Unfortunately, this did not occur. Some four weeks passed and I had not heard from the company I reached out to their office inquiring when the process would begin. Communication with this company consisted of leaving messages and being told someone will call me back. I left Brandon numerous messages and several time spoke with him. He stated he forwarded the information to his office scheduler. Again several weeks passed and I elevated my inquiry and spoke to Chris Monk, who I later learned was one of the owners. He scheduled a date and time to dispatch an installer to verify the measurements, however on that date no one showed up. I again called the office and asked what was going on. Finally, he scheduled another date and Brandon the sales representative arrived. Again he measured the windows from the inside except for the garage window because he could not gain access from the inside. (Note: Brandon is a sales man with little to no training in window installation.)

On June 16, 2023, a crew of installers came to my home. They spread out and began pulling out every window, I tried to speak with them, but none of them claimed they spoke English. I was unable to keep tack of that many workers in different areas. I later learned this crew were sub-contractors, not employees of ECOVIEW.

I heard pounding from inside my home and exited to see what was going on. I observed one worker using a pry bar at the bottom of the windows. Both from the outside and inside, trying to get the window out. They had laid open the entire surrounding areas of my windows by using a utility knife to cut the chalking and the water membrane barrier that protected the exterior wood wall from moisture. I also observed them pulling out all the window insulation. I assumed at the time that this would be replaced. I observed large amounts of exposed wood at this point and asked about this, as this process repeated window to window throughout my home. After they began putting the new windows I saw the vinyl J-chanal twisted, torn and large gaps under the windows. In some place the gaps were in excess of 2 inches. I saw screws through these excessive gaps not secured into wood but passing through the large voided areas between the window frame and the exterior house frame. Again I questioned the integrity of the window and the large gaps. I was told that it meets industry standards, no worries we will do a good job. I walked to the side of my home to take garbage out and noticed a worker in the process of adding metal flashing around the garage window. The window had large gaps around the window and was crooked by 3/8 inch. I brought this to his attention and he also stated, industry standards, no worries. He continued to frame in the crooked window. I stopped him and told the worker that this was not acceptable. I immediately called the office and reported what was going on. About 1/2 hour later an individual identifying himself as Joe called and stated the reason this happened is because of the drywall on the inside would not allow the window to go in level and his crew are not permitted to cut or trim the dry on the inside of the home. I again called the main office to seek further assistance. By this time the worker had framed in the crooked window and was on to another window. I'm not sure who finally became involved from their office, but someone called and I later saw the worker inside the garage and he cut the dry wall back and reinstalled the window, still not level at this point. Later I learned that Joe was the installation supervisor for this job. He was not on the job site but making the calls behind the scene. Throughout the process I took photos of what I was seeing and voiced my concerns.

I reached out to my neighbor Marshall Landesman and asked him to come over and observe what was going on and explained that I was concerned. Marshall came over and he too expressed his concerns to me and the crew. He remained here until the crew stated they were finished and we all walked around. The absolute mess at every window was obvious. Bad framing, damaged framing, excessive caulking, debris all over, damaged J-Chanel, windows to small for the openings. I told the crew that this was unacceptable. They showed no concern and said the job met industry standards. Then the crew spokesperson stated they were finished and then presented me with a Certificate of Completion form to sign. I refused to sign the form and made notes at the bottom of what I saw that was unacceptable *that I understood at the time*. By this time they had covered over the windows with large metal flashing, bent, dinged, scrapped, twisted and then added an additional plastic 1 inch strips trying to fill the large gaps. (Note: they did not call for a frame inspection) My neighbor Marshal was here when this occurred and he too walked around and pointed out a host of issues with the workmanship and issues concerning the gaps, and that the windows do not fit, the framing and damage to my home. At this point it became apparent that the windows were too small for the openings creating the hideous mess at my home. I called and spoke to Chris Monk regarding the window size and other defects and

damages seen. He stated that these are replacement windows not new installs so it's different that I do not need all the house wrap that the frame acts as the water barrier. I reached out to Marion County Building Department at this point.

Later Chris Monk called and told me he would resolve the items seen in the photos that I sent him via text, and that he was sending his very best installer (Joe). Shortly thereafter Joe called me to arrange a date and time. He said it would not take him but a quick minute to make corrections. I asked him if he saw the photos sent to Chris Monk, he replied, "I did, they did a great install." I called Chris Monk back and told him what his best installer said and that was not any assurance that he would correct this mess. He assured me he would talk to Joe and we would all be on the same page.

On July 5, 2023, Joe the supervisory installer arrived and said that overall the job was great. He walked around and then recommended that he just extend further the metal flashing to cover all the cosmetic issues and that would be better for me as it's an additional layer of water protection. He spent the remaining of the day here and only added wider metal flashing over defected metal flashing and the defect areas. This only increased the eye sore without addressing the concerns ECOVIEW and now Joe their best installer continued to conceal the deficiencies behind the flashing.

Throughout the process I reiterated my concerns to Chris Monk and Joe. Joe kept insisting that all protocols were taken according to the FL Product approval number and they went above and beyond by adding additional screw. He tried to convince me window replacement have different requirements and they had exceeded the requirements. Again, I reached out to Marion County Building Department and sent them photos. ECOVIEW called for an inspection of the job. On July 12, 2023, inspector Cook failed (2) both the frame and structure inspection, as ECOVIEW failed to call for a frame inspection prior to sealing the windows. Note: Joe and all the workers *stated they have never called for frame inspections for any of their jobs* and that this is "Bull**it." They expressed that this was ridiculous and over kill and their company would deal with this inspection issue at a later date. Joe also insinuated the only reason that the inspection failed was due to my unreasonable demands and involvement and not letting them do their jobs.

This behavior and the condition of my home urged me to reach out to the Marion County Building Department yet again. I also reached out to Building Department in Tallahassee. I began to research the Windows' product approval requirements to better understand what I was seeing and what I was told by ECOVIEW. I again forwarded photos to Chris Monk the owner of ECOVIEW, Marion County Inspector and the Engineer who certified the Product Approval Code. I quickly discovered that ECOVIEW installed an inside mount window to replace my outside mount windows which reduced the size of the window pane and was the reason for the large gaps around the exterior windows and why ECOVIEW put in excessive oversized white metal flashing to conceal all the deficiencies. In addition, the photos I took from the original installation revealed that ECOVIEW failed to add bucking strips and shim to provide adequate fastening (screw in wood) strength as required in the Product Approval Code. Also, that gaps exceeded what is required by code. The chalking they used to seal the windows was in excess of 2 inches to cover the gaps and then they pressed in a piece of 1 inch plastic strip in the center of the gap and used more caulking to keep it attached. The gaps were so large that their standard 1 inch fill strip wasn't large enough. Caulking oozed out the sides of the strip and smeared on the vinyl j-chanal and house vinyl. I was livid at this point and began to send photos of every window to Chris Monk. My home looked terrible. The quality of work was below contract requirements and homeowners' expectations and below trade standards and building code requirements. I also reached out to Marion County Building & Permits and spoke with a woman. She told me to forward the photos to the manager. Later, Mike Biganzoli the manager reviewed the photos and I had an opportunity to speak with him. He stated that the inspection failed and they must correct the issues noted by the inspector. The only problem is, when the inspector came, he could not see inside the frame area, as ECOVIEW had already sealed the window to conceal the gaps.

To date, I have provided seven opportunities to ECOVIEW properly identify the cause of the gaps and make correct defective work. After numerous attempts on the part of ECOVIEW Windows and Doors, they have failed or refused to properly identify and correct deficiencies. They continued to performed subpar installation, insulation, and below standard workmanship, they installed the wrong size and style mounted windows creating a host of other issues/damages. They refused to order the proper style and mounted window claiming their installation was within guidelines.

On August 25, 2023, Marion County Inspector Vogt came to my home and with an ECOVIEW employee. Joe from ECOVIEW was supposed to be there and did not call me. Chris Monk later told me Joe was sick and he was sending someone else. The ECOVIEW company sent another employee out to meet with the inspector. This was his first day on the job and had no idea what he was doing as he had no experience (Per Him) in the window field. The inspector had him remove the metal flashing to expose yet another layer of metal flashing. When the 1st layer of metal flashing was removed water was observed dripping inside and also revealed yet another layer of metal flashing which the water was collecting and dripping from. The ECOVIEW employee turned and stated to the inspector, 'I didn't do this job, this is my first day on the job.' He then removed the second metal flashing to expose the frame for the inspector, This inspection failed because of in excessive 1/8 gaps (Gaps were 2-2 ½ inches), no filler wood, no shims and improper installation.

On 9/28/2023, ECOVIEW Window again came to my home and Joe was supervising the job and a two man crew. From the very beginning he instructed his crew that they were not pulling any window regardless what the homeowner or the Building Department said. He remained on the job for about 1 hour and left the job site. He was annoyed about the gaps and the missing house wrap and insisted that only the bottom inner ledge needs sealed and that the remaining wood did not need any covering and that's the directions he gave his crew. Note the exposed wood around

the window was damaged when original crew cut the wrap off the house to remove the window up to the J-Chanel. In addition he instructed them to add bucking strips in the attempt to fill the large gaps without removing the window. Note: Joe the site supervisor at this point still refused to pull the windows to correctly add the bucking strips. The purpose of the bucking strips and shims are to provide a solid foundation for the screws to properly be embedded in enough wood to provide stability and integrity. What they did was cut short pieces of board and slide them into the gap butting up against the screw that held the window in. I took a video of this and it clearly shows the improper methods and poor workmanship. In the video it shows Joe using a nail gun securing the buck strips to the exterior inner frame. The screws securing the window had over a 1 ¹/₂ inch voided area between the window and the frame. I brought this to Joe's attention and he flew off the handle. I called Jessie the inspector who had told me Joe and he already did a remote inspection and it looked ok. I told him what I saw and asked him to come physically to my home. When Jessie the Marion County Inspector arrived to my home we went to the livingroom window and he was able to pull out the short cut bucking strip. He verified that what Joe was doing is not the proper way to install a bucking strip. After that Jessie called Joe, and instructed him that the windows need pulled and a full width bucking strip and shims need to be added and then the screw through the window frame through the bucking into the house frame was the proper installation method. At that point Joe already left the job site to get moisture barrier tape. I was standing next to Joe's crew when he called and heard him yell, pull the damn Fu**ing windows. This was now about 2:30 in the afternoon. His crew began to pull every window out at one time exposing my entire home to the elements at this late time. When Joe arrived back I asked him not to pull windows at one time, just two and complete. He yelled at me that if they were here until midnight that's what is going to happen, because he's done with this and he wasn't coming back. I had to call my neighbor Representative to get permission to have workers here after 7:00 p.m. There shortly after night fall and his crew were forced to work using their cell phone flashlights to install my windows, frame and caulk. Note the photos that show a horrific mess. In addition, the next morning I noticed tobacco spit on my house just outside my bedroom door. Joe was the only one chewing tobacco. The inspection Jessie preformed that day also failed because Joe added the flashing framing the window in again. I specifically asked his about the frame inspection. He told me he knew what he was doing and did not need me to tell him how to do his job.

On 10/3/2023, Mike Biganzoli came to inspect the job and failed it for framing and structure, because ECOVIEW sealed the windows again and Joe refused to come back out.

On November 2, 2023, the inspection was canceled by Mike Biganzoli. To date the project has failed 6 inspections by the County for framing and structure defects.

On November 12-13, 2023, Chris Monk, Travis and Zack came to my home to make repairs. From the onset Zack who is a sub-contractor stated that he could only work with what he has. He also told Chris Monk and me that the installation defects were because the windows were the wrong size and mount. It was noted that when they pulled the windows the excessive amount of caulking around the frame squirted into the interior of my hose. Zack worked two days with Chris and Travis to reinstall the water membrane and try to correct the hideous framing and gaps. However, he did not pull back or loosen the J-chanal so in many areas the water membrane only butts up against the house wrap, not ½ inch overlap as required. Also, it is noted that the windows are installed on top of the marble windowsill and pushed back into the opening in order to get an acceptable inner seal. He also told Chris Monk that because of the previous damage from the installers the J-chanal and some vinyl should be replaced it would save time and money and be a better looking finished product. I heard Chris Monk tell him, no we are not doing that, not our job. Efforts made to restore my home were fruitless because of the wrong windows and the previous damages by initial installers and subsequent installers.

On November 14, 2023, the permit expired.

Consequently, because of the ongoing issues and ECOVIEWS refusal to take appropriate actions, I made final notice to ECOVIEW and demanded completion of the job properly and repair all damages. Since November 2, 2023, I have hired three independent inspectors to perform inspections to document installation defects and show causation of all the damages to my home and property and the quality of workmanship/installation. I have attached three inspections all indicating the windows ECOVIEW ordered and installed are the wrong size and style window. They concurred the damages seen were caused when the window company pulled the original windows and subsequent damage occurred because they tried to make the window fit and when they tried to coverup the subpar workmanship and damages they produced.

Scope of Deficiencies discovered during ongoing installation: Replacement windows are too small for the openings, wrong style and mount (inside-not exterior) set which directly caused the large gaps on every window installed, damage to window marble windowsills, windows are mounted directly on top of the windowsill, improperly sealed exterior and interior seals to windows, no insulation, destroyed anesthetics, reduction of window size, framing not plum/even, framing not correctly mitered and not leveled and nailed properly, frame is recessed on some windows and protrudes out of the J-chanal on others. There is also damage to some of the exterior windows caused when installers cut away the old metal flashing cutting into the window frame creating large gashes, damage to all vinyl J-Chanel and some vinyl siding and drywall damage to interior walls around the window openings. Openings are improperly sealed allows moisture and pest to access my home. Note: To date, the enormous amount of caulking they used is still wet. The independent inspectors noted the wrong caulking was used and improperly applied.

The problem is rooted from the original measuring process failing to take into consideration the existing window mount & finish (Vinyl.) He measured from inside the home, not exterior nor the depth. ECOVIEW did not conduct a second verification of size and style by an installer/but a sales man prior to ordering windows. It was noted during three independent inspections that the current windows are mounted on top of my window seal, raising the gap on the exterior and reducing require seal specifications for this installation. Also, damage to vinyl, drywall, marble window seals by workmen during removal of windows occurred, failure to follow standards for

installation of windows throughout the process (see photos and videos), and numerous half hearted efforts by ECOVIEW not to correct, but to conceal defects. In addition, damages incurred to the house water barrier wrap when initial Installers used a utility knife to cut away the house wrap to the edge of the j-chanal. There has been less than acceptable efforts made to properly replace water barriers as the tape does not overlap the house wrap in many areas because they did not remove the J-Chanel to allow ample overlap to provide water barrier protection, as well as the insulation was previously removed and was not reinstalled around every window. On the 4th attempt, Joe stated that it wasn't necessary to add insulation that the tape was ample and that his nozzle was to large to use expanded foam, They have failed six inspections to date.

To restore my home to its original value, the proper size and style windows need to be installed, repair/adjust house wall vinyl and replace J-chanal, drywall damage repaired and painted, 2 new window seals and replacement of broken window treatments front bedroom that the workers damaged. The estimated cost is between \$25,000.00 - \$30, 000.00 to make necessary repairs. This does not include my current loss wages and future loss wages, three independent inspector fees, contractor engineer fees, attorney and court cost fees. Should ECOVIEW not complete this job properly, all cost mentioned above will be sought.

It is my opinion, that this company took advantage of an elderly disabled single female. I make this statement because of how ECOVIEW staff talked to me, their delay in communication, their actions, their misrepresentations, their defective work, their inability to properly measure and select proper replacement windows, their out and out lies and their ongoing attempts to coverup the defects.

I have enclosed photos, contract, inspection reports and estimated repair cost. It should be noted, with each inspection the inspectors are identifying other defects. And this process is ongoing. The final complaint may need to be updated at the conclusion of this process and especially, when the General Contractor begins to pull this hideous mess apart to restore my home to it's original state.

PLEASE SEE ATTACHED DOCUMENTS.

CONTRACT PHOTOS INSPECTION EMAILS SETTLEMENT OFFER OTHERS

PLEASE SEE ATTACHED DOCUMENTS.

CONTRACT PHOTOS INSPECTIONS EMAILS SETTLEMENT OFFER OTHERS

-

.

. .

My original home before New Vivyl Siding, roof Windows Note: Windows are flush with the house.



TUIA 19 mo

Package Zof3

0087-hSh-852 - 2140 man most

(2) INDEPENDENT INSPECTIONS



Window Installation Inspection at 8870 SW 115th St., Ocala FL 34481

On November 20, 2023, a visual inspection was performed of the completed window installation at the request of the homeowner Ana Ortiz. Numerous deficiencies were observed with the installation practices at 8870 SW 115th St Ocala, FL 34481. It is the belief of this inspector that improper steps were taken from the very beginning of this replacement process. First and foremost, it seems that the proper measuring of the rough opening for these windows was not performed. It appears that the window installers performed a retrofit install, rather than a complete tear-out. A complete tear-out is recommended to get the most efficiency out of the new window installation. This method will allow for a nearly airtight seal between the new window and the existing structure. The complete tear-out is often recommended as the best method of installation by industry professionals.

As a result of the retrofit installation, gaps in the interior and exterior were observed. These gaps will be avenues of moisture infiltration due to improperly connecting the window to the building envelope. As a result of this installation method, caulking is primarily used as a means to create a seal. The caulking used to create this seal appears to not be a proper exterior caulking, as it had not cured and was still soft and tacky at the time of the inspection.

Proper installation of the window for a vinyl siding home would be to remove the siding around the area, remove any rotten material, and replace it with new wood for attachment. Installing a properly sized window with a nailing fin/flange. While securing the flange installer needs to ensure the window remains properly centered, level, plumb, and square. Once the fin/flange is secured it should be sealed to restore a properly weather-tight seal.

The installers on this home cut the nailing fin/flange (area to attach to the window to the exterior of the home) using an inside mount method. By doing this the weatherproofing exterior envelope has been broken and will lead to future leaking and moisture infiltration. Additionally, the marble sill plate was not removed, instead, the windows were installed directly on top of this.

In conclusion, the installation of these new windows was wrong from the start of the process. As an attempt to compensate for the initial installation shortcomings, more damage to the property was incurred. As a result, vinyl siding repair/replacement is needed for the siding, trim, j-channel, waterproof barrier, etc... Interior damage to drywall, sills, window trim, and corner beads was noted at all windows.


Julie Cain Owner, Strategic Inspection Service Home Inspector 15941

Julie Cain


Julie Cain, Owner, Strategic Inspection Service


11705 Boyette Rd, Riverview. FL 33569 352.867.7625 ph | 352.789.9286 cell www.strategicinspectionservice.com Inspection Photos:


LRB 2024-3LR





181 41


































DATE: NOVEMBER 26,2023

Fitzroy Home Improvement Inc. For All Your Home Improvement Needs!

4430 SW 98 Street Ocala, FL 34476 Phone: 352-667-1176 Website: Frhomeimprove.com * Email: Fitzroyhomeimprove@gmail.com

PROPERTY Ana M Megahan - Warga Ortiz ADDRESS 8870 SW 115th ST Ocala FL 34476 Telephone: Email: loboyuma@aol.com

> License # P21000002218 Service Type: Basic

CONTRACTOR	JOB	START DATE	END DATE	PAYMENT TERMS	DUE DATE OF COMPLETE PAYMENT
Fitzroy				As per Contract	

ESTIMATE TOTAL (\$) AREA DESCRIPTION SIZE After inspecting the home at 8870 SW 115th Street, Ocala FI, I determined that the original measurements for the replacement windows were incorrect and the direct cause of the host of issues seen. The overall installation is below acceptable trade standards. The incorrect size and style window installed should have been an outside mounted unit with fin. Because of windows small size and style of windows installed, it created very large gaps around the exterior rough openings in excess 2 inches. This in turn caused damage to Vinyl Siding and J channel. Other property damage was noted during the house inspection to the Master Bedroom window, Spare bedroom, living-room, garage and bathroom. The drywall underneath several window ledges has been broken and several windowsills are damaged from what appeared to be the use of a tool used to pry the windows out. Windows are not properly installed as the frame is mounted on top of the marble sill, not butted against the sill. This appears to be an effort to get a acceptable rear seal space. This reduced the inside windowsill space and adding to the larger gap to the exterior of home. Also, noted one window is leaking. Vinyl Siding needs repaired/adjusted; new J Channel added after proper sized/style windows

reinstalled. This must be done to every wall containing wrong sized/style window installed.

All windows need to be removed and replaced with the proper size and style window to restore house to its previous state.

Total labor Cost

Quotation prepared by Fitzroy

Please Note: This estimate is for visible areas <u>ONLY</u>. Due to lack of active utilities, not all damages may be identifiable. The price quoted is subject to change if any further damages are noticed and/or if the owners' desires change.

To accept this quotation, sign here and return:

THANK YOU FOR YOUR BUSINESS!

Revised Date: November 26, 2023

Photos of Install Over (7) visits. I ALSO HAVE VIDED EVIDENCE of workers Performing Improper Install of Windows and Intentional deviation of Standards.

PHOTOS OF 3RD VISIT WITH INSPECTOR. FLASHING REMOVED AND BEHIND IT WAS WATER.




Water Wilde Frame


PHOTOS OF 4TH VISIT, PHOTO I SHOWS THAT THERE WAS INSULATION IN WINDOWS AND THEY REMOVED IT. 2ND PHOTO SHOWS IMPROPER INSTALL OF BUCKING. CUT SHORT TO BUT AGAINST THE SCREWS IN WINDOW FRAME. THEY REFUSED TO PULL WINDOWS AND PROPERLY INSTALL BACKING AND PROVIDE PROPER SCREW PLACEMENT FOR STRENGTH IN ACCORDANCE WITH PRODUCT APPROVAL CODE. REMAINING PHOTOS CLEARLY SHOW SUBPAR WORKMANSHIP.














COMPLAINT Package 30f3




From ana Ortiz 352 454-2300


Photo Display from beginning thru 11-13-23


L'screws roper




KITCHEN WINDOW LEFT SIDE BACK PORCH AFTER 11-13-23-COMPLETION













PHOTOS OF WINDOW INSTALLED DIRECTLY ON TOP OF THE MARBLE WINDOWSILL



THIS IS A PHOTO OF THE ORIGINAL STYLE WINDOWS INSTALLED IN THE WOOD FRAMED HOMES THROUGHOUT OAKRUN. NOTE THE FLUSH MOUNT WITH THE HOUSE AND THE WINDOW IS AN EXTERIOR MOUNT FRAME UNIT.




SCOVIEN

Settlement (2) pages

Note they are not taking any responsibility for damages and improper install nor wrong window Size.

Ecoview Contract





November 15, 2023

SETTLEMENT AND RELEASE AGREEMENT

This Settlement and Release Agreement ("Agreement") is entered into by EcoView Windows & Doors ("EcoView") and <u>Anna</u> Ortiz ("Customer") on the <u>15th</u> day of <u>NOVEMBER</u> 20<u>23</u>.

Disputes have arisen between EcoView and Customer regarding _____ The installation of replacement windows

and the damaged J-Channel (referred to as the "Transaction" below).

In consideration of the payment, releases and agreements listed below, the parties agree to the following settlement:

- As a result of EcoView reducing the agreement and balance by \$1,500, Customer agrees to pay <u>Seven Thousand Five</u> <u>Hundred Twenty-Three Dollars & 00/100</u> (\$7,523.00) to EcoView upon execution of this Agreement via UpGrade Finance or other forms of payment if unable to utilize UpGrade Finance.
- 2. EcoView will ensure a final inspection conducted by the Marion County Building Department will pass per Florida Building Code.
- 3. In Exchange for the \$1,500 Reduction, Customer will resolve all J-Channel issues at her will with a siding company of her choice.
- 4. Customer fully releases and discharges EcoView, and its officers, employees, and authorized service providers, from any and all claims, actions, damages, losses, and liability of every kind relating to the Transaction.
- 5. EcoView fully releases and discharges Customer from any and all claims, actions, damages, losses, and liability of every kind relating to the Transaction. EcoView does not release any defense it might have to claims of Customer relating to any manufacturer's warranty for products purchased by Customer as part of the Transaction.
- 6. This Agreement constitutes the entire agreement between the parties and supersedes all prior negotiations and discussions which are merged in this document.
- 7. The parties acknowledge that they have read and fully understand this Agreement and that each has executed this binding agreement freely and without compulsion.
- 8. This Agreement is to be construed and enforced under the laws of the State of Florida.
- 9. Additionally, Customer agrees to refrain from any and all disparaging or otherwise negative statements in any public forum such as but not limited to Review Forums or sites, social media, news media, etc. that could in any way potentially, whether intentional or otherwise, harm EcoView from its ability to earn financially or its reputation.

EcoView Windows & Doors

By		

(Signature)

(Signature)

(Printed)

CUSTOMER

By

(Date)

(Printed)

(Date)

2200 NE 36th Avenue, Suite 508 Ocala, FL 34470 (352) 385-7488 Information@EcoViewNFL.com

	15 Spe	14	13	12	11	10	9	00	7	6	5	2	ω	2	-	LINE #			_	D	
	cial C			-	-	-	-	-	-	-	-	-	-	-	-	FLOOR	100			NAA.	
	Special Considerations:			ιν	Ĩ	٤N	GAR	9	9	MBATH	MBED	6ED I	BED1	BED 1	BED 1	ROOM	LOCATION			NDOW	
	ations:			316	312	312	21.5	215	215	212	2115	215	SIE	315	SIE			EXISTING		DAIN CI	
				ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	ALUM	Existing Material Aluminum Wood Steel Vinyl		EXISTING WINDOW		CUDDO C	
				VINY	VINYI	VINYL	Brick Block Stucco Cut Wood Vinyl Hardie	Opening													
Ň				вох	BOX	вох	BOX	вох	INSTALLATION N (BOX, NAIL FIN FRAME	, JU			GATE CODE:	JUBSHE AUDRESS							
				PH	DH	рн	рн	рн	рн	рн	PH	댂	рн	рн	рн	STYLE CODE		NEW			55
				7000	7000	7000	7000	7000	7000	7000	7000	7000	7000	7000	7000	SERIES		WINDOV			
																OPERATING DIRECTION 315 STYLE ORIEL SPLIT		NEW WINDOW or SLIDING GLASS DOOR		Ucaia	100/0 Sommon Standing
				WH	WH	WH	WH	WH	WH	WH	WH	WH	WH	WH	¥н	INTERIOR	8	ASS DOO			ICHWEST
-				WH	WH	WH	WH	WH	WH	WH	WH	WH	WH	WH	WH	EXTERIOR	COLOR	*		HOL	C IDCTT
]				32	32	32	49	400	450	47	47	47	32	32	32	WIDTH	RO	4		HOA OR COA NEEDED:	treet
				47	47	47	25	35	35	21	47	47	47	47	47	HEIGHT	ROUGH OPENING	MEASUREMENTS		DANE	
																LEG	PENIN	EMEN		E	
				79	79	79	74	83	83	89	94	94	79	79	79	⊆	16	IS			BILLING
				*	~								*	<		MULL TO PREVIOUS	LIN	E?			
				*	~	~	~	*	~	*	~	~	*	×	~	PREM. PKG. UPGRADE				19446T	
				Ā	Æ	Æ	Ŧ	Æ	Æ	Æ	Ŧ	Æ	Æ	Æ	풂	SCREEN - HR, HE or F		MIN.		ľ	
a RE																TEMPERED LOCATION		WINDOW OPTIONS	1.		
# REMOVALS																OBSCURED LOCATION		OPTIC	NE	Ŧ,	, vi
STALLS																SOUND & SECURITY (9	000)	SNC	WW	DME	ONU
8																GLASS TINT - BZ, GRY,	TU		NDOV	HOME BUILT F	
																TYPE (FLAT or SCULPT, SCULPT)	1"		N or S	LTP	SECONDART FHUNE
5		-	+	-		-	-						+	1		PATTERN (C, PE, PR, et	c)		NEW WINDOW or SLIDING GLASS DOOR	HOME BUILT PRE-1978	1
		-	-		1		-			-	-		1	1	1	TOP BOT ENDS or ALL	6		GGLA	876	
																# VERTICAL or SPOKES	GRID LINES	GRIDS	SS DO		
																# HORIZONTAL	Ē	SQ	0R		
												-				TOP BOT ENDS or ALL	GR			NO	
																# VERTICAL or SPOKES	GRID LINES			Libra	
		_		-			-	-		-				-		# HORIZONTAL	5	_		47.00m	
								1								HANDLE COLOR				diron.	
																FOOTBOLT		DOOR OPTIONS		PROSPECT/JOB	
X																BLINDS BETWEEN GLA	ss	OPTIC		PEO	
P																GLASS TINT - BZ, GRY,	TU	SNG		70	
				-		-							-	-		COASTAL HARDWARE		_		#	
																MISC. ITEM CODE		OPTIONS			DATE
																WIDTH				7971	
																HEIGHT	1	MEASU		and a lot	4/6/2023
																LEG	FINAL	MEASUREMENTS	'	ľ	
11		-		-						1	-	-	-	-	-			-		1	

			CRC M	11330954				2
lomer		Ana Ortiz			Prim	ary Phone: (352) 454-2300		-
difress:		8870 Southwest 115th Street			ferme	lary Phone		
ares.								
City.		Ocala		-	Pris	toboyuma@aol.com		-
State	FL	Zu: 34	481		NOTIFIC	ATION PREFERENCE EMAIL		
								-
YTD		DESCRIPTION	EACH	TOTAL	qTr	DESCRIPTION	EACH	TO
		WINDOWS				DOORS		
		ECO 3000 Series	1			7700 SERIES MAXVIEW SLIDING GLASS E Min/Vew SGD - 570" x 878" (60 x 80) (401)	52,645	-
	Double Hung (301) Two lite Sider (302)		\$452 \$452			Marvew360 - 21, x 8.8, [60 x 80] [402] Marvew560 - 60, x 6.8, [72 x 808 [402]	\$2,845	-
	Pistore Window (103)		548/2			MaxVerw SGD - 8'C" x 6'8" (96 x 80) (40 %	\$3,955	
		ECO 7000 Series				MarView SGD - 612" x 810" [72 x 96] [404)	\$2,775	-
12	Double Hung (301)		\$698	\$8,376		MaxWear St(D - 9"C" x 6"8" [3 Panet - 000 Only] [405]	\$4,965	-
	Two Lite Sider (305)		5608			9700 SERIES ECOVIEW INOVO SLIDING GLAS	54,320	T
	Picture Window (308) Germetric Shares (NO	NOPERATING HR, HRL EB, CNLY) (107)	SH25			EcoNew (NOVD 550 - 510" + 618" 54061 EcoNew (NOVD 550 - 610" + 618" 14071	54,595	+
		ECO 9000 Series				Loovew NOVO 560 - 8'0" + 0'1" [498]	\$5,305	
	Dryuble Hune (30%)		58-11			(coVew NOVD \$60 - 5'0" + 6'0" (409)	\$4,695	-
	Two Lite Sider [309]		852			Loview INOVD 560 - 6'0" + 8'0" (410)	54,815	-
	Three Lice Sider (710) Dicture Window/Fixed	Casement/Fixed Awining (311)	\$2,091 \$7\$7			Ecologie (NOV0.560 - 970 x 85° [411] Ecologie (NOV0.560 - 970 x 85° [3 Ravel - 040] [412]	\$5,565 \$5,940	1
	Fixed Centretric Shape	* [312]	PERUI			EcoView INDVO 56D - 12*D x 8*8* (4 Pariel - 0XNO) (413)	\$2,555	
	Operable Geometric St	opes (313)	52,079			9750 SERIES ECOVIEW IMPACT SLIDING GLA	SS DOORS	-
_	Caurments/Aaming - 5	ngle (314)	51,289			fcoVew MPACT 50D - 5'0" + 5'8" [414]	\$4,805	-
_	Long to Port of Long .	OVERSIZE UPCHARGES	\$75			EcoNew IMPACT IGD = 8'0" × 6'8" (415) EcoNew IMPACT SGD - 8'0" × 6'8" (416)	\$5,260	-
	OVER SIZED WINDOW OVER SIZED WINDOW	115 - 124 0/13221	\$125		-	EcoView IMPACT SSD - 6'0" x 8'0" [417]	\$5,930	1
_	OVER SZED WINDOW	>124 UI (829)	\$175			(coview MPACT SGD - 8'0" x 8'0" [418]	\$7,915	-
		ECO 9500 IMPACT Series				troView IMPACT SGD - 9'G" x 6'8" [3 Pane: - OXO Only] [419]	\$7,515	-
	Cicuble Hung [315]		\$1,598			LODVIEW IMPACT SGD - 1210" x 618" [3 Panel - CKO Cnity] (420)	\$10,170	-
	Two Lite Sixter (316) Three Lite Slider (317)		\$1,998 \$3,657			EcoView IMPACT SGD - 9'0" x 8'0" [3 Panel - OXO Criv) [423] EcoView IMPACT SGD - 12'0" x 8'0" [3 Panel - OXO Criv) [423]	\$8,810 \$11,710	-
		Casement/Fixed Awning (318)	\$1.689			SPR Sliding Glass Door (400)	Ment Provided	1
		5 (bit containing \$8.54 Per, 115 or 93) (\$2)	52,698			SLIDING DOOR OPTIONS	-1-4	-
	Casements/Awnings -		\$1,751			Colonial Grizs FLAT (423)	\$150	I
		IMPACT OVERSIZE UPCHARGES				Prairie, Perimeter, Diamond Grids - FLAT (424-426)	\$200	
	OVER SPED WINDOW OVER SPED WINDOW	104 - 114 U(324)	\$150 \$750			Make Brids Sculptured - (9700 & 9750 Only) (427)	\$50 \$125	
	OVER SIZED WINDOW		\$175			Handle Color Upgrade - (9700 & 9750 Only) (428) Ten ht. & Ext. for Driftwood for 9700 & 9750 only (429-430)	\$175	+
	Contracto nonson		1 1			Exterior Painted Colors (Includes Handle Color Upgrade) (431)	\$895	
12	PREMIUM UPGRA	E PACKAGE(N/A 3000 Series) (327)	5125	51,500		Secondary Lock/Foot boit (432)	\$30	
_		Window Options			-	Coastal Hardware (Handles will be Brushed Nickel Only) (433)	\$175	-
	Orlet (add per worston	(328)	565			Bircis Between Glava (9700 Only 5'6,6'0 & 9'0 X 6'8 Only) (434)	\$425/Parel	-
	Colonial Grids - TLAT [Prairie: Perimater, Vict	29) onan, & Damond Grids - F(AT (330-333)	505			Furtle Glass (9750 Only) (4.15) Tinted Glass (add per door Panel) (N/A 9750) (436)	\$150	
	Specialty Grids - FLAT	Need Phote) (N/A on 3000) 154)	5475			MAKE 9700 DR 9750 SERIES CUSTOM SIZE - 2PNL ONLY (437)	\$750	
	Geometric Grids - FLA	[335]	\$175			LABOR OPTIONS		
	Make Grids Sculptures	TORC & SOLO Conty (N/A Specialty) [336]	A50 545			Metal Window Removal/Wood Frame Modification (501) Multion (502)	\$69	1 3
	Obscured Glass ladd p Tempered Glass (per L	nited inch) (338)	\$341			Steel Casement Culcuts (IN ADD/TION TO MWR) (SOC)	585	1
	Finted Gass (add per s	Andowi (339)	\$95			Jump Frame(SDB)	\$59 \$85	-
	Turtle Glass (add per a	or Driftwood for 9000 only (\$41-542)	5165			Stucco Frame Cut (IN ADDITION TO MWR) (569) Stucco Cut Back/Repair (Average Price) (IN ADDITION TO	5850	-
	Interior Laminate Colo	5 (343)	\$175			MWR3(557)		_
	Painted Exterior Color	(\$000 & \$500 Series CMLT) (344) (ruded Frame-7000 & \$000 only) (345)	5425			Speciality TrimyWilaps(Per WINDOW Removed-2a for Door)(50) Remove A/C Unit (Remove ONIY) (505)	1 <u>\$125</u> \$50	+
	Double Verd Latch (34		58			Bernave & Replace Awaings (206)	\$75	-
		Package (9000 Only) (347) Indification for Nat Fin Instalis (348)	\$400			Remove ONLY (surger Sars (510) Miscellaneous Labor - Amount to be provided by ISM (SOC)	\$1:0 180	
-	Manufacture: Frame N	ENTRY DOORS	\$75			Miscellaneous Labor - Amount to be provided by ISM (SCC)	180	1
ηTγ.	00	OR SPEC SHEET PAGE	PRICE	TOTAL	Desc.			
111		on arte meet rate	PRICE	TOTAL	Labor			
_					Labor			_
Inmer	agrees to the terms of p	arment as follows						-
	MABOVE	\$11,128	Future	AMOUNT	NANCED	\$2,023 FINANCED BY UNGRADE	PROCRAM	60
			warest					_
ROMD	TIDAS/ADJUSTMENTS	30	~ ~	PAYMENT	TADA FUE		AMOUNT	51
		13.5% 51.500		1 004	LEPOST CA	FORM OF PAYMENT	MACONT	L
ALM/DI	SPOSAL/PERMIT	\$85		IOTAL AMO	UNT RECEIVE	D (FINANCED & PAYMENTE \$10,02.8		
AL PRO	DIECT	\$10,023		BALANCE DR	ETO NISTAL	LERATCOMPLETION \$2		
	Mar Deday	Manager Manager and All	the builded of the	alizza harr a	face address	, agrees to buy, and EcoView Windows & Ecors of North Horida	(Troubless West	
tab. rist	ormedon: Undersigned	Con ["Installation") of all materials descr	then above and or	n the attached	meature sh	, agrees to buy, and continue wondows & court of sorth retries eet, all of which are incorporated into this contract by this refer	tree, along with ap	oplicate
		ny Change Orders (collectively, "Contract						
torner A	grees that, immediately up	on completion of the work for each product, I	Customer will execu	ite a Completto-	Certificate a	nd pay any balance due. As applicable, each Costenter under this Contri	et agrees to be Joint	tig and s
dated a	nd Bable here under.	14 - 30 A.						
Victor (M	indust records the right t	i hour a Change Order or terminate the Cont	ract to any portion I	herein, if termin	w Windows c	r is authorized service provider determine that it cannot parform its o	digations share to a st	the the al
		d harards such as mold, ashershis of lead pain	t other safety cance	erted, arming me	of a of because	work required to complete the job was not included in the Contract.		
lem sid	th the bosis, group correct							

In the send of termination of this Contract, Centering ages to any Earlier Windows that an it of material, likely, sender membrands, pais any pointer annount of this in this phasement on indexed inter agricultural basis. Beccontract Announces and Anthogonation, Contract, ages and understands that this Appendix Announces that are earlier and Antopological and Anthogonation. So that are and update such a close of the ages and the areas closed and discussion and agest that Contract and and such such as the close of the areas of and has received and areas of the ages and the closed and antipological such as the closed and antipological and account of the ages of the ages and the closed and agest and an and update such a closed and areas of an internet and areas and an exclusion of the ages and a such as the closed and a such as the such agest such as closed and areas of an internet and areas and an exclusion of the agest and a such as the closed and an areas and agest such as closed and areas of an internet and areas and an exclusion of the agest and an areas and an areas and agest such as closed and areas and an areas and areas and areas areas and areas ar

fucts and installation services and supervestes all prior

(1) and house ment to be provided to the Constance ment by: B. Gimmer Per Reporter statute Signature Accepted by: 4/6/2024 Date 2 4/6/2023 Date Customer's Signature Customer's Signature Date Email Address Phone Mumber

NOTICE OF CARCELLATION. CLUTOMER MAY CANCEL THIS ADREAMENT WITHOUT PERALTY BY DELIVERING WRITEN NOTICE TO ECONEW WINDOWS BY MINIONIT OUT THE THING BUSINESS DAY AFTER BORNING THIS ADREAMENT. THE STATE SUPERIMENT TALKHER HERITO CONTAINS A FORM TO USE IF OWE IS SPECIFICALLY PRESCRIPT OF LAW IN CUSTOMER'S STATE.

NOTICE: ADDITIONAL TERMS AND CONDITIONS ARE STATED ON THE FOLLOWING PAGE AND ARE A PART OF THIS CONTRACT.

PLEASE READ THIS HOME IMPROVEMENT CONTRACT

.

են խորհետությունը որ հայտությունը հարտարարությունը որ հայտությունը որ հայտությունը որ հայտությունը որ հայտությո հայտությունը հայտությունը հայտությունը հայտությունը որ հայտությունը հայտությունը հայտությունը հայտությունը հայտո Առաջանակությունը հայտությունը հայտությունը հայտությունը հայտությունը հայտությունը հայտությունը հայտությունը հայտո Low hubbles whether and provide the frequencies of the investor sheet, restriction of the second sector of another provide the frequencies of the second sector of another provide the frequencies of the second sector of another provided the second sector of the sector of the second sector of the second sector of the se

Construction of the second se second seco

use provintion: energy in a second s

35inilgisuodeag

αριφά ότρι ο πρωθεί τοντό για τη τορία (προτολη τολη τολη τολη το μοντική) το τορί το πορία το τορία το πορία το πορία

matching of the second s second se TYILIN

Here and the state of the state try captor typacted pain has a your person a subject of Academic Strategies (strategies Asing as and or aging any weapont measors) from Appropriately SISTERIAL TRACESS SHOLD V

HIST ENVELOPMENTAL ORIGINATION AND CLEAR TRADUCTORY OF THE TRADUCTORY OF THE ADDRESS OF THE ADDR NOUTHINGS SUIVERSING SUIVERSING AND TREASURED AND TREASURE

CONVERSES MODILES FUNCTION FOR CONTRACT STATUS OF CONTRACT STA

AND OLDALINGLE STOD

ης ειρίον χρούς η συς αγτί πητοις μομίαν η καιτωρίο της θυταιρίας τους θητι μη μους το ματά το ματ στα ματά το ματα το ματα ματά το ματα το ματα το ματά το ματά το ματα το ματα το ματά το ματα το μ

IVILIN

Provide the second s

Any second set in the conditioned set of the second second set of the second set of

\$29020

63

Thank you for choosing Ecoview Windows and Doors

Your new Ecoview Windows and Doors are made with your comfort in mind. In addition to that, you will find that Ecoview Windows and Doors add beauty and value to your home. Please take a few moments to review our installation procedures. While this will likely be a slight disruption of your daily life at home, we hope that years of enjoyment will make it worthwhile.

1) Expected Delivery: Our windows and doors are custom manufactured and then shipped to one of our many locations nationwide. Although we cannot guarantee how long this process will take, the time between when you place an order and delivery to your local dealership is typically between 12 and 16 weeks. When your products are delivered to the dealership location, we will contact you to arrange an installation date that is most convenient for you if for some reason you cannot allow us to install within 2 weeks, we will store your windows for a reasonable period of time and arrange an installation date that works best for you. However, we will need to collect any balance due within 2 weeks of notification of delivery.

2) Arrival Time: We will advise you of approximate arrival time to expect our crew when we schedule the installation date if for some reason beyond our control we will not be able to be at your home during that time frame, we will notify you as soon as possible. We typically will stay and work as long as there is daylight, especially if we feel the work can be completed in that same day. Please notify us if that will be a problem for you. We will advays feave your property secure and weather-tight if we do not finish the job on the same day we start even if the widows/doors installed are not complete. Please do not critique at this time.

3) Expect some disruption: Removal and Installation of windows and doors can be noisy. We appreciate your patience and will do our best to be as neat and quiet as possible. Remember, as with almost any remodel, it looks worse before it looks better. Please keep in mind that our installation crews are competent and will complete the job in a manner that you would expect from a professional. Your satisfaction is our ultimate goal.

4) Window Coverings: Please remove any mini blinds, vertical blinds, roll up shades, drapes, shutters and/or any other window covering including any mounting hardware or brackets inside the window opening(s) prior to our installation. We are not responsible for removal, re-installation or alterations that may be required to re-install them.

5) Exterior Foliage: Occasionally we will need to work in a landscaped area of your home that is adjacent to the windows and/or doors. Please take time to examine these areas for potential problems prior to our arrival. Trees and/or bushes may need to be pruned or cut back to give us access to your windows. We will, of course, respect your property. However, our attention will need to be focused on your windows and/or doors and our safety. Please remove or temporarily relocate plants or shrubs that may not survive accidently being stepped on during this process.

6) Work Area: We will need approximately 2 feet in front of your windows and/or doors on the inside of your home. If furniture items are too heavy for you to move, we will be glad to assist you. Be aware that wind gust can blow after or during the removal of your old windows. Please remove any important papers or other items that may be disturbed as a result of this.

7) Alarm System: Our crews are not trained to remove or install alarm systems. Please contact your alarm service to arrange disconnect and reconnect around our installation.

8) Pets: Unfortunately, we are not always able to close a gate or door behind us during installation. Please secure your pets during the installation.

9) Pre-Existing & Incidental Damage: Our Installation Professionals take every reasonable step to prevent new or not worsen pre-existing damage. Due to sweating, loaks and/or age, some of this is completely unavoidable. Examples of, but no limited to, are: 1. Drywall, sheetrock, plaster or exterior stucco may fall out when the old windows are removed (in most cases we can seal this up with no issue, sometimes it may require patching and touch up paint 2. Window Sills (ceramic, porcelain, marble and wood) often becomes dislodged since they are mostly held in place by the sealant between the sill and the existing window. More often than not, our installation professional will be able to set it right back in place and seal it to the new window. Sometimes it new violds beneath the sill that are completely invisible to the installer, that cause them to become easily cracked while extracting the existing window despite every effort to prevent the cracking from happening. 3. Old trim stops and wood or stop replacement not previously charged for (as recorded in contract) will be the responsibility of the homeowner. Neither EcoView, nor the installer can accept responsibility for any of these incidental damages, but will assist in correcting them to the best of our ability. If the damages exceed the installer's capabilities of a quick fix, or if additional materials are needed, we will gladiy quote a competitive rate for such repairs.

10) Job Completion: Upon completion, our crew leader will need someone of authority to inspect the job and sign a certificate of completion We will ask that you call our office (or after-hours number) for a brief completion questionnaire. We will need to collect any balance due at this time unless prior arrangements have been made.

11) FINAL INSPECTIONS (when needed): If you live outside of the City of Jacksonville, or if you live inside the City of Jacksonville AND your project total <u>costs</u> exceed the pre-set threshold of the building department, you will need a final inspection. All inspections are conducted Monday through Friday at the time the municipality chooses. While we are more than happy to schedule the final inspection for you, however please understand, we have no control over when the inspection will take place other than the day. We can schedule inspections for the next day until 4:00 pm the day prior.

CUSTOMER SIGNATURE___

CUSTOMER SIGNATURE

HOME IMPROVEMENT CONTRACT PLEASE READ THIS

Florida Construction Lien Law:

ACCORDING TO FLORIDA'S CONSTRUCTION LIEN LAW (SECTIONS 713.001-713.37, FLORIDA STATUTES), THOSE WHO WORK ON YOUR PROPERTY OR PROVIDE MATERIALS AND SERVICES AND ARE NOT PAID IN FULL HAVE A RIGHT TO ENFORCE THEIR CLAIM FOR PAYMENT AGAINST YOUR PROPERTY. THIS CLAIM IS KNOWN AS A CONSTRUCTION LIEN. IF YOUR CONTRACTOR OR A SUBCONTRACTOR FAILS TO PAY SUBCONTRACTORS, SUB-SUBCONTRACTORS, OR MATERIAL SUPPLIERS, THOSE PEOPLE WHO ARE OWED MONEY MAY LOOK TO YOUR PROPERTY FOR PAYMENT, EVEN IF YOU HAVE ALREADY PAID YOUR CONTRACTOR IN FULL IF YOU FAIL TO PAY YOUR CONTRACTOR, YOUR CONTRACTOR MAY ALSO HAVE A LIEN ON YOUR PROPERTY. THIS MEANS IF A LIEN IS FILED YOUR PROPERTY COULD BE SOLD AGAINST YOUR WILL TO PAY FOR LABOR, MATERIALS, OR OTHER SERVICES THAT YOUR CONTRACTOR OR A SUBCONTRACTOR MAY HAVE FAILED TO PAY. TO PROTECT YOURSELF, YOU SHOULD STIPULATE IN THIS CONTRACT THAT BEFORE ANY PAYMENT IS MADE, YOUR CONTRACTOR IS REQUIRED TO PROVIDE YOU WITH A WRITTEN RELEASE OF LIEN FROM ANY PERSON OR COMPANY THAT HAS PROVIDED TO YOU A "NOTICE TO OWNER." FLORIDA'S CONSTRUCTION LIEN LAW IS COMPLEX, AND IT IS RECOMMENDED THAT YOU CONSULT AN ATTORNEY.

Florida Recovery Fund:

FLORIDA HOMEOWNERS' CONSTRUCTION RECOVERY FUND PAYMENT, UP TO A LIMITED AMOUNT, MAY BE AVAILABLE FROM THE FLORIDA HOMEOWNERS' CONSTRUCTION RECOVERY FUND IF YOU LOSE MONEY ON A PROJECT PERFORMED UNDER CONTRACT, WHERE THE LOSS RESULTS FROM SPECIFIED VIOLATIONS OF FLORIDA LAW BY A LICENSED CONTRACTOR. FOR INFORMATION ABOUT THE RECOVERY FUND AND FILING A CLAIM, CONTACT THE FLORIDA CONSTRUCTION INDUSTRY LICENSING BOARD AT THE FOLLOWING TELEPHONE NUMBER AND ADDRESS:

> Construction Industry Licensing Board 1940 North Monroe Street, Suite 42 Tallahassee, Florida 32399-2202 Phone 850.487.1395

Construction Defects:

CHAPTER 558 NOTICE OF CLAIM CHAPTER 558, FLORIDA STATUTES, CONTAINS IMPORTANT REQUIREMENTS YOU MUST FOLLOW BEFORE YOU MAY BRING ANY LEGAL ACTION FOR AN ALLEGED CONSTRUCTION DEFECT. SIXTY DAYS BEFORE YOU BRING ANY LEGAL ACTION, YOU MUST DELIVER TO THE OTHER PARTY TO THIS CONTRACT A WRITTEN NOTICE, REFERRING TO CHAPTER 558, OF ANY CONSTRUCTION CONDITIONS YOU ALLEGE ARE DEFECTIVE AND PROVIDE SUCH PERSON THE OPPORTUNITY TO

INSPECT THE ALLEGED CONSTRUCTION DEFECTS AND TO CONSIDER MAKING AN OFFER TO REPAIR OR PAY FOR THE ALLEGED CONSTRUCTION DEFECTS. YOU ARE NOT OBLIGATED TO ACCEPT ANY OFFER WHICH MAY BE MADE. THERE ARE STRICT DEADLINES AND PROCEDURES UNDER THIS FLORIDA LAW WHICH MUST BE MET AND FOLLOWED TO PROTECT YOUR INTERESTS.

CUSTOMER SIGNATURE:

CUSTOMER SIGNATURE:



IN HOME SALE OR SERVICE


NOTICE OF CANCELLATION

YOU MAY CANCEL THIS ENTIRE TRANSACTION OR ANY PORTION THEREOF WITHOUT ANY PENALTY OR OBLIGATION, WITHIN THREE BUSINESS DAYS (EXCLUDING HOLIDAYS) OF THE DATE OF THE SALES CONTRACT. IF YOU CANCEL, ANY PROPERTY TRADED IN, ANY PAYMENTS MADE BY YOU UNDER THE SALES CONTRACT, AND ANY NEGOTIABLE INSTRUMENT EXECUTED BY YOU WILL BE RETURNED WITHIN 10 BUSINESS DAYS FOLLOWING RECEIPT BY SELLER OF YOUR CANCELLATION NOTICE, AND ANY SECURITY INTEREST ARISING OUT OF THE TRANSACTION WILL BE CANCELLED. THERE WILL BE A SERVICE CHARGE EQUAL TO THE GREATER OF, TEN PERCENT (10%) OF THE TOTAL CONTRACT AMOUNT OR ACTUAL EXPENSES INCURRED TO DATE IF YOU CANCEL THIS TRANSACTION AFTER THE THIRD BUSINESS DAY FOLLOWING THE DATE OF SALE, BUT BEFORE MATERIALS ARE ORDERED. THERE WILL BE A SERVICE CHARGE EQUAL TO THE GREATER OF, TWENTY-FIVE PERCENT (25%) OF THE TOTAL CONTRACT AMOUNT OR ACTUAL COSTS INCURRED IF YOU CANCEL THIS TRANSACTION AFTER MATERIALS ARE ORDERED.

IF YOU CANCEL, YOU MUST MAKE AVAILABLE TO SELLER AT YOUR RESIDENCE, IN SUBSTANTIALLY AS GOOD CONDITION AS WHEN RECEIVED, ANY GOODS DELIVERED TO YOU UNDER THE SALES CONTRACT, OR YOU MAY COMPLY WITH THE INSTRUCTIONS OF THE SELLER REGARDING THE RETURN OF THE GOODS AT SELLER'S EXPENSE AND RISK.

IF YOU MAKE THE GOODS AVAILABLE TO SELLER BUT SELLER DOES NOT PICK THEM UP WITHIN 20 DAYS OF THE DATE OF YOUR NOTICE OF CANCELLATION, YOU MAY RETAIN OR DISPOSE OF THE GOODS WITHOUT ANY FURTHER OBLIGATIONS. IF YOU FAIL TO MAKE THE GOODS AVAILABLE TO SELLER, OR IF YOU AGREE TO RETURN THE GOODS TO SELLER AND FAIL TO DO SO, YOU WILL REMAIN LIABLE FOR PERFORMANCE OF ALL OBLIGATIONS UNDER THE SALES CONTRACT.

TO CANCEL THIS TRANSACTION, MAIL OR DELIVER A SIGNED AND DATED COPY OF THIS CANCELLATION NOTICE OR ANY OTHER WRITTEN NOTICE TO ECOVIEW WINDOWS AND DOORS AT THE ADDRESS AT THE TOP OF THE SALES CONTRACT NO LATER THAN MIDNIGHT OF:



I HEREBY CANCEL THIS TRANSACTION:		
	Customer Signature	DATE



The items listed below are our opinion on the windows that were installed.

- 1. When replacing windows measurements should be taken from the interior and exterior of the house. It should be taken into consideration what type of windows exist. Also need to know that this house had vinyl siding.
- 2. Windows installed were interior mount, which does not appear to be the correct size since the original windows were exterior mount.
- 3. The new windows did not fit the opening correctly as from the outside now they had to install a 4-to-6-inch trim around the windows which were not there before.
- 4. The 2x4 bucks were removed from the windows when new windows were installed which created gaps. Photo shown to us by customer revealed that large gap with screw that was not into a buck.
- 5. There is damage to the vinyl J trim. See photos.
- 6. There is damage to drywall and windowsills where the windows were installed.
- 7. Portion of the vinyl siding will need to be removed and re-installed when new windows are to be installed as it appears that it is not in the J trim track.
- 8. There are gaps around the windows that can be seen in the photos, which should have been insulated.
- 9. Insulation and house wrap should have been done prior of installation of windows to unsure no water penetration would happen.
- 10. Further inspection revealed that new windows were installed on top of the windowsill. The existing windows were not, because they were exterior mount.
- 11. Per our interview with the customer, Marion County Building Inspector has not passed the installation of the windows.
- 12. In our opinion the windows were the wrong size and style to fit in with the existing openings. The look of the house has been changed with the trim that was added. Shutters were on both sides of the windows prior to installation. They have been removed and not put back as the size has changed with the installation of the trim around the windows.
- 13. To make corrections:
 - New windows will need to be ordered.
 - Install 2x4 bucks as needed.
 - Install house wrap and insulation as needed per code.
 - Repair and paint damage to interior drywall
 - Remove and replace any damaged windowsill.
 - Remove and replace vinyl J trim.
 - Repair vinyl siding
 - Install existing shutters.

Attached is the estimate for repairs.



Advanced Restoration Services, LLC

Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

18885 NW 88th Ave Rd

Reddick, FL 32686

Client: Ana Ortiz Property: 8870 SW 115th St Ocala, FL 34481

L.OZCEL

Lee Ozcel

Other

Operator:

Estimator:

Business:

Type of Estimate:

Date Entered:

Home: (352) 454-2300

Business: (352) 804-0300 E-mail: lee.ozcel@arsflo.com

Price List:	FLOC8X_NOV23
Labor Efficiency:	Restoration/Service/Remodel
Estimate:	ORTIZ-ANA

11/20/2023

This is only an estimate. When windows are removed additional cost and labor is possible for vinyl siding.

Date Assigned:



ORTIZ-ANA

Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

ORTIZ-ANA

DESCRIPTION	QTY	UNIT PRICE	TOTAL
1. Tandem axle dump trailer - per load - including dump fees	1.00 EA @	212.78 =	212.78
Exterio	or		
Exterior			
DESCRIPTION	QTY	UNIT PRICE	TOTAL
2. Final cleaning - construction - Residential	1,560.71 SF @	0.35 =	546.25

Ext_Surfaces

DESCRIPTION	QTY	UNIT PRICE	TOTAL
3. Siding Installer - per hour	48.00 HR @	77.09 =	3,700.32
Remove and re-install vinyl siding by window areas			
4. R&R Vinyl J trim	14.00 LF @	4.55 =	63.70
5. House wrap (air/moisture barrier)	200.00 SF @	0.34 =	68.00
6. Rigid foam insulation board - 1"	200.00 SF @	1.12 =	224.00
7. Material Only 2" x 4" lumber (.667 BF per LF)	64.00 LF @	0.67 =	42.88
8. Carpenter - General Framer - per hour	8.00 HR @	76.49 =	611.92
9. Caulking - silicone	164.37 LF @	2.53 =	415.86

Main Level

Garage			Height: 8'
DESCRIPTION	QTY	UNIT PRICE	TOTAL
10. R&R Vinyl window - double hung, 9-12 sf	1.00 EA @	391.79 =	391.79
11. Additional charge for a retrofit window, 3-11 sf	1.00 EA @	101.60 =	101.60
12. Contents - move out then reset - Large room	1.00 EA @	114.76 =	114.76
13. Floor protection - heavy paper and tape	392.67 SF @	0.46 =	180.63
14. Mask and prep for paint - paper and tape (per LF)	81.67 LF @	0.85 =	69.42
15. Paint the walls - one coat	653.33 SF @	0.73 =	476.93

Main			Height: 8'
DESCRIPTION	QTY	UNIT PRICE	TOTAL
ORTIZ-ANA	an an an ann an an an an ann an an an an	11/26/2023	Page: 2



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

CONTINUED - Main

DESCRIPTION	QTY	UNIT PRICE	TOTAL
16. R&R Vinyl window - double hung, 13-19 sf	9.00 EA @	444.19 =	3,997.71
17. R&R Vinyl window - double hung, 9-12 sf	1.00 EA @	391.79 =	391.79
18. Additional charge for a retrofit window, 12-23 sf	10.00 EA @	143.49 =	1,434.90
19. Additional charge for vinyl window mullion - per LF	16.00 LF @	12.89 =	206.24
20. R&R Window sill	34.00 LF @	4.32 =	146.88
21. Drywall Installer / Finisher - per hour	16.00 HR @	98.94 =	1,583.04
22. Content Manipulation charge - per hour	8.00 HR @	52.13 =	417.04
23. Floor protection - heavy paper and tape	1,168.04 SF @	0.46 =	537.30
24. Mask and prep for paint - paper and tape (per LF)	154.50 LF @	0.85 =	131.33
25. Paint the walls - one coat	1,236.00 SF @	0.73 =	902.28

Grand Total Areas:

1,560.71	SF Walls SF Floor SF Long Wall	173.41	SF Ceiling SY Flooring SF Short Wall	424.17	SF Walls and Ceiling LF Floor Perimeter LF Ceil. Perimeter
	Floor Area Exterior Wall Area		Total Area Exterior Perimeter of Walls	1,889.33	Interior Wall Area
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length



Advanced Restoration Services, LLC

Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

Summary

Line Item Total	16,969.35
Overhead	1,696.93
Profit	1,696.93
Material Sales Tax	330.18
Replacement Cost Value	\$20,693.39
Net Claim	\$20,693.39

Lee Ozcel



Advanced Restoration Services, LLC

Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

1 1-Neighbors house Date Taken: 11/22/2023

Original look of windows as it was same as neighbor



2 2-Neighbors house Date Taken: 11/22/2023

Original look of windows as it was same as neighbor



11/26/2023

Page: 5



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

3 3-Front window Date Taken: 11/22/2023



4 4-Front window Date Taken: 11/22/2023

Gap in window, appears to be caulk or paint on the J trim






Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

5 5-Front window Date Taken: 11/22/2023

Same



6 6-Front window Date Taken: 11/22/2023

same



11/26/2023



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

7 7-Window not replaced Date Taken: 11/22/2023



8 8-Window front master bedroom Date Taken: 11/22/2023







Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

9 9-Window front master bedroom Date Taken: 11/22/2023

Vinyl J trim missing








11/26/2023




Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

11 11-Window front master bedroom Date Taken: 11/22/2023



12 12-Window front master bedroom Date Taken: 11/22/2023



11/26/2023



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

13 13-Window front master bedroom Date Taken: 11/22/2023



14 14-Left side of house Date Taken: 11/22/2023






Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

15 15-Side master bedroom window Date Taken: 11/22/2023










Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

17 17-Side master bedroom window Date Taken: 11/22/2023






18 18-Side master bedroom window Date Taken: 11/22/2023




Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

19 19-Side master bedroom window Date Taken: 11/22/2023





Damaged J trim





Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

21 21-Side master bedroom window Date Taken: 11/22/2023

Vinyl siding that is existing and trim that was added to cover it



22 22-2nd side window Date Taken: 11/22/2023



11/26/2023



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

23 23-2nd side window Date Taken: 11/22/2023



24 24-2nd side window Date Taken: 11/22/2023





Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

25 25-Rear window Date Taken: 11/22/2023



26 26-Rear window Date Taken: 11/22/2023

No J trim





Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

27 27-Rear window on the rear right Date Taken: 11/22/2023

No J trim, instead its been caulked






28 28-Rear window on the rear right Date Taken: 11/22/2023

11/26/2023



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

29 29-Rear window on the rear right Date Taken: 11/22/2023



30 30-Garage window Date Taken: 11/22/2023





Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

31 31-Garage window Date Taken: 11/22/2023



32 32-Garage window Date Taken: 11/22/2023




11/26/2023



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

33 33-Garage windowDate Taken: 11/22/2023









Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

35 35-Living room window Date Taken: 11/22/2023



36 36-Bedroom window Date Taken: 11/22/2023





Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

37 37-Bedroom window Date Taken: 11/22/2023




38 38-Bedroom window Date Taken: 11/22/2023





Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

39 39-Bedroom window Date Taken: 11/22/2023





40 40-Bedroom window Date Taken: 11/22/2023


11/26/2023




Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

41 41-Bedroom window Date Taken: 11/22/2023







ORTIZ-ANA



Advanced Restoration Services, LLC 18885 NW 88th Ave Rd Reddick, FL 32686

43 43-Bedroom window Date Taken: 11/22/2023



44 44-Bathroom window Date Taken: 11/22/2023





Marion County Board of County Commissioners

Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

January 26, 2024

CERTIFIED # 7020 2450 0000 1094 2978 CERTIFIED # 7020 2450 0000 1094 2985

ANA ORTIZ 8870 SW 115TH ST OCALA, FL 34481

Dear Ana Ortiz;

Please be advised your formal complaint, Case #LRB 2024-3 has been received against: Contractors Name:

GEORGE M BECK ECOVIEW WINDOWS & DOORS OF NORTH FLORIDA 5105 PHILIPS HWY STE 5 JACKSONVILLE, FL 32207

Before the Marion County License Review Board at their meeting on Tuesday, March 12th, 2024 at 5:30 P.M. In the Marion County Growth Management Building – Training Facility at, 2710 E. Silver Springs Blvd. A copy of the complaint has been sent to the contractor.

It is requested that you attend this meeting. You may bring legal counsel to this meeting (if you so desire.) Any additional documentation substantiating your claim must be received ten (10) working days prior to the hearing as it is accepted as evidence and therefore becomes part of the case file. You will be given five (5) minutes to present your case and then a two (2) minute rebuttal.

Please contact the License Review Board Secretary at 438-2429 on Monday, March 11th, 2024 to verify the status of this complaint. Should you settle your dispute prior to the case date, please ask the complainant to send the Building Department a written statement before the scheduled hearing date requesting the complaint be withdrawn.

<u>Please be advised</u>, if any person or persons wish to appeal a decision of the license review board made at the above hearing, a record of the proceedings will be needed by such person or persons as well as a verbatim record. If you wish to preserve the testimony given at the hearing, you must make your own arrangements to do so. If any person requiring special equipment should contact the Board Secretary at least two (2) business days prior to the meeting.

Sincerely,

Antoinette Her License Review Board Secretary

Empowering Marion for Success





Marion County Board of County Commissioners

Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

January 26, 2024

CERTIFIED MAIL #7020 2450 00001094 2978 CERTIFIED MAIL #7020 2450 00001094 2985

GEORGE M BECK / ECOVIEW WINDOWS & DOORS OF NORTH FLORIDA 5105 PHILIPS HWY STE 5 JACKSONVILLE, FL 32207

Dear Mr. Beck;

Please be advised a formal complaint, Case # LRB 2024-3 has been brought against you by:

Complainant's Name:

ANA ORTIZ 8870 SW 115TH ST OCALA, FL 34481

Before the Marion County License Review Board at their meeting on Tuesday, March 12th, 2024 at 5:30 P.M. In the Marion County Growth Management Building – Training Facility at 2710 E. Silver Springs Blvd. Enclosed is a copy of the complaint and supporting documentation.

It is requested that you attend this meeting. You may bring legal counsel to this meeting (if you so desire.) Any additional documentation substantiating your claim must be received ten (10) working days prior to the hearing as it is accepted as evidence and therefore becomes part of the case file. You will be given five (5) minutes to present your case and then a two (2) minute rebuttal.

Please contact the License Review Board Secretary at 438-2429 on Monday, March 11th, 2024 to verify the status of this complaint. Should you settle your dispute prior to the case date, please ask the complainant to send the Building Department a written statement before the scheduled hearing date requesting the complaint be withdrawn.

<u>Please be advised</u>, if any person or persons wish to appeal a decision of the license review board made at the above hearing, a record of the proceedings will be needed by such person or persons as well as a verbatim record. If you wish to preserve the testimony given at the hearing, you must make your own arrangements to do so. If any person requiring special equipment should contact the Board Secretary at least two (2) business days prior to the meeting.

Sincerely, Antoinette Hernandez

Antoinette Hernandez License Review Board Secretary

Empowering Marion for Success

marionfl.org

An# 1059557

LRB 2024-3





USPS Tracking[®]

Remove X

70202450000010942985

Сору

Tracking Number:

Add to Informed Delivery (https://informeddelivery.usps.com/)

Latest Update

Your item was delivered to an individual at the address at 11:56 am on January 31, 2024 in JACKSONVILLE, FL 32207.

Get More Out of USPS Tracking:

USPS Tracking Plus[®]

Delivered Delivered, Left with Individual JACKSONVILLE, FL 32207 January 31, 2024, 11:56 am

See All Tracking History

What Do USPS Tracking Statuses Mean? (https://faq.usps.com/s/article/Where-is-my-package)


Text & Email Updates	\checkmark
USPS Tracking Plus®	\sim
Product Information	\sim
See Less 🔨	
rack Another Package	

Enter tracking or barcode numbers


Need More Help?

Contact USPS Tracking support for further assistance.









COUNTY A	Marion County Board of County Commissioners	
	Building Safety • Licensing	
* COD WE TRUE	2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org	
/	CONTRACTOR INFORMATIC	ON FORM
	IVE [] INACTIVE	DATE: 22924
LRB CAS	SE # 2024 - APPEA	L #
DATE CO	OMPLAINT / APPEAL RECEIVED: 11/27	23
PERMIT	REQUIRED: VES OR [] NO PERMIT #	2023052164
SPECIFY	PERMIT TYPE: <u>Window Ood</u> (i.e.: pool, SFR, shed, etc.)	
	FINALED [] YES OR [] NO DATE FI e fee permit	NALED
CONTRA	CTOR: GEORGE M. BLCK	
DBA: _E	COVIEW WINNE DOORS	OF NORTH FLORIDA
MARION	COUNTY CERTIFICATE #: 21872	
[] R.	ERTIFIED STATE #: <u>CLC 1330954</u> EGISTERED STATE #: OMP CARD #:	
WORKE	ITY INSURANCE:ITY YES OR [] NORS COMP. INSURANCE:] YES OR [] NORS COMP. EXEMPT:[] YES OR [] NO	
PREVIO PREVIO	JS COMPLAINTS: [] YES OR [] NO HOW JSE CITATIONS: [] YES OR [] NO HOW	MANY: MANY:
ADDITIC	ONAL NOTES:	
[] Contrac [] Comme	ntractors file etors Certificate Detail ents Comp exempt printout if exempt	 Pull permit file Complete Permit History DBPR print out (to verify status) Corporation papers (verify if in file)

Empowering Marion for Success

Certificate Detail Report

PR2305 - Cei	rtificate De	= tail Report		
ERT NBR	QUALIFIER NA	ME	DBA	STATUS
21872	GEORGE M BE	ECK	ECOVIEW WINDOWS & DOORS (OF NORTH FL ACTIVE
CLASS CODE	CLASS DESC			STATE NBR
CRC	CERTIFIED	RESIDENTIAL BUILDIN	G CONTRA	CRC1330954
ORIG ISSD				STATE EXP DATE
8/23/2022				8/31/2024
RENEWAL DA	TE			
		COUNTY COMP CARD	COUNTY EXP DATE	
EXPIRE DAT	E	21872	8/31/2024	
8/31/2024				OTH OL NBR
		COUNTY OL EXEMPT	N	
CNCL DATE				
		<u>COUNTY OL NBR</u> NO FILE	COUNTY OL EXP DATE	OTH OL EXP DATE
REINSTATE	DATE			
			DBA	
		PHONE	FAX	
		904-281-0067		
MAILING AD	DRESS		PHYSICAL ADDRESS	
5105 PHIL	IPS HWY		5105 PHILIPS HWY	
STE 5			STE 5	
JACKSONVI	LLE	FL 32207	JACKSONVILLE	FL 32207
		LIABI	LITY INSURANCE	
COMPANY			EXP DATE	
CLEAR BLU	E INSURANCE	E COMPANY	9/27/2024	
PHONE			EFFECTIVE DATE	
850-438-9	169		9/27/2023	
POLICY NUM	IBER		CNCL DATE	
BGFL00200	53803			
INSURANCE				
2,000,000				
		WORKERS CO	MPENSATION INSURANCE	
WC EXEMPT	Y			
COMPANY			EXP_DATE	
EXEMPT/AF	FIDAVT			
PHONE			EFFECTIVE DATE	
POLICY			CNCL DATE	

BOND INSURANCE

COMPANY

EXP DATE

PHONE

EFFECTIVE DATE

POLICY

CNCL DATE

INSURANCE LIMITS

LAST UPDATE DATE 11/27/2023 <u>LAST UPDATE USER</u> BU341KH02 PREV UPDATE DATE 9/28/2023 PREV UPDATE USER BU341SL2

2024.03

OUT OF POCKET LOSS/HOME DAMAGE REPAIR COST

Deposit to ECOVIEW:\$1000.00 Material Cost: \$400.00 Attorney Fee: \$250.00 Inspector Cunningham Fee-\$200.00 Inspector Ozcel Fee \$-350.00 Inspector Strategic Inspection Service Fee \$125.00 Paralegal Fee:\$1500.00 Handyman Fee: 150.00-Clean up Handyman Fee: 60.00-Dry Wall initial patch Handyman Fee: 350.00-Repair Dry Wall under and around master Bedroom Window & Paint (1) wall Court Cost: Unknown/in process Processor Cost: Unknown/in process Filing Fees: Unknown/in process Server Fees: Unknown/in process

Total to date: \$4385.00

Home Repair estimated Cost based on estimates

Vinyl Siding, House wrap, J-Channel, soffit and additional dry wall repair and paint \$ 25,533.77

Replace windows with proper size and style. Exterior mount with flange. \$10,884.46

Replace broken and marred window sills. \$1076.00

Total to date: \$37, 494.23

GRAND TOTAL: \$41,879.23

LIVING ROOM WINDOW PANE	OVERALL FRAME SIZE	PANE ONLY	LOSS OF
MINE	OVAF 95"W X 45.25"H	72" W X 36" H	24''W X 7''H
ORIGINAL	OVAF 98"W X 47' H	96" W X 43"H	

FRONT BEDROOM

MINE	OVAF 95"W X 45.25"H	72" W X 36" H	24''W X 7''H
ORIGINAL	OVAF 98"W X 47' H	96" W X 43"H	

FRONT SIDE BEDROOM WINDOW

MINE	OVAF 44"W X 45.5H	39"W X 37.5" H	5.5"W X 9.5" H
ORIGINAL	OVAF 49"W X 51.25 H	44.5"W X 47" H	

BATHROOM

MINE	OVAF 45"W X 21" H	18.75"W X 14.5" H	3.5"W X 7.5 H
ORIGINAL	OVAF 52.25" W X 27.25"H	22.25"W X 23" H	

KITCHEN WINDOW 1

MINE	OVAF 44.5" W X 34.25" H	39.25"W X 25.5" H	5.25"W X 9.5" H
ORIGINAL	OVAF 51.25" W X 39.25" H	44.5"W X 35" H	

GARAGE

MINE	OVAF 46"W X 22.5H	38"W X 16" H	6.5" W X 6.75"H
ORIGINAL	OVAF 49"W X 25 H	44.5" W X 22.75"H	



Marion County

License Review Board

Agenda Item

File No.: 2024-14568

Agenda Date: 4/9/2024

Agenda No.: 8.1.

SUBJECT: LRB 2024-4 Marion County Building Dept. v. Rickie Earl Glass / Ecoview Construction LLC



Marion County Board of County Commissioners

Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

February 15, 2024

CERTIFIED MAIL #7020 2450 0000 1094 3074

RICKIE EARL GLASS / ECOVIEW CONSTRUCTION LLC 3355 COPTER RD UNIT 4 PENSACOLA, FL 32514 CT # 17390

Dear Mr. Glass;

Please be advised a formal complaint, Case # LRB 2024-4 has been brought against you by:

Complainant's Name:

MARION COUNTY BUILDING DEPARTMENT 2710 E. SILVER SPRINGS BLVD OCALA, FL 34470

Before the Marion County License Review Board at their meeting on <mark>Tuesday, April 9th, 2024</mark> at 5:30 P.M</mark>. In the Marion County Growth Management Building – Training Facility at 2710 E. Silver Springs Blvd. Enclosed is a copy of the complaint and supporting documentation.

It is requested that you attend this meeting. You may bring legal counsel to this meeting (if you so desire.) Any additional documentation substantiating your claim must be received ten (10) working days prior to the hearing as it is accepted as evidence and therefore becomes part of the case file. You will be given five (5) minutes to present your case and then a two (2) minute rebuttal.

Please contact the License Review Board Secretary at 438-2429 on Monday, April 8th, 2024 to verify the status of this complaint. Should you settle your dispute prior to the case date, please ask the complainant to send the Building Department a written statement before the scheduled hearing date requesting the complaint be withdrawn.

<u>Please be advised</u>, if any person or persons wish to appeal a decision of the license review board made at the above hearing, a record of the proceedings will be needed by such person or persons as well as a verbatim record. If you wish to preserve the testimony given at the hearing, you must make your own arrangements to do so. If any person requiring special equipment should contact the Board Secretary at least two (2) business days prior to the meeting.

Sincerely, binette

License Review Board Secretary

Empowering Marion for Success

marionfl.org



Marion County **Board of County Commissioners**

Building Safety . Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

ADMINISTRATIVE REVIEW MARION COUNTY LICENSE REVIEW BOARD

LRB# 2024-4

COMPLAINANT/PETITIONER:

Marion County Licensing Division - Building Official 2710 East Silver Springs Boulevard Ocala, FL 34470 (352) 438-2429

CONTRACTOR/RESPONDENT

RICKIE EARL GLASS DBA / ECOVIEW CONSTRUCTION LLC Certificate # 17390 3355 COPTER RD UNIT 4 Pensacola, FL 32514 (850) 500-4937

Contractor is in violation of Florida Building Code 105.4 and Marion County Code of Ordinances 5.5-33(i)(1) by having allowed to expire and/or exhausted all extensions without obtaining a passing inspection within a 180-day period, on permits 2018041444 and 2022120004, constituting abandonment of the job.

COMPLAINT CERTIFICATION, PLEASE READ CAREFULLY BEFORE SIGNING. I HEREBY CERTIFY AND/OR AFFIRM THAT ALL INFORMATION FURNISHED IN THIS COMPLAINT IS TO THE BEST OF MY KNOWLEDGE, TRUE AND CORRECT.

Signature of Investigator: $\underline{\int ame \ \mathcal{R}_{OGV}}$ Date: $\underline{2 / 13 / 24}$

Empowering Marion for Success



CODE ENFORCEMENT SERVICES

Marion County, Florida

	on Order D	etail Report						
<u>OPEN DATE:</u>	February	01, 2024	TIN	<u>/IE:</u> 09:3	86 PM	<u>ACT</u>	ION ORDER NBR:	661311
OPENED BY:	BU341MF	=1	<u>DU</u>	<u>E_DATE</u>	2/1/2024	<u>[</u>	DISPATCHED BY	
COMPLAINANT	•					<u>[</u>	Date/Time:	
TYPE: CTZN		IAME: DDRESS:	LMF			LRB 2024-		
	P	HONE:				Marion Cou v.	-	
	<u>F</u>	<u>AX:</u>				Rickie Earl Certificate	Glass / Ecoview Const # 17390	truction LLC
ALLEGED VIOL	ATORS:					AO 661311		
□ Property O	wner	NAME:				····		· ·
□ Tenant		ADDRESS	:					
		PHONE:						<u>_</u>
		FAX:						
ALLEGED VIOL	ATION(S):							
CON-PERMIT	CON -	PERMITS						
ME ON THIS - T LOCATION OF V 5232 SE 15TH A <u>RANGE:</u> 22	<u>/IOLATION</u> VE OCAI	<u> </u>	16	SEC	<u>CTION:</u> 04			
DIRECTIONS / I	NOTES:							
REFERRED TO	LRB FOR	ADMIN RE\	/IEW					
PROPERTY INF	ORMATIO	<u>N: LE</u>	GAL:			ATE KEY:	ZONING	·
INSPECTION D						DFFICER:	ROGERS, JAMES	
INSPECTION S	<u>TATUS:</u>	VALID:		INVALID):	REFERRED:	CLEA	RED:
VIOLATION CO	<u>DE / REMA</u>	ARKS:						
						· · · · · ·		
	<u> </u>							
							<u> </u>	
<u></u>								
NOTICE OF HE	ARING DA	<u></u>			RESULTS:		FINE LEVIED	D:
NOTICE OF HE		<u>.TE:</u>			RESULTS:	APP	<u>FINE LEVIEI</u> ROVAL DATE:	

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY				
 Complete items 1, 2, and 3. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. 1. Article Addressed to: 	A. Signature X Le Carse B. Received by (Printed Name) C. Date of Delivery C. Date of Delivery				
Rickie Earl Glass Ecoview Construction LLC 3355 Copter Rd. Unit 4 Penasacola, FL 32514	If YES, enter delivery address below:				
9590 9402 5367 9189 0556 60	3. Service Type □ Priority Mail Express® □ Adult Signature □ Registered Mail™ □ Adult Signature Restricted Delivery □ Certified Mail® □ Certified Mail® Delivery □ Certified Mail Restricted Delivery □ Certified Mail Restricted Delivery □ Certified Mail Restricted Delivery □ Certified Mail® Delivery □ Certified Mail Delivery □ Collect on Delivery □ Rechandise				
2. Article Number (Transfer from service label)	□ Collect on Delivery Restricted Delivery □ Signature Confirmation™ □ Signature Confirmation™				
7020 2450 0000 1094 3098	Insured Mail Restricted Delivery Restricted D 110 (over \$500)				
PS Form 3811, July 2015 PSN 7530-02-000-9053	Domestic Réturn Receipt				

ALVER SMALL





Marion County

License Review Board

Agenda Item

File No.: 2024-14569

Agenda Date: 4/9/2024

Agenda No.: 8.2.

SUBJECT:

LRB 2024-5 Marion County Building Dept. v. Mark Clifton Norman / Mark Norman Construction Inc.



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

February 15, 2024

CERTIFIED MAIL #7020 2450 0000 1094 3081

MARK CLIFTON NORMAN / MARK NORMAN CONSTRUCTION INC 5540 NE 2ND LANE OCALA, FL 34470 CT # 12398

Dear Mr. Norman;

Please be advised a formal complaint, Case # LRB 2024-5 has been brought against you by:

Complainant's Name:

MARION COUNTY BUILDING DEPARTMENT 2710 E. SILVER SPRINGS BLVD OCALA, FL 34470

Before the Marion County License Review Board at their meeting on <mark>Tuesday, April 9th, 2024</mark> at 5:30 P.M</mark>. In the Marion County Growth Management Building – Training Facility at 2710 E. Silver Springs Blvd. Enclosed is a copy of the complaint and supporting documentation.

It is requested that you attend this meeting. You may bring legal counsel to this meeting (if you so desire.) Any additional documentation substantiating your claim must be received ten (10) working days prior to the hearing as it is accepted as evidence and therefore becomes part of the case file. You will be given five (5) minutes to present your case and then a two (2) minute rebuttal.

Please contact the License Review Board Secretary at 438-2429 on Monday, April 8th, 2024 to verify the status of this complaint. Should you settle your dispute prior to the case date, please ask the complainant to send the Building Department a written statement before the scheduled hearing date requesting the complaint be withdrawn.

<u>Please be advised</u>, if any person or persons wish to appeal a decision of the license review board made at the above hearing, a record of the proceedings will be needed by such person or persons as well as a verbatim record. If you wish to preserve the testimony given at the hearing, you must make your own arrangements to do so. If any person requiring special equipment should contact the Board Secretary at least two (2) business days prior to the meeting.

Sincerely,

Antoinette Hernandez License Review Board Secretary

Empowering Marion for Success



CODE ENFORCEMENT SERVICES Marion County, Florida

202₄ <u>TIM</u> <u>DUI</u>			ON ORDER NBR: 661570 ISPATCHED BY			
<u>001</u>						
			ate/Time:			
<u>:</u> LMF RESS:		LRB 2024-5				
<u>1E:</u>		v.				
		Certificate # 12398	n / Mark Norman Construction			
		AO 661570				
ME:						
DRESS:						
ONE:						
K :		·				
MITS						
			ONTRACTOR IS			
MERFIELD						
<u>IP:</u> 17	<u>SECTIC</u>	<u>N:</u> 31				
IN REVIEW						
LEGAL:		ALTERNATE KEY:	ZONING:			
		CODE OFFICER:	ROGERS, JAMES			
ALID:	INVALID:	REFERRED:	CLEARED:			
<u>):</u>						
	<u> </u>					
		······································	······································			
			· · · · • • • • • • • • • • • •			
	RE	SULTS:	FINE LEVIED:			
		APPROVAL DATE:				
	IE: ME: DRESS: DNE: C MITS , RENEWED AN S HE WANTS MO MERFIELD IP: 17 IN REVIEW LEGAL: ALID:	IE: ME: DRESS: DNE: C: MITS , RENEWED AND EXPIRED A S HE WANTS MORE PERMIT AERFIELD IP: 17 SECTION IN REVIEW LEGAL: ALID: INVALID:	IE: Marion County V. Mark Clifton Norma Certificate # 12398 AO 661570 ME:			



Building Safety . Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

ADMINISTRATIVE REVIEW MARION COUNTY LICENSE REVIEW BOARD

LRB# 2024-5

COMPLAINANT/PETITIONER:

Marion County Licensing Division - Building Official 2710 East Silver Springs Boulevard Ocala, FL 34470 (352) 438-2429

CONTRACTOR/RESPONDENT

MARK CLIFTON NORMAN DBA / MARK NORMAN CONSTRUCTION INC Certificate # 12398 5540 NE 2ND LANE Ocala, FL 34470 (352) 572-3030

Contractor is in violation of Florida Building Code 105.4 and Marion County Code of Ordinances 5.5-33(i)(1) by having allowed to expire and/or exhausted all extensions without obtaining a passing inspection within a 180-day period, on permits 2022011570 and 2023020881, constituting abandonment of the job.

COMPLAINT CERTIFICATION, PLEASE READ CAREFULLY BEFORE SIGNING. I HEREBY CERTIFY AND/OR AFFIRM THAT ALL INFORMATION FURNISHED IN THIS COMPLAINT IS TO THE BEST OF MY KNOWLEDGE, TRUE AND CORRECT.

Signature of Investigator: $\sqrt{a_{mer}} \sqrt{N_{og}}$ Date: $\frac{2/13/24}{2}$

Empowering Marion for Success

marionfl.org

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY			
 Complete items 1, 2, and 3. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. 1. Article Addressed to: Mark Clifton Norman Mark Norman Construction Inc 5540 NE 2nd Lane Ocala, FL 34470 	A. Signature X Addressee B. Received by (Printed Name) C. Date of Delivery C. Date of Del			
9590 9402 5367 9189 0555 92	3. Service Type □ Adult Signature Adult Signature Restricted Delivery □ Certified Mail® Restricted Delivery □ Collect on Delivery Restricted Delivery			
2. Article Number firansfer from service label).	Insured Mail Signature Confirmation Insured Mail Restricted Delivery Restricted E 116			
PS Form 3811, July 2015 PSN 7530-02-000-9053	Domestic Return Receipt			





Marion County

License Review Board

Agenda Item

File No.: 2024-14570

Agenda Date: 4/9/2024

Agenda No.: 8.3.

SUBJECT: LRB 2024-6 Marion County Building Dept. v. Rickie Earl Glass / Ecoview Construction LLC



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

February 15, 2024

CERTIFIED MAIL #7020 2450 0000 1094 3098

RICKIE EARL GLASS / ECOVIEW CONSTRUCTION LLC 3355 COPTER RD UNIT 4 PENSACOLA, FL 32514 CT # 17390

Dear Mr. Glass;

Please be advised a formal complaint, Case # LRB 2024-6 has been brought against you by:

Complainant's Name:

MARION COUNTY BUILDING DEPARTMENT 2710 E. SILVER SPRINGS BLVD OCALA, FL 34470

Before the Marion County License Review Board at their meeting on Tuesday, April 9th, 2024 at 5:30 P.M. In the Marion County Growth Management Building – Training Facility at 2710 E. Silver Springs Blvd. Enclosed is a copy of the complaint and supporting documentation.

It is requested that you attend this meeting. You may bring legal counsel to this meeting (if you so desire.) Any additional documentation substantiating your claim must be received ten (10) working days prior to the hearing as it is accepted as evidence and therefore becomes part of the case file. You will be given five (5) minutes to present your case and then a two (2) minute rebuttal.

Please contact the License Review Board Secretary at 438-2429 on Monday, April 8th, 2024 to verify the status of this complaint. Should you settle your dispute prior to the case date, please ask the complainant to send the Building Department a written statement before the scheduled hearing date requesting the complaint be withdrawn.

<u>Please be advised</u>, if any person or persons wish to appeal a decision of the license review board made at the above hearing, a record of the proceedings will be needed by such person or persons as well as a verbatim record. If you wish to preserve the testimony given at the hearing, you must make your own arrangements to do so. If any person requiring special equipment should contact the Board Secretary at least two (2) business days prior to the meeting.

Sincerely,

Antoinette Hernande

License Review Board Secretary

Empowering Marion for Success

CODE ENFORCEMENT SERVICES

Marion County, Florida

CDPR4205 - Act	ion Order Detail Repor	t		,		
<u>OPEN DATE:</u>	February 01, 2024	TIME:	09:33 PM	ACT	ON ORDER NBR:	661310
OPENED BY:	BU341MF1	DUE D	<u>ATE</u> 2/1	/2024 <u>C</u>	ISPATCHED BY	
COMPLAINANT	<u></u>				ate/Time:	
TYPE:	NAME:	LMF				
CTZN	ADDRESS:			LRB 2024-6 Marion County		
	PHONE:					
ALLEGED VIOL	<u>FAX:</u> .ATORS:			Rickie Earl Glass / Certificate # 17390 AO 661310	Ecoview Constructi	
			_			
Property (Tenant						
	ADDRES	<u>s:</u>				<u> </u>
	PHONE:				······	
	FAX:					
ALLEGED VIOI	<u>_ATION(S):</u>					
CON-PERMIT	CON - PERMITS					
CONTRACTOR ME ON THIS -	A HAS PERMITTED JO THANK YOU MICHEL	DB 3 TIMES AI	ND HAS NO WS	T OBTAIN INSPECT	TIONS. PLEASE S	EE
LOCATION OF	VIOLATION(S):					
	HAVE OCALA		١			
<u>RANGE:</u> 21	TOWNSHIP:	16	SECTION	1: 30		
DIRECTIONS /			0201101	<u></u>		
	D LRB FOR ADMIN RE					
REFERRED IC						
EARL MATTHE	WS OWNER POC 35	2-362-1244				
					701/11	:
PROPERTY IN		EGAL:		LTERNATE KEY:	ZONIN	
INSPECTION I	DATE:			CODE OFFICER:	ARBUCKLE.RYA	
INSPECTION S	STATUS: VALID:	IN	IVALID:	REFERRED:	<u>CLE</u>	EARED:
VIOLATION CO	DDE / REMARKS:					
				<u> </u>		
					<u></u>	
·				<u> </u>		
NOTICE OF H	EARING DATE:		_ <u>RES</u>	ULTS:	FINE LEV	IED:
CASE REVIEV	VED BY:			<u>APP</u>	ROVAL DATE:	
Marion County					Printed on: 02/13/	/2024 10:33:53Al ₁



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

ADMINISTRATIVE REVIEW MARION COUNTY LICENSE REVIEW BOARD

LRB# 2024-6

COMPLAINANT/PETITIONER:

Marion County Licensing Division - Building Official 2710 East Silver Springs Boulevard Ocala, FL 34470 (352) 438-2429

CONTRACTOR/RESPONDENT

RICKIE EARL GLASS DBA / ECOVIEW CONSTRUCTION LLC Certificate # 17390 3355 COPTER RD UNIT 4 Pensacola, FL 32514 (850) 500-4937

Contractor is in violation of Florida Building Code 105.4 and Marion County Code of Ordinances 5.5-33(i)(1) by having allowed to expire and/or exhausted all extensions without obtaining a passing inspection within a 180-day period, on permits 2018061580, 2020062104 and 2022120006, constituting abandonment of the job.

<u>COMPLAINT CERTIFICATION, PLEASE READ CAREFULLY BEFORE SIGNING.</u> I HEREBY CERTIFY AND/OR AFFIRM THAT ALL INFORMATION FURNISHED IN THIS COMPLAINT IS TO THE BEST OF MY KNOWLEDGE, TRUE AND CORRECT.

a felrichte Signature of Investigator: _

Date: <u>2-13-24</u>

Empowering Marion for Success

marionfl.org



Marion County

License Review Board

Agenda Item

File No.: 2024-14571

Agenda Date: 4/9/2024

Agenda No.: 8.4.

SUBJECT: LRB 2024-7 Marion County Building Dept. v. Philip Thomas Dolfi / Custom Vinyl Systems Inc.



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

February 15, 2024

CERTIFIED MAIL #7020 2450 0000 1094 2589

PHILIP THOMAS DOLFI / CUSTOM VINYL SYSTEMS INC 2110 SW 7TH AVE STE 103 OCALA, FL 34471 CT # 14827

Dear Mr. Dolfi;

Please be advised a formal complaint, Case # LRB 2024-7 has been brought against you by:

Complainant's Name:

MARION COUNTY BUILDING DEPARTMENT 2710 E. SILVER SPRINGS BLVD OCALA, FL 34470

Before the Marion County License Review Board at their meeting on Tuesday, April 9th, 2024 at 5:30 P.M. In the Marion County Growth Management Building – Training Facility at 2710 E. Silver Springs Blvd. Enclosed is a copy of the complaint and supporting documentation.

It is requested that you attend this meeting. You may bring legal counsel to this meeting (if you so desire.) Any additional documentation substantiating your claim must be received ten (10) working days prior to the hearing as it is accepted as evidence and therefore becomes part of the case file. You will be given five (5) minutes to present your case and then a two (2) minute rebuttal.

Please contact the License Review Board Secretary at 438-2429 on Monday, April 8th, 2024 to verify the status of this complaint. Should you settle your dispute prior to the case date, please ask the complainant to send the Building Department a written statement before the scheduled hearing date requesting the complaint be withdrawn.

Please be advised, if any person or persons wish to appeal a decision of the license review board made at the above hearing, a record of the proceedings will be needed by such person or persons as well as a verbatim record. If you wish to preserve the testimony given at the hearing, you must make your own arrangements to do so. If any person requiring special equipment should contact the Board Secretary at least two (2) business days prior to the meeting.

Sincerely,

Antoinette Hernandez License Review Board Secretary

Empowering Marion for Success



CODE ENFORCEMENT SERVICES

Marion County, Florida

CDPR4205 - Acti	on Order D	etail Report	t			•				
<u>OPEN DATE:</u>	February	∕ 12, 202 ∠		TIME:	03:08	B PM	ACTI	ON ORDER NBR:	661614	
OPENED BY:	BU341MI	-1		DUE D	ATE	2/12/2024	4 <u>D</u>	ISPATCHED BY		
<u>COMPLAINANT</u>	_						D	ate/Time:		
TYPE:	-	<u>IAME:</u> DDRESS:	LMF	-			LRB 2024-7			
CTZN		<u>PHONE:</u>					Marion Count	У		
		FAX:					v. Phillip Thoma Certificate # 1	us Dolfi / Custom Vin 4827	yl Systems Inc.	
ALLEGED VIOL	ATORS:						AO 661614			
Property C	Wner	NAME:				·				
□ Tenant		ADDRES	S:							
		PHONE:				<u></u>				
		FAX:								
ALLEGED VIOL	ATION(S):									
CON-PERMIT	CON -	PERMITS								• •
permitted 20210)92673, rep	ermitted 20	2212	1077 - w	anting t	to permit a	3rd time.			
		10								
LOCATION OF 9268 SW 56TH										
<u>9266 SW 561 H</u> <u>RANGE:</u> 20		/ <u>NSHIP:</u>	16		SEC	<u>TION:</u> 02				
DIRECTIONS /		<u>NOLITE .</u>	10			<u>11011.</u> 02				
REFERRED TO			VIFW	1						
		, (2)((1)(1)(2)	•							
								ZONIN	~ .	
		<u>un: Lt</u>	<u>EGAL:</u>							
INSPECTION D		VALID:		IN	VALID:		<u>OFFICER:</u> REFERRED:	ARBUCKLE.RYAN	<u>!</u> ARED:	
INSPECTION S					VALID.	·	NEFERNED.			
VIOLATION CO		<u>inno.</u>								
								<u></u>		
<u></u>							<u>_</u>			
					·					
		c								
NOTICE OF HE	ARING DA	.TE:			. <u>F</u>	RESULTS:			<u>:D:</u>	
CASE REVIEW	ED BY:							ROVAL DATE:		



Building Safety - Licensing

2710 E. Silver Springs Blvd. Ocala, FL 34470 Phone: 352-438-2400 buildinglicensing@marionfl.org

ADMINISTRATIVE REVIEW MARION COUNTY LICENSE REVIEW BOARD

LRB# 2024-5

COMPLAINANT/PETITIONER:

Marion County Licensing Division - Building Official 2710 East Silver Springs Boulevard Ocala, FL 34470 (352) 438-2429

CONTRACTOR/RESPONDENT

PHILIP THOMAS DOLFI DBA / CUSTOM VINYL SYSTEMS INC Certificate # 14827 2110 SW 7TH AVE STE 103 Ocala FL 34471 (352) 237-3088

Contractor is in violation of Florida Building Code 105.4 and Marion County Code of Ordinances 5.5-33(i)(1) by having allowed to expire and/or exhausted all extensions without obtaining a passing inspection within a 180-day period, on permits 2021092673 and 2022121077, constituting abandonment of the job.

<u>COMPLAINT CERTIFICATION, PLEASE READ CAREFULLY BEFORE SIGNING.</u> I HEREBY CERTIFY AND/OR AFFIRM THAT ALL INFORMATION FURNISHED IN THIS COMPLAINT IS TO THE BEST OF MY KNOWLEDGE, TRUE AND CORRECT.

Signature of Investigator: _

- Asbuchie

Date: 2-13-24

Empowering Marion for Success

