FIRST AMENDMENT TO THE AGREEMENT

In accordance with the Fire Station 11 CM AT RISK Agreement entered into on February 29, 2024, and all of its amendments (if any), collectively (the "Agreement") this First Amendment to the Agreement (this "Amendment") is made and entered into by and between **Dinkins Construction LLC**, whose address is 2831 SE 17th Street, Ocala, FL 34471; possessing FEIN <u>27-0867581</u>, (hereinafter referred to as "CM AT RISK") and Marion County, a political subdivision of the State of Florida, 601 SE 25th Avenue, Ocala, FL, 34471, (hereinafter referred to as "COUNTY").

WITNESSETH

WHEREAS this Amendment shall remain in full force and effect until completion of all services required of CM AT RISK, and the parties wish to amend the Agreement.

IN CONSIDERATION of the mutual covenants and conditions contained herein, COUNTY and CM AT RISK (singularly referred to as "Party", collectively "Parties") hereto agree as follows:

- 1. This Amendment shall be deemed to amend and become part of the Agreement in accordance with the project 24Q-055, (the "Project"). All provisions of the Agreement not specifically amended herein shall remain in full force and effect.
- 2. This Amendment adds the following provisions to the Agreement: Exhibit A Schedule of Values

IN WITNESS WHEREOF the Parties have entered into this Amendment, as approved by the Marion County Board of County Commissioners, on the date of the last signature below.

ALLSI

GREGORY C. HARRELL, DATE MARION COUNTY CLERK OF COURT

FOR USE AND RELIANCE OF MARION COUNTY ONLY, APPROVED AS TO FORM AND LEGAL SUFFICIENCY

MARION COUNTY, A POLITICAL SUB-DIVISION OF THE STATE OF FLORIDA

KATHY BRYANT CHAIRMAN DATE

BCC APPROVED: July 15, 2025 24Q-055-CA-01 Fire Station 11 CM AT RISK

MATTHEW G. MINTER, DATE MARION COUNTY ATTORNEY

DINKINS CONSTRUCTION LLC

DATE

PRINTED:

BY:

ITS: (TITLE)

SIGNATURE

WITNESS:

WITNESS:

SIGNATURE

PRINTED NAME

PRINTED NAME



MARION COUNTY FIRE STATION #11 - 24Q-055

<u>Schedule of Values</u> June 11, 2025

01015Contingency - Jobsite Super01018Jobsite Super01019Job Trailer Lec01600Job Trailer Lec01600Project Identif01050Permits - ALL01100Impact Fees -01150Builder's Risk01250Testing - Stiel01250Testing - Build01250Testing - GMF01250Testing - Spec01250Testing - Spec01255Soil Boring - E01300Surveying - As01430CADD Usage01450Blueprint Repr	ral Conditions EXCLUDED - See Below vision Cost ase Iding Tank cation Sign OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masony Testing - EXCLI ially Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	\$ \$ UDED \$	109,200.00 28,376.25 3,902.25 1,000.00 17,000.00 56,250.00 8,350.00	TBD Dinkins Dinkins Florida Express Dinkins Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01015Contingency - Jobsite Super01018Jobsite Super01019Job Trailer Lec01600Job Trailer Lec01600Project Identif01050Permits - ALL01100Impact Fees -01150Builder's Risk01250Testing - Stiel01250Testing - Build01250Testing - GMF01250Testing - Spec01250Testing - Spec01255Soil Boring - E01300Surveying - As01430CADD Usage01450Blueprint Repr	EXCLUDED - See Below vision Cost ase Iding Tank cation Sign OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLU ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	S S S S S S S S S S S S S S S S S S S	109,200.00 28,376.25 3,902.25 1,000.00 17,000.00 56,250.00 8,350.00 8,425.00	TBD Dinkins Dinkins Florida Express Dinkins Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01018Jobsite Super01019Job Trailer Le.01600Job Trailer Ho.01040Project Identif01050Permits - ALL01100Impact Fees -01150Builder's Risk01200Bonding - See01250Testing - Site01250Testing - Site01250Testing - Site01250Testing - Site01250Testing - Set01250Testing - Set01255Soil Boring - E01300Surveying - As01430CADD Usage01450Blueprint Repr	vision Cost ase Iding Tank cation Sign OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI ially Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	s s s s s s s s s s s s s s s s s s s	109,200.00 28,376.25 3,902.25 1,000.00 17,000.00 56,250.00 8,350.00 8,350.00 8,425.00	Dinkins Dinkins Florida Express Dinkins Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01019Job Trailer Le01600Job Trailer Ho01040Project Identifi01050Permits - ALL01100Impact Fees -01150Builder's Risk01200Bonding - See01250Testing - Site01250Testing - Build01250Testing - Bell01250Testing - Spec01250Testing - Spec01255Soil Boring - E01300Surveying - B01300Surveying - As01430Blueprint Repr	ase Iding Tank cation Sign OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLU ially Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	s s s s s s s s s s s s s s s s s s s	28,376.25 3,902.25 1,000.00 17,000.00 56,250.00 8,350.00 8,350.00 8,425.00	Dinkins Florida Express Dinkins Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01600Job Trailer Ho01040Project Identifi01050Permits - ALL01100Impact Fees -01150Builder's Risk01200Bonding - See01250Testing - Site01250Testing - Build01250Testing - Build01250Testing - GMF01255Soil Boring - E01300Surveying - At01300Surveying - At01430CADD Usage01450Blueprint Repr	Iding Tank cation Sign OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	s s s s s s s s s s s s s s s s s s s	3,902.25 1,000.00 17,000.00 56,250.00 8,350.00 8,425.00	Florida Express Dinkins Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01040Project Identifi01050Permits - ALL01100Impact Fees -01150Builder's Risk01200Bonding - See01250Testing - Build01250Testing - Build01250Testing - GMF01250Testing - GMF01250Testing - Spec01255Soil Boring - E01300Surveying - At01430CADD Usage01450Blueprint Repr	cation Sign OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI cialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	s s s s s s s s s s s s s s s s s s s	1,000.00 17,000.00 56,250.00 8,350.00 8,425.00	Dinkins Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01050Permits - ALL01100Impact Fees -01150Builder's Risk01200Bonding - See01250Testing - Site'01250Testing - Build01250Testing - GMF01250Testing - See01250Testing - See01250Testing - See01255Soil Boring - E01300Surveying - As01430CADD Usage01450Blueprint Repr	OWANCE EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masony Testing - EXCLI isialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	s s s s s s s s s s s s s s s s s s s	17,000.00 56,250.00 8,350.00 8,425.00	Marion County Excluded Brown and Brown Below Geo-Tech Geo-Tech
01100Impact Fees -01150Builder's Risk01200Bonding - See01250Testing - Site01250Testing - Build01250Testing - Bell01250Testing - Spec01250Testing - Spec01255Soil Boring - E01300Surveying - B01300Surveying - As01430Blueprint Repr	EXCLUDED Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI ially Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	s s s s s s uDED s puct	56,250.00 8,350.00 8,425.00	Excluded Brown and Brown Below Geo-Tech Geo-Tech
01150Builder's Risk01200Bonding - See01250Testing - Site01250Testing - Build01250Testing - PEM01250Testing - GMF01250Testing - Spec01255Soil Boring - E01300Surveying - B01300Surveying - As01430CADD Usage01450Blueprint Repr	Insurance - ALLOWANCE Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	\$ \$ \$ UDED \$	8,350.00 8,425.00	Brown and Brown Below Geo-Tech Geo-Tech
01200Bonding - See01250Testing - Site01250Testing - Build01250Testing - PEM01250Testing - GMF01250Testing - Spec01255Soil Boring - E01300Surveying - Bt01300Surveying - At01430CADD Usage01450Blueprint Repr	Below Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	\$ \$ \$ UDED \$	8,350.00 8,425.00	Below Geo-Tech Geo-Tech
01250Testing - Site01250Testing - Build01250Testing - Build01250Testing - GMF01250Testing - GMF01255Soil Boring - E01300Surveying - As01430CADD Usage01450Blueprint Repr	Work Allowance (Proctors, Compaction, Etc.) ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI isialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	\$ \$ UDED \$	8,350.00 8,425.00	Geo-Tech Geo-Tech
01250Testing - Build01250Testing - PEM01250Testing - GMF01250Testing - Spec01255Soil Boring - E01300Surveying - Build01300Surveying - Build01430CADD Usage01450Blueprint Repr	ing Materials (Cylinders, Slumps, Etc.) B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCL ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	\$ \$ UDED \$	8,425.00	Geo-Tech
01250Testing - PEM01250Testing - GMF01250Testing - Spec01255Soil Boring - E01300Surveying - B01300Surveying - As01430CADD Usage01450Blueprint Repr	B Nuts and Bolts Inspection REVIEW 5-15-25 - Masonry Testing - EXCLI ially Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	\$ UDED \$		
01250Testing - GMF01250Testing - Spec01255Soil Boring - E01300Surveying - B01300Surveying - As01430CADD Usage01450Blueprint Repr	REVIEW 5-15-25 - Masonry Testing - EXCLI ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	UDED \$	1,200.00	
01250Testing - Spec Pressurization01255Soil Boring - E Soil Surveying - Bu 0130001300Surveying - Au CADD Usage01430Blueprint Repr	ialty Testing - Windows, Caulking, Floor Flatn - EXCLUDED XCLUDED uilding Comers and Benchmark	less Duct		
01250 Pressurization 01255 Soil Boring - E 01300 Surveying - B 01300 Surveying - As 01430 CADD Usage 01450 Blueprint Repr	- EXCLUDED XCLUDED uilding Comers and Benchmark	s \$		EXCLUDED
01255Soil Boring - E01300Surveying - Bu01300Surveying - As01430CADD Usage01450Blueprint Repr	XCLUDED ilding Comers and Benchmark			Excluded
01300 Surveying - Bu 01300 Surveying - As 01430 CADD Usage 01450 Blueprint Repr	uilding Comers and Benchmark	\$		Excluded
01300 Surveying - As 01430 CADD Usage 01450 Blueprint Repr	-	\$ (3,500.00	
01430 CADD Usage 01450 Blueprint Repr	5 Bullt	\$	2,000.00	
01450 Blueprint Repr		\$	1,500.00	
		\$	1,500.00	QRS
		Ť		
	and Food ALLOWANCE GATEGO CARL	n to Duildin - "	7 500 00	Municipality
01500 Utility Deposits	and Fees - ALLOWANCE for TECO Gas Lin	ne to Building \$	7,500.00	Municipality
01500 Utility Deposits	and Fees - Electric Utility Fees - EXCLUDE	\$	-	Excluded
01510 Water & Sewe	r Connection Fees - EXCLUDED	\$	-	Excluded
01520 Water Meter -	EXCLUDED	\$		Excluded
	lities - Provider Set Up Fees	\$		Utility Provider Allowance
	lities - Pole Install	S		Utility Provider Allowance
	lities - Safety Light	\$		Utility Provider Allowance
	lities - Monthly Construction Service	s S		Utility Provider Allowance
	lities - Hot Check Service Fees lities - Water Monthly Service	S S		Utility Provider Allowance Utility Provider Allowance
	lities - Meter Rental	3 S		Utility Provider Allowance
01330 Temporary Ou	intes - Weter Rental	*	000,00	
01600 Portable Sanit	ation - Toilets	s	9,600,00	Florida Express
Portable Sanit	ation - GMP REVIEW 5-15-25 - Hand Wash S	Stations -		
01600 EXCLUDED		\$	-	EXCLUDED
01650 Refuse Contai	ners	\$	27,300.00	Florida Express
01650 Storage Conta	iners	\$	4,000.00	Buck Storage
01700 Equipment Re		\$	14,400.00	
	ntal / Scaffold - Water Trailer With Pump - 4 N		6,600.00	
	g - GMP REVIEW 5-15-25 - 1500 LF - EXCLU			EXCLUDED Many Aquirro
	struction Cleaning	\$		Mary Aguirre
	al Construction Cleaning xing - EXCLUDED	\$		Mary Aguirre
01850 Cleaning - Wa 01900 Direct Job Site		\$ \$		Excluded Action Labor
	- Field Office and Job Site Equipment, Tools,		5,000.00	
	 Protection of Finished Surfaces & Weatherp 		5,000.00	
	- Maintenance of Traffic	stooting \$	2,500.00	
	Signage for Security and Safety	\$	2,500.00	
	s & Materials - hard hats, vests, PPE, first aid		1,500.00	
01975 Punch Out Ma		, c.c. \$	5,000.00	
01980 Procore Usage		\$	10,200.00	
		itions Subtotal \$		



MARION COUNTY FIRE STATION #11 - 24Q-055


# STE DEVELOPMENT VALUES NOTES 00000 Suburities General Quantities Suburities General Arbeits 115 \$ 5,25.00 Marine Rock \$ 5,20.00 00000 Teaing - 11.5 \$ 5,25.00 Marine Rock \$ 20,000 Marine Rock \$ 20,000 00000 Teaing - 11.5 \$ 12,000.00 Marine Rock \$ 22,000 Marine Rock \$ 22,000.00 00000 BULCONTECT SINGARY - SWPPP Construction Entrance - 11.5 \$ 42,975.00 Marine Rock \$ 03,887.5 00000 Construction Entrance - 11.5 \$ 0,388.75 Marine Rock \$ 0,388.75 Marine Rock \$ 0,388.75 00000 Sibicontract Silework - SwPPP Construction Entrance - 11.5 \$ 1,355.00 Marine Rock \$ 0,388.75 Marine Rock \$ 0,388.75 00000 Sibicontract Silework - SwPPP Construction - 205.1F \$ 1,172.50 Marine Rock \$ 0,388.75 Marine Rock \$ 0,388.75 00000 Marine Rock \$ 1,358.00 S 1,355.00 Marine Rock \$ 0,355.00 Marine Rock \$ 0,355.00 00000 Sibicontract Silework - SwPPP Construct Silework - SwPPP Sibilized Subgrade - 1401 SY \$ 1,358.20 Marine Rock \$ 1,358.20 00000 Sibilized Silized Sibilized Silized Silized Sibilized Silized Sibilized Silized Silized Silized Silized Silized		June 11, 2025				
02000 Subcontract Sitework - Seneral 5 5.425.00 Marion Rock 02000 As-Bults -1 LS \$ 6.033.00 Marion Rock 02000 Mobilization -1 LS \$ 6.033.00 Marion Rock 02000 Mobilization -1 LS \$ 4.2000.00 Marion Rock 02000 BDI LEVELER - GMP REVIEW 5.15.25 - CONTINGENCY - EXCLUDED \$ - EXCLUDED 02000 BDI LEVELER - GMP REVIEW 5.15.25 - CONTINGENCY - EXCLUDED \$ - EXCLUDED 02000 Construction Entrance -1 LS \$ 4.435.00 Marion Rock 02000 Construction Entrance -1 LS \$ 1.925.00 Marion Rock 02000 Sile Fince - 5005 LF \$ 1.925.00 Marion Rock 02000 Sile Clean Up -1 LS \$ 2.500.00 Dirkins 02000 Sile Clean Up -1 LS \$ 2.500.00 Dirkins 02000 Sile Clean Up -1 LS \$ 5 5.65.55 Marion Rock 02000 Sile Clean Up -1 LS \$ 5 5				VALUES	NOTES	
02000 Layout and Survey -1 LS \$ 5425.00 Marion Rock 02000 Testing -1 LS \$ 6.030.00 Marion Rock 02000 MOT -1 LS \$ 8.200.00 Marion Rock 02025 Mobilization -1 LS \$ 42.975.00 Marion Rock 02026 BID LEVELER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED \$ - EXCLUDED 02000 Subcontract Sitework - SWPPP \$ 43.950.00 Marion Rock 02000 Subcontract Sitework - SWPPP \$ 11.27.30 \$ 43.950.00 02000 Subcontract Sitework - SWPPP \$ 11.27.30 \$ 11.97.20 02000 Construction Entrance -1 LS \$ 11.97.20 \$ 11.97.20 02000 Site Cenau Do -1 LS \$ 2.900.00 Marion Rock 02000 Site Cenau Do -1 LS \$ 1.95.55 Marion Rock 02000 Site Cenau Do -1 LS \$ 1.95.55 Marion Rock 02000 Site Cenau Do -1 LS \$ 1.95.55 S 1.95.55 02000 Site Cenau Do -1 LS \$ 1.95.55 S 1.95.55 02000 Site Cenau Do -1 LS \$ 1.95.55				VALUES	NOTES	
02000 As Builts - 11.S \$ 6.030.00 Marion Rock 02000 MOT - 11.S \$ 12.000.00 Marion Rock 02020 MoDitation - 11.S \$ 42.975.00 Marion Rock 02020 Bib LEVELER - GMP REVIEW 51-25- CONTINGENCY - EXCLUDED \$ 42.975.00 Marion Rock 02020 Bib LEVELER - GMP REVIEW 51-25- CONTINGENCY - EXCLUDED \$ 42.905.00 Marion Rock 02020 Construction Entrance - 11.S \$ 4.350.00 Marion Rock 02020 Construction Entrance - 11.S \$ 6.338.77, Marion Rock 020200 Tere Protection - 20.5 LF \$ 1.127.50 Marion Rock 020200 Silte Clean Up - 1 LS \$ 2.5000.00 Darion Rock 020200 Silte Clean Up - 1 LS \$ 1.956.55 Marion Rock 020200 Silte Clean Up - 1 LS \$ 1.956.55 Marion Rock 020200 Silte Clean Up - 1 LS \$ 1.956.55 Marion Rock 020200 Silte Clean Up - 1 LS \$ 1.956.55 Marion Rock 020200 Silte Clean Up - 1 LS \$ 1.956.55 Marion Rock 020200 Tere Rough Grading - 1491 SY \$ 1.956.55 Marion Rock			\$	5 4 2 5 0 0	Marion Rock	
12000 Testing - 11.S \$ 6200.00 Marion Rock 12020 MOT-11.S \$ 42975.00 Marion Rock 12022 Performance and Payment Bond - 11.S \$ 42970.00 Marion Rock 12020 Bib LEVELER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED \$ - EXCLUDED 12000 Subcontract Sitework - SWPPP \$ 4350.00 Marion Rock 12000 Subcontract Sitework - SWPPP \$ 4350.00 Marion Rock 12000 Subcontract Sitework - SWPPP \$ 4350.00 Marion Rock 12000 Site France - 5095 LF \$ 6,388.75 Marion Rock 12000 Intel Protection - 12 EA \$ 1,127.50 Marion Rock 12000 Subcontract Sitework - Asphalt Payment Marion Rock 12000 Subcontract Sitework - Asphalt Payment Marion Rock 12000 Subcontract Sitework - Suphalt Payment \$ 1,555.55 127 Subladied Subgrade - 1491 SY \$ 1,757.80 Marion Rock 128 Subgrade - 1491 SY \$ 1,757.80 Marion Rock 129 Subcontract Sitework - Asphalt Payment \$ 7,455.55 Marion Rock 12000 Filt Sitrace Coat - 1491 SY						
02000 MODT-1LS \$ 12,000,00 Maron Rock 02020 Bib LEVELER - GMP REVIEW 51-25- CONTINGENCY - EXCLUDED \$ 42,975,00 Maron Rock 02000 Bib LEVELER - GMP REVIEW 51-25- CONTINGENCY - EXCLUDED \$ 43,50,00 Maron Rock 02000 Bib LEVELER - GMP REVIEW 51-25- CONTINGENCY - EXCLUDED \$ 43,50,00 Maron Rock 02000 Construction Entrance - 1LS \$ 43,50,00 Maron Rock 02000 Subcontract Sitework - SWPPP \$ 6,388,77,50 Maron Rock 02000 Construction Entrance - 1LS \$ 6,388,77,50 Maron Rock 02000 Subcontract Sitework - Asphalt Pavement Maron Rock \$ 2,600,00 Maron Rock 02000 Subcontract Sitework - Asphalt Pavement Maron Rock \$ 13,85,20 Maron Rock 02000 Prime and Sand - 1491 SY \$ 1,852,55 Site Glaan Up - 1LS \$ 7,45,300 Maron Rock 02000 Prime and Sand - 1491 SY \$ 1,862,50 Maron Rock \$ 2,600,00 Maron Rock 02000 Prime and Sand - 1491 SY \$ 1,37,300 \$ 1,37,300 Maron Rock \$ 22,35,000 Maron Rock 02000 Prime and Sand - 1491 SY \$ 1,						
02025 Mobilization - 11.5 \$ 42,000.0 Marion Rock 02000 BID LEVELER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED \$ - EXCLUDED 02000 Subcontract Sitework - SWPPP 5 - EXCLUDED 02000 Subcontract Sitework - SWPPP 5 - EXCLUDED 02000 Site Face - 5095 LF 5 5,368.75 Airon Rock 02000 Inter Protection - 20.5 LF 5 1,36,00 Marion Rock 02000 Maintenance - 11.S 5 2,500,00 Dinkins 02000 Site Clean Up - 11.S 5 2,500,00 Dinkins 02000 Feary Duty Asphalt Marion Rock Marion Rock 02000 Frain rock - 1491 SY 5 1,565.55 Marion Rock 02000 Frain rock - 1491 SY 5 7,475.00 Marion Rock 02000 Frain Rock - 1491 SY 5 7,475.00 Marion Rock 02000 Frain Rock - 1491 SY 5 7,475.00 Marion Rock 02000 Frablack Surator Coat - 1491 SY <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>						
Did Evel.ER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED \$ 42,000.00 Marion Rock 0000 Subcontract Silework - SWPPP - EXCLUDED 0000 Construction Entrance - ILS \$ 4,350.00 Marion Rock 0000 Construction Entrance - ILS \$ 1,127.50 Marion Rock 0000 The Fredexion - 20 LF \$ 1,127.50 Marion Rock 0000 Marion Rock \$ 1,227.50 Marion Rock 0000 Marion Rock \$ 1,356.00 Marion Rock 0000 Marion Rock \$ 1,356.00 Marion Rock 0000 Bub Contract Silework - Asphalt Pavement Marion Rock 0000 Fleary Duty Asphalt \$ 1,555.55 Marion Rock 00000 Prime and Sand - 1491 SY \$ 1,555.55 Marion Rock 00000 Prime and Sand - 1491 SY \$ 2,28500 Marion Rock 00000 1.5" SP12.5 Construction Lill + 1491 SY \$ 2,28500 Marion Rock 00000 1.5" SP12.5 Construction Lill + 1491 SY \$ 2,28500 Marion Rock 00000 Flisbiabled Subgrade - 1312 SY \$ 7,472.0<						
02000 BID LEVELER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED \$ EXCLUDED 02000 Subcontract Sitework - SWPPE 5 4,350.00 Mariop Rock 02000 Site Face - 5095 LF 5 6,586.75 4,370.70 Rock 02000 Tree Protection - 205 LF 5 1,365.00 Marion Rock 02000 Maintenance - 1 LS 5 2,500.00 Dirking Rock 02000 Site Clean Up - 1 LS 5 2,500.00 Dirking Rock 02000 Flags Subcontract Sitework - Asphalt Pavement Marion Rock 20000 02000 Prime and Sand - 1491 SY 5 1,75.719.00 Marion Rock 02000 Prime and Sand - 1491 SY 5 7.475.00 Marion Rock 02000 Prime and Sand - 1491 SY 5 7.475.00 Marion Rock 02000 Prime and Sand - 1491 SY 5 7.475.00 Marion Rock 02000 File Sourdare Coat - 1491 SY 5 7.475.00 Marion Rock 02000 File Sourdare Coat - 1491 SY 5 7.475.00 Marion Roc						
00000 Subcontract Sitework - SWPPP 02000 Construction Entrance - 11.S \$ 4,350.00 Marior Rock 02000 Tree Protection - 205 LF \$ 6,387.57 Marion Rock 02000 Marior Protection - 205 LF \$ 1,277.50 Marion Rock 02000 Marior Protection - 13 EA \$ 1,325.00 Marion Rock 02000 Marior Index \$ 2,500.00 Marion Rock 02000 Site Clean Up - 11.S \$ 2,500.00 Marion Rock 02000 Rough Grading - 1491.SY \$ 1,825.55 Marion Rock 02000 Privacy Duty Asphait Marion Rock 0.000 02000 Prime and Sand - 1491 SY \$ 1,718.25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 1,718.25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 22.365.00 Marion Rock 02000 Tack Coat - 1491 SY \$ 1,718.25 Marion Rock 02000 Tack Coat - 1491 SY \$ 2,2365.00 Marion Rock 02000 Tack Coat - 1491 SY \$ 1,378.60 Marion Rock				42,000.00		
02000 Construction Entrance - 11.S \$ 4,350.00 Marin Rock 02000 Sile Incree - 5095 LF \$ 1,355.00 Marin Rock 02000 Tree Protection - 205 LF \$ 1,355.00 Marin Rock 02000 Inite Protection - 13 EA \$ 2,500.00 Marin Rock 02000 Maintenance - 11.S \$ 2,500.00 Marin Rock 02000 Sile Clean Up - 11.S \$ 2,500.00 Dinkins 02000 Marin Rock \$ 2,500.00 Dinkins 02000 Heavy Duty Asphal \$ 1,556.55 Marin Rock 02000 Prime and Sand - 1491 SY \$ 1,556.55 Marin Rock 02000 Prime and Sand - 1491 SY \$ 1,118.25 Marin Rock 02000 Prime and Sand - 1491 SY \$ 1,118.25 Marin Rock 02000 1.5' SP12.5 Stratee Coal - 1491 SY \$ 22,305.00 Marin Rock 02000 Auto Asphalt Pavement Marin Rock \$ 22,305.00 Marin Rock 02000 Guty Grading - 1312 SY \$ 1,377.60 Marin Rock \$ 1,377.60 Marin Rock 02000 <td>02000</td> <td>BID LEVELER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED</td> <td>4</td> <td></td> <td>EXCLODED</td> <td></td>	02000	BID LEVELER - GMP REVIEW 5-15-25 - CONTINGENCY - EXCLUDED	4		EXCLODED	
02000 Silt Fance - 305 LF \$ 6,368.75 . Marinn Rock 02000 Tree Protection - 205 LF \$ 1,355.00 02000 Maintenance - 1 LS \$ 2,500.00 02000 Silt Event D, 1 LS \$ 2,500.00 02000 Silt Cean Up - 1 LS \$ 2,500.00 02000 Silt Cean Up - 1 LS \$ 1055.55 02000 Silt Cean Up - 1 LS \$ 1055.55 02000 Tark Silt Silt Silt Silt Silt Silt Silt Silt						
02000 Tree Protection - 13 EA \$ 1,127.50 Marion Rock 02000 Maintenance - 1 LS \$ 2,500.00 Marion Rock 02000 Site Clean Up - 1 LS \$ 2,500.00 Dinkins 02000 Heavy Duty Asphalt Marion Rock 02000 Rough Grading - 1491 SY \$ 6194.60 Marion Rock 02000 9" Lime rock - 1491 SY \$ 6194.60 Marion Rock 02000 9" Lime rock - 1491 SY \$ 6194.60 Marion Rock 02000 9" Lime rock - 1491 SY \$ 6194.60 Marion Rock 02000 9" Lime rock - 1491 SY \$ 17,519.25 Marion Rock 02000 7" SP12.5 Surface Coat - 1491 SY \$ 243.50 Marion Rock 02000 Tack Coat - 1491 SY \$ 1,37.60 Marion Rock 02000 Tack Coat - 1491 SY \$ 745.50 Marion Rock 02000 Tack Coat - 1491 SY \$ 745.50 Marion Rock 02000 Auto Asphalt Pavement Marion Rock \$ 767.00 02000 Auto Asphalt Pavement Marion Rock \$ 777.20 02000 G" Stabileed Subgrade - 1312 SY \$ 7.871.20 Marion Ro						
02000 Intel Protection - 13 EA \$ 1365.00 Maintenance - 1 LS 02000 Maintenance - 1 LS \$ 2,500.00 Maintenacc 02000 Stubcontract Sitework - Asphalt Pavement Marion Rock 02000 Heavy Duty Asphalt Marion Rock 02000 TS Isbilized Subgrade - 1491 SY \$ 1,565.55 Marion Rock 02000 12" Stabilized Subgrade - 1491 SY \$ 1,752.25 Marion Rock 02000 Prime rock - 1491 SY \$ 1,752.25 Marion Rock 02000 Prime rock - 1491 SY \$ 1,752.25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 1,752.50 Marion Rock 02000 Tack Coat - 1491 SY \$ 1,752.00 Marion Rock 02000 1.5" SP12.5 Construction Lift - 1491 SY \$ 22,365.00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock \$ 22,000.00 Marion Rock 02000 B" Stabilized Subgrade - 1312 SY \$ 1,377.60 Marion Rock 02000 Prime and Sand - 1312 SY \$ 1,377.60 Marion Rock 02000 Prime rock - 1491 SY \$ 22,960.00 Marion Rock 02000						
02000 Maintenance - 1.1S \$ 2,500.00 Maintenance - 1.1S 02000 Site Clean Up - 1 LS \$ 2,500.00 Dinkins 02000 Rough Grading - 1491 SY \$ 1,565.55 Marion Rock 02000 B' Lime rock - 1491 SY \$ 1,565.55 Marion Rock 02000 9" Lime rock - 1491 SY \$ 1,7519.25 Marion Rock 02000 9" Lime rock - 1491 SY \$ 1,7519.25 Marion Rock 02000 15" SP12.5 Unstace Coat - 1491 SY \$ 7,45.50 Marion Rock 02000 Tack Coat - 1491 SY \$ 2,365.00 Marion Rock 02000 1.5" SP12.5 Unstruction Lift - 1491 SY \$ 2,365.00 Marion Rock 02000 Auto Aphalt Pavement Marion Rock \$ 2,365.00 Marion Rock 02000 Filme rock - 1312 SY \$ 1,377.60 Marion Rock \$ 1,377.60 Marion Rock 02000 Filme rock - 1312 SY \$ 1,377.60 Marion Rock \$ 1,377.60 Marion Rock 02000 Filme rock - 1312 SY \$ 3,255.00 Marion Rock \$ 1,377.60 Marion Rock \$ 1,377.60						
02000 Site Clean Up - 1 LS \$ 2,500,000 Dinkins 02000 Subcontract Sitework - Asphalt Pavement Marion Rock 02000 Heavy Duty Asphalt Marion Rock 02000 12° Stabilized Subgrade - 1491 SY \$ 1,585.55 Marion Rock 02000 Prime and Sand - 1491 SY \$ 1,7519.25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 7,7519.25 Marion Rock 02000 Tack Coat - 1491 SY \$ 7,7519.25 Marion Rock 02000 1,5° SP12.5 Construction Lift - 1491 SY \$ 223,65:00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock Marion Rock 220,66:00 Marion Rock 02000 B° Stabilized Subgrade - 1312 SY \$ 1,377.60 Marion Rock 220,000.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 1,377.60 Marion Rock 220,000.00 Marion Rock 02000 Prime and Replace Coat - 1312 SY \$ 3,255.00 Marion Rock 22,365.00 Marion Rock						
O2000 Subcontract Sitework - Asphalt Pavement Majon Rock O2000 Rough Grading - 1491 SY \$ 5 1,585,55 Manon Rock O2000 Sitabilized Subgrade - 1491 SY \$ 8 6,846,00 Marion Rock O2000 Sitabilized Subgrade - 1491 SY \$ 17,519,25 Marion Rock O2000 Sitabilized Subgrade - 1491 SY \$ 17,519,25 Marion Rock O2000 Tack Coat - 1491 SY \$ 22,365,00 Marion Rock O2000 1,5" SP12,5 Suface Coat - 1491 SY \$ 22,365,00 Marion Rock O2000 1,5" SP12,5 Construction Lift - 1491 SY \$ 22,365,00 Marion Rock O2000 1,5" SP12,5 Suface Coat - 1312 SY \$ 1,377,60 Marion Rock O2000 Rough Grading - 1312 SY \$ 7,872,00 Marion Rock O2000 Filme rock - 1312 SY \$ 7,872,00 Marion Rock O2000 Filme rock - 1312 SY \$ 22,960,00 Marion Rock O2000 Filme rock - 1312 SY \$ 3,255,00 Marion Rock O2000 Filme rock - 1312 SY \$ 3,255,00			\$			
02000 Heavy Duty Asphalt Marion Rock 02000 Rough Grading - 1491 SY \$ 1,555,55 Marion Rock 02000 9" Lime rock - 1491 SY \$ 6,946,00 Marion Rock 02000 9" Lime rock - 1491 SY \$ 745,55 Marion Rock 02000 9" Lime rock - 1491 SY \$ 745,50 Marion Rock 02000 Tack Coal - 1491 SY \$ 745,50 Marion Rock 02000 Tack Coal - 1491 SY \$ 745,50 Marion Rock 02000 1.5" SP12.5 Stratee Coat - 1491 SY \$ 745,50 Marion Rock 02000 1.5" SP12.5 Construction Lift - 1491 SY \$ 22,365,00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock Marion Rock 02000 6" Lime rock - 1312 SY \$ 1,377.60 Marion Rock 02000 6" Lime rock - 1312 SY \$ 22,960.00 Marion Rock 02000 7: Brainized Stubgrade - 1312 SY \$ 3,255.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255.00 Marion Rock 02000 1.2" Stabilized Stubgrade at HC Parking, HD Conc	02000	Site Clean Up - 1 LS	\$	2,500.00	Dinkins	
02000 Rough Grading - 1491 SY \$ 1,55,55 Marion Rock 02000 9" Lime rock - 1491 SY \$ 17,519,25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 17,519,25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 17,118,25 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1491 SY \$ 22,365,00 Marion Rock 02000 1.5" SP12.5 Construction Lift - 1491 SY \$ 22,365,00 Marion Rock 02000 Auto Asphait Pavement Marion Rock 02000 Rough Grading - 1312 SY \$ 7,872,00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 11,808,00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 11,808,00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 11,808,00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 13,516,00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255,00 Marion Rock 02000 1.5" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad - \$ 13,516,00 Marion Rock 02000 1.5" Stabilized Subgrade at HC Parking, HD Concrete, and						
02000 12" Stabilized Subgrade - 1491 SY \$ 6 946.00 Marion Rock 02000 9" Lime rock - 1491 SY \$ 17,519.25 Marion Rock 02000 Tack Coal - 1491 SY \$ 745.50 Marion Rock 02000 Tack Coal - 1491 SY \$ 745.50 Marion Rock 02000 1.5" SP12.5 Londrace Coal - 1491 SY \$ 22,365.00 Marion Rock 02000 1.5" SP12.5 Construction Lift - 1491 SY \$ 22,365.00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock \$ 7,872.00 Marion Rock 02000 Reing Frading - 1312 SY \$ 1,377.60 Marion Rock \$ 7,872.00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 11,808.00 Marion Rock \$ 22,960.00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 11,808.00 Marion Rock \$ 22,960.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255.00 Marion Rock \$ 22,960.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255.00 Marion Rock \$ 13,518.00 Marion Rock 02000 Tree Removal and Clearing - 1 LS \$ 12,000	02000	Heavy Duty Asphalt				
02000 9" Lime rock - 140 ^T SY \$ 17,319,25 Marion Rock 02000 Prime and Sand - 1491 SY \$ 1,118,25 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1491 SY \$ 22,365,00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1491 SY \$ 22,365,00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1491 SY \$ 22,365,00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock \$ 1,377.60 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 1,377.60 Marion Rock 02000 7: Stabilized Subgrade Coat - 1312 SY \$ 11,808.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 22,960.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY \$ 3,255.00 Marion Rock 02000						
02000 Prime and Sand - 1491 SY \$ 1,118,25 Marion Rock 02000 Tack Coat - 1491 SY \$ 745,50 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1491 SY \$ 22,365,00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock 02000 Rough Grading - 1312 SY \$ 1,377,60 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 1,377,60 Marion Rock 02000 6" Lime rock - 1312 SY \$ 1,377,60 Marion Rock 02000 6" Lime rock - 1312 SY \$ 1,808,00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 11808,00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 1480,00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 3,255,00 Marion Rock 02000 Remove and Repiace Asphalt - 21 SY \$ 3,255,00 Marion Rock 02000 Remove and Repiace Asphalt - 21 SY \$ 3,255,00 Marion Rock 02000 Removal and Clearing - 1 LS \$ 22,960,00 Marion Rock 02050 Demolition \$ 22,960,00 Marion Rock 02050 Tree Removal an	02000	12" Stabilized Subgrade - 1491 SY	\$			
02000 Tack Coat - 1491 SY 5 745,50 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1491 SY 5 22,355,00 Marion Rock 02000 Auto Asphalt Pavement S 22,355,00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock S 1,3" S712.0 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY S 1,3" S72.00 Marion Rock 02000 6" Lime rock - 1312 SY S 1,18.08.00 Marion Rock 02000 Prime and Sand - 1312 SY S 118.08.00 Marion Rock 02000 Prime and Sand - 1312 SY S 118.08.00 Marion Rock 02000 Prime and Replace Coat - 1312 SY S 13.08.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY S 3.255.00 Marion Rock 02000 Remove and Replace Asphalt - 11S S 3.255.00 Marion Rock 02000 Tree Removal and Clearing - 1 LS S 3.2000.00 Marion Rock 02050 Tree Removal as Required for Ullily Install -1 LS S 4.000.00 Marion Rock	02000		\$			
02000 1.5" SP12.5 Surface Coat - 1491 SY \$ 22,365,00 Marion Rock 02000 1.5" SP12.5 Construction Lift - 1491 SY \$ 22,365,00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock 02000 Rough Grading - 1312 SY \$ 1,377,60 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 7,872.00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 7,872.00 Marion Rock 02000 75" Stabilized Subgrade - 1312 SY \$ 11,808.00 Marion Rock 02000 Remove and Replace Asphalt -21 SY \$ 3,255.00 Marion Rock 02000 Remove and Replace Asphalt -21 SY \$ 13,516.00 Marion Rock 02000 Tree Removal and Clearing - 11.S \$ 23,000.00 Marion Rock 02050 Demolition \$ 12,000.00 Marion Rock 02050 Tree Removal as Required for Utility Install -1 LS \$ 1,510.00 Marion Rock 02050 Remove and Reinstall Fencing for Utility Install -1 LS \$ 1,750.00 Marion Rock 02050 Removal of Stripping is/Clearing - 1 LS	02000		\$			
02000 1.5" SP12.5 Construction Lift - 1491 SY \$ 22,365.00 Marion Rock 02000 Auto Asphalt Pavement Marion Rock 02000 Rough Grading - 1312 SY \$ 1,377.60 Marion Rock 02000 B' Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 984.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 984.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 984.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 984.00 Marion Rock 02000 Remove and Repiace Asphalt -21 SY \$ 3.255.00 Marion Rock 02000 Remove and Repiace Asphalt -21 SY \$ 3.255.00 Marion Rock 02000 Tree Removal and Clearing - 1 LS \$ 23,000.00 Marion Rock 02050 Tree Removal as Required for Utility Install -1 LS \$ 4,600.00 Marion Rock 02050 Removal and Reinstall Fencing for Utility Install -1 LS \$ 10,944.00 Marion Rock 02050 Remo	02000		\$			
O2000 Auto Asphalt Pavement Marion Rock O2000 Rough Grading - 1312 SY \$ 1,377.60 Marion Rock O2000 8" Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock O2000 6" Lime rock - 1312 SY \$ 984.00 Marion Rock O2000 6" Lime rock - 1312 SY \$ 984.00 Marion Rock O2000 1.5" SP12.5 Surface Coat - 1312 SY \$ 984.00 Marion Rock O2000 1.5" SP12.5 Surface Coat - 1312 SY \$ 22,960.00 Marion Rock O2000 1.5" SP12.5 Surface Coat - 1312 SY \$ 3,255.00 Marion Rock O2000 Remove and Replace Asphalt -21 SY \$ 3,255.00 Marion Rock O2000 Tree Removal and Clearing - 1 LS \$ 13,516.00 Marion Rock O2050 Tree Removal and Clearing - 1 LS \$ 12,000.00 Marion Rock O2050 Tree Removal and Clearing - 1 LS \$ 20,250.00 Marion Rock O2050 Removal of Stipping and Grubbing - 1 LS \$ 10,944.00 Marion Rock O2050 Removal and Clearing - 1 LS \$ 10,944.00 Marion Rock	02000	1.5" SP12.5 Surface Coat - 1491 SY	\$			
02000 Rough Grading - 1312 SY \$ 1,377.60 Marion Rock 02000 8" Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 11,808.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 984.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 22,960.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY \$ 3,255.00 Marion Rock 02000 Ziso SY \$ 3,255.00 Marion Rock 02000 Demolition \$ 3,255.00 Marion Rock 02050 Demolition \$ 3,255.00 Marion Rock 02050 Stripping and Grubbing - 1 LS \$ 12,000.00 Marion Rock 02050 Stripping and Grubbing - 1 LS \$ 4,600.00 Marion Rock 02050 Removal and Reinstall Fencing for Ulility Install - 1 LS \$ 1,750.00 Marion Rock 02050 Removal and Reinstall Fencing or Ulility Install - 1 LS \$ 10,944.00 Marion Rock 02050 Removal and Reinstall Fencing rot - 150 SY \$ 3,085.25 Marion Rock 02000 Site Cut - 3648 CY \$ 10,944.00 Marion R	02000	1.5" SP12.5 Construction Lift - 1491 SY	\$	22,365.00	Marion Rock	
02000 Rough Grading - 1312 SY \$ 1,377.60 Marion Rock 02000 6" Stabilized Subgrade - 1312 SY \$ 7,872.00 Marion Rock 02000 6" Lime rock - 1312 SY \$ 11.808.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 984.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 984.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY \$ 22,960.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY \$ 3.255.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY \$ 3.255.00 Marion Rock 02000 Tree Removal and Clearing - 1 LS \$ 3.255.00 Marion Rock 02050 Demolition \$ 23,000.00 Marion Rock 02050 Stripping and Grubbing - 1 LS \$ 4,600.00 Marion Rock 02050 Removal and Rehstall Fencing for Utility Install - 1 LS \$ 4,600.00 Marion Rock 02050 Removal and Rehstall Fencing for Utility Install - 1 LS \$ 1,750.00 Marion Rock 02050 Removal and Rehstall Fencing for Utility Install - 1 LS \$ 1,750.00 Marion Rock 02000 Site C	02000	Auto Asphalt Pavement		~	Marion Rock	
020008" Stabilized Subgrade - 1312 SY\$7,872.00Marion Rock020006" Lime rock - 1312 SY\$11,808.00Marion Rock02000Prime and Sand - 1312 SY\$9,940.00Marion Rock020001.5" SP12.5 Surface Coat - 1312 SY\$22,960.00Marion Rock02000Remove and Replace Asphalt - 21 SY\$3,255.00Marion Rock0200012" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad- 2180 SY\$3,255.00Marion Rock02050Demolition\$13,516.00Marion Rock02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Tree Removal and Clearing - 1 LS\$12,000.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$10,944.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$10,944.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$10,944.00Marion Rock02050Site Cut - 3648 CY\$10,944.00Marion Rock02000Site Cut - 3648 CY\$15,9508.80Marion Rock02000Site Cut - 3648 CY\$15,9508.80Marion Rock02000Site Cut - 3648 CY\$\$16,317.7002000Site Cut - 3648 CY\$\$15,9508.800			\$	1,377.60	Marion Rock	
02000 6" Lime rock - 1312 SY \$ 11,808.00 Marion Rock 02000 Prime and Sand - 1312 SY \$ 22,960.00 Marion Rock 02000 1.5" SP12.5 Surface Coat - 1312 SY \$ 22,960.00 Marion Rock 02000 Remove and Replace Asphalt - 21 SY \$ 3,255.00 Marion Rock 02000 12" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad - 2180 SY \$ 13,516.00 Marion Rock 02050 Demolition \$ 23,000.00 Marion Rock 02050 Tree Removal and Clearing - 1 LS \$ 23,000.00 Marion Rock 02050 Tree Removal as Required for Ullilly Install - 1 LS \$ 1,750.00 Marion Rock 02050 Remove and Reinstall Fencing for Ullilly Install - 1 LS \$ 1,0944.00 Marion Rock 02050 Removal of Stripping's/Clearing - 1 LS \$ 10,944.00 Marion Rock 02050 Removal of Stripping's/Clearing - 1 LS \$ 10,944.00 Marion Rock 02050 Removal of Stripping's/Clearing - 1 LS \$ 10,944.00 Marion Rock 02050 Removal and Compact Building Pad - 1505 SY \$ 3,085.25 Marion Rock 02200 Import Fill - 9328 CY \$ 159,508.80 Marion			\$			
02000Prime and Sand - 1312 SY984.00Marion Rock020001.5" SP12.5 Surface Coat - 1312 SY\$984.00Marion Rock02000Remove and Replace Asphall - 21 SY\$3.255.00Marion Rock12" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad - 2180 SY\$3.255.00Marion Rock02050Demolition\$23,000.00Marion Rock02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$10,944.00Marion Rock02050Site Fill - 1297 CY\$10,944.00Marion Rock02050Site Fill - 1297 CY\$10,944.00Marion Rock02050Site Fill - 1297 CY\$10,944.00Marion Rock02050Site Fill - 1297 CY\$3,085.25Marion Rock02200Fill - 9328 CY\$159,508.80Marion Rock02200Fill - 1297 CY\$10,925.00Marion Rock02200Flace and Compact Building Pad - 1505 SY\$3,085.25Marion Rock02200Fills Grade - 11500 SY\$10,925.00Marion Rock02200Fills Grade - 11500 SY\$5,508.00 <t< td=""><td></td><td></td><td>\$</td><td>11,808.00</td><td>Marion Rock</td><td></td></t<>			\$	11,808.00	Marion Rock	
020001.5" SP12.5 Surface Coat - 1312 SY\$22,960.00Marion Rock02000Remove and Replace Asphalt - 21 SY\$3.255.00Marion Rock0200012" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad- 2180 SY\$3.255.00Marion Rock02050Demolition\$23,000.00Marion Rock02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$10,944.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$10,944.00Marion Rock02050Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Cut - 3648 CY\$\$10,944.00Marion Rock02200Finish Grade - 11500 SY\$\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$10,925.00Marion			\$			
12" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad - 2180 SY13,516.00Marion Rock02050Demolition\$23,000.00Marion Rock02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$10,944.00Marion Rock02050Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Fill - 12976 CY\$42,172.00Marion Rock02200Site Fill - 12976 CY\$3,085.25Marion Rock02200Rough Grade - 23311 SY\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$10,925.00Marion Rock02200Grade for Concrete - 2448 SY\$5,508.00Marion Rock02200Grade for Concrete - 2448 SY\$\$5,508.0002200DRA Construction per Notes on C9 of 16 - 1 LS\$3,675.00Marion Rock			\$			
12" Stabilized Subgrade at HC Parking, HD Concrete, and Dumpster Pad - 2180 SY13,516.00Marion Rock02050Demolition\$13,000.00Marion Rock02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250.00Marion Rock02200Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Fill - 12976 CY\$42,172.00Marion Rock02200Site Gut - 3648 CY\$159,508.80Marion Rock02200Site Gut - 3648 CY\$159,508.80Marion Rock02200Site Gut - 3648 CY\$10,944.00Marion Rock02200Site Gut - 3648 CY\$\$10,944.00Marion Rock02200Site Gut - 3648 CY\$\$10,944.00Marion Rock02200Site Gut - 3648 CY\$\$10,944.00Marion Rock02200Site Gut - 11976 CY\$\$10,944.00Marion Rock02200Finish Grade - 23311 SY\$\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$\$ <td>02000</td> <td>Remove and Replace Asphalt - 21 SY</td> <td>\$</td> <td>3,255,00</td> <td>Marion Rock</td> <td></td>	02000	Remove and Replace Asphalt - 21 SY	\$	3,255,00	Marion Rock	
020002180 SY313,310,00Marion Rock02050Demolition02050Tree Removal and Clearing - 1 LS\$23,000,00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000,00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600,00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750,00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250,00Marion Rock02200Site Cut - 3648 CY\$10,944,00Marion Rock02200Site Cut - 3648 CY\$10,944,00Marion Rock02200Site Cut - 3648 CY\$159,508,80Marion Rock02200Site Cut - 3648 CY\$159,508,80Marion Rock02200Site Gut - 3648 CY\$159,508,80Marion Rock02200Site Gut - 3648 CY\$\$159,508,8002200Site Gut - 3648 CY\$\$159,508,8002200Site Gut - 3648 CY\$\$3,085,2502200Import Fill - 9328 CY\$\$3,085,2502200Rough Grade - 23311 SY\$16,317,7002200Finish Grade - 11500 SY\$\$10,925,0002200Finish Grade - 11500 SY\$\$5,508,0002200Finish Grade - 11500 SY\$\$5,508,0002200Finish Grade - 11500 SY\$\$5,508,00 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td></td<>						
02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250.00Marion Rock02200Earthwork\$20,250.00Marion Rock02200Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Fill - 12976 CY\$42,172.00Marion Rock02200Site Fill - 12976 CY\$3,085.25Marion Rock02200Rough Grade - 23311 SY\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$10,925.00Marion Rock02200Grade for Concrete - 2448 SY\$5,508.00Marion Rock02200DrA Construction per Notes on C9 of 16 - 1 LS\$3,675.00Marion Rock	02000		Ф	13,516,00	Manon Rock	
02050Tree Removal and Clearing - 1 LS\$23,000.00Marion Rock02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$12,000.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250.00Marion Rock02050Earthwork\$20,250.00Marion Rock02200Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Fill - 12976 CY\$42,172.00Marion Rock02200Site Fill - 2976 CY\$3,085.25Marion Rock02200Place and Compact Building Pad - 1505 SY\$3,085.25Marion Rock02200Finish Grade - 21311 SY\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$10,925.00Marion Rock02200Finish Grade - 11500 SY\$5,508.00Marion Rock02200Grade for Concrete - 2448 SY\$\$5,508.00Marion Rock02200DRA Construction per Notes on C9 of 16 - 1 LS\$3,675.00Marion Rock	02050	Demolition				
02050Stripping and Grubbing - 1 LS\$12,000.00Marion Rock02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Remove and Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250.00Marion Rock02000Earthwork\$20,250.00Marion Rock02200Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Fill - 12976 CY\$42,172.00Marion Rock02200Site Fill - 12976 CY\$159,508.80Marion Rock02200Import Fill - 9328 CY\$3,085.25Marion Rock02200Rough Grade - 23311 SY\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$10,925.00Marion Rock02200Grade for Concrete - 2448 SY\$5,508.00Marion Rock02200Driveway install - 1 LS\$3,675.00Marion Rock02200DRA Construction per Notes on C9 of 16 - 1 LS\$3,675.00Marion Rock			\$	23,000.00	Marion Rock	
02050Tree Removal as Required for Utility Install - 1 LS\$4,600.00Marion Rock02050Removal ad Reinstall Fencing for Utility Install - 1 LS\$1,750.00Marion Rock02050Removal of Stripping's/Clearing - 1 LS\$20,250.00Marion Rock02200Earthwork\$20,250.00Marion Rock02200Site Cut - 3648 CY\$10,944.00Marion Rock02200Site Fiil - 12976 CY\$42,172.00Marion Rock02200Import Fiil - 9328 CY\$159,508.80Marion Rock02200Rough Grade - 23311 SY\$16,317.70Marion Rock02200Finish Grade - 11500 SY\$10,925.00Marion Rock02200Grade for Concrete - 2448 SY\$5,508.00Marion Rock02200Driveway install - 1 LS\$3,675.00Marion Rock02200DRA Construction per Notes on C9 of 16 - 1 LS\$3,675.00Marion Rock			\$	12,000.00	Marion Rock	
02050 Remove and Reinstall Fencing for Utility Install-1 LS \$ 1,750.00 Marion Rock 02050 Removal of Stripping's/Clearing - 1 LS \$ 20,250.00 Marion Rock 02200 Earthwork \$ 10,944.00 Marion Rock 02200 Site Cut - 3648 CY \$ 42,172.00 Marion Rock 02200 Site Fill - 12976 CY \$ 10,944.00 Marion Rock 02200 Dirpon Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Rough Grade - 23311 SY \$ 3,085.25 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Driveway install - 1 LS \$ 3,675.00 Marion Rock			\$	4,600.00	Marion Rock	
O2200 Earthwork \$ 10,944.00 Marion Rock O2200 Site Cut - 3648 CY \$ 42,172.00 Marion Rock O2200 Site Fill - 12976 CY \$ 42,172.00 Marion Rock O2200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock O2200 Place and Compact Building Pad - 1505 SY \$ 3,085.25 Marion Rock O2200 Rough Grade - 23311 SY \$ 16,317.70 Marion Rock O2200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock O2200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock O2200 Driveway install - 1 LS \$ 3,675.00 Marion Rock			\$			
02200 Site Cut - 3648 CY \$ 10,944.00 Marion Rock 02200 Site Fill - 12976 CY \$ 42,172.00 Marion Rock 02200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Place and Compact Building Pad - 1505 SY \$ 3,085.25 Marion Rock 02200 Rough Grade - 23311 SY \$ 16,317.70 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock			\$	20,250.00	Marion Rock	
02200 Site Cut - 3648 CY \$ 10,944.00 Marion Rock 02200 Site Fill - 12976 CY \$ 42,172.00 Marion Rock 02200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Place and Compact Building Pad - 1505 SY \$ 3,085.25 Marion Rock 02200 Rough Grade - 23311 SY \$ 16,317.70 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock	02200	Earthwork				
02200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Place and Compact Building Pad - 1505 SY \$ 3,085.25 Marion Rock 02200 Rough Grade - 23311 SY \$ 16,317.70 Marion Rock 02200 Flnish Grade - 21300 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock			\$			
02200 Import Fill - 9328 CY \$ 159,508.80 Marion Rock 02200 Place and Compact Building Pad - 1505 SY \$ 3,085,25 Marion Rock 02200 Rough Grade - 23311 SY \$ 16,317.70 Marion Rock 02200 Finish Grade - 1500 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock	02200	Site Fill - 12976 CY	\$			
02200 Rough Grade - 23311 SY \$ 16,317.70 Marion Rock 02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Move/Relocate/Replace Decorative Boulders as Required for Utility and Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock			\$	159,508.80	Marion Rock	
02200Finish Grade - 11500 SY\$ 10,925.00Marion Rock02200Grade for Concrete - 2448 SY\$ 5,508.00Marion Rock02200Move/Relocate/Replace Decorative Boulders as Required for Utility and Driveway install - 1 LS\$ 750.00Marion Rock02200DRA Construction per Notes on C9 of 16 - 1 LS\$ 3,675.00Marion Rock	02200	Place and Compact Building Pad - 1505 SY	\$	3,085.25	Marion Rock	
02200 Finish Grade - 11500 SY \$ 10,925.00 Marion Rock 02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Move/Relocate/Replace Decorative Boulders as Required for Utility and Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock	02200	Rough Grade - 23311 SY	\$	16,317.70	Marion Rock	
02200 Grade for Concrete - 2448 SY \$ 5,508.00 Marion Rock 02200 Move/Relocate/Replace Decorative Boulders as Required for Utility and Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock	02200		\$	10,925.00	Marion Rock	
02200 Driveway install - 1 LS \$ 750.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock	02200	Grade for Concrete - 2448 SY	\$	5,508.00	Marion Rock	
Driveway install - 1 LS \$ 3,675.00 Marion Rock 02200 DRA Construction per Notes on C9 of 16 - 1 LS \$ 3,675.00 Marion Rock	02200		\$	750.00	Marion Rock	
			\$			
02200 EXCLUDED - Proposal Assumes Windfab PP-10 is an Acceptable Product \$ 23,613.75 Marion Rock -31485 SF MIRAFI Non-Woven Erosion Mat - Erosion Mat ALLOWANCE \$ 40,930.50 Marion Rock 02200 Earthwork Remediation - EXCLUDED - See Alternates for Remove and Replace Unit Cost \$ - Excluded		MIRAFI Non-Woven Erosion Mat - QUALIFICAITON - MIRAFI is				
02200 MIRAFI Non-Woven Erosion Mat - Erosion Mat ALLOWANCE \$ 40,930.50 Marion Rock 02200 Earthwork Remediation - EXCLUDED - See Alternates for Remove and Replace Unit Cost \$ - Excluded	02200		t \$	23,613.75	Marion Rock	
02200 Earthwork Remediation - EXCLUDED - See Alternates for Remove and \$ - Excluded Replace Unit Cost		MIRAFI Non-Woven Erosion Mat - Erosion Mat ALLOWANCE	\$	40,930.50	Marion Rock	
Replace Unit Cost	02200				Evaluded	
	02200 02200		\$	<u>2</u>	Excluded	



MARION COUNTY FIRE STATION #11 - 24Q-055

Schedule of Values

	<u>Schedule of Values</u> June 11, 2025				
023					
023		\$	13.545.00	Marion Rock	
023		\$		Marion Rock	
023	00 24" RCP - 78 LF	\$	6,520.80	Marion Rock	
023	00 Type 6 Gutter Inlet - 2 EA	\$	19,830.00	Marion Rock	
023	00 Type C Inlet - 5 EA	\$	19,275.00	Marion Rock	
023	00 Type F Inlet - 2 EA	\$	9,180.00	Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$ \$		Marion Rock Marion Rock	
023		۹ \$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
022	Cleanouts - QUALIFICATION - Cleanouts are Note Shown - Allowance for	\$	4 200 00	Marion Rock	
023	10 Yard Drains - 10 EA	φ	4,200.00	Manon Rock	
					·
023					
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$	2,600.00	Marion Rock	
023	Lint Interceptor - QUALIFICATION - Lint Interceptor is Specified on the Plumbing Sheets and the Civil Sheets - Proposal Includes Lint Interceptor	\$	5 845 00	Marion Rock	
023	per the Civil Drawings	Ψ	0,040.00	Manon Rock	
023		\$	500.00	Marion Rock	
023		\$	105.00	Marion Rock	
023		\$	500.00	Marion Rock	
023					
	Lift Station Tum-Key - Dinkins Construction will Connect Power to the				
	Control Panel, All Other Electrical is to be included by the Site Work	¢	111 000 00	Marian Deale	
023		Ф	111,000.00	Marion Rock	
	the Site Work and Utility Subcontractor is to Furnish and Install the Transformer - 1 LS				
023		\$	14,718,90	Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
023		\$	2,795.00	Marion Rock	
023	00 Line Manhole - 1LS	\$	7,250.00	Marion Rock	
023	00 Utility Markers - 10 EA	\$	1,250.00	Marion Rock	
023		\$		Marion Rock	
023	00 Testing - 1 LS	\$	2,250.00	Marion Rock	
0230		•	04 500 00	Marian Deale	
0230		\$		Marion Rock	
0230		\$ \$		Marion Rock Marion Rock	
023		\$		Marion Rock	
023		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230	SCOPE REVIEW - Wet Tap - Drawings Do Not Call for Tapping Sleeve.	\$	13 900 00	Marion Rock	
	Can be Deducted if Not Required				
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock Marion Rock	
0230		\$ \$		Marion Rock	
0230	00 Testing - 1 LS	φ	3,000,00	Manun RUCK	
0230	0 Underground Utilities - Fire				
0230		\$	32,940.00	Marion Rock	
0230		\$		Marion Rock	
0230		\$		Marion Rock	
0230		\$	17,755.00		
0230		\$	3,040.00	Marion Rock	
0230		\$	3,300.00	Marion Rock	





MARION COUNTY FIRE STATION #11 - 24Q-055

	Schedule of Values			
	June 11, 2025 SCOPE REVIEW - Wet Tap - Drawings Do Not Call for Tapping Sleeve.			
02300	Can be Deducted if Not Required	\$	16,900.00	Marion Rock
	6" Neptune Meter and Valve Assembly. Meter Vault - Fire Truck Filling - 1	•	00 740 00	M I D I
02300	LS	\$	28,710.00	Marion Rock
02300	Fire Hydrant Assembly - Fire Truck Filling - 1 EA	\$	8,900.00	Marion Rock
02300	Fire Hydrant Assembly - 1 EA	\$		Marion Rock
02300	Utility Markers - 4 EA	\$		Marion Rock
02300	Fittings - 1 LS	\$		Marion Rock
02300	Testing - 1 LS	\$		Marion Rock
02300	Fire Watch - EXCLUDED	\$	10 A	Excluded
02375	Site Concrete			
02375	Curb and Gutter - 325 LF	\$	9.750.00	Marion Rock
02375	Trench Curb - 1215 LF	\$		Marion Rock
02450	Signage & Striping			
02450	Wheel Stops - 3 EA	\$		Marion Rock
02450	Handicap Parking Stall and Sign - 3 EA	\$		Marion Rock
02450	Handicap Aisle - 2 EA	\$		Marion Rock
02450	6" Wide Double Yellow Striping - 120 LF	\$		Marion Rock
02450	Stop Bar - 105 LF	\$		Marion Rock Marion Rock
02450 02450	Stop Sign - 3 EA Do Not Enter Sign - 2 EA	9 \$		Marion Rock
02450	Fire Truck Warning Sign - 3 EA	\$		Marion Rock
02450	Directional Arrows - 5 EA	\$		Marion Rock
02450	Parking Stripe - 741	\$		Marion Rock
02450	Crosswalk to Dumpster Pad - 60 LF	\$	90.00	Marion Rock
02475	Fencing & Gates - 6' Tall Light Commercial Grade Fence - Black Vinyl	\$	36 542 00	Allan Quality Fence
024/0	Coates Fence Wire and Framework - 2.5" Terminals and 2" Line Posts	*		hair ddairy'r orrod
02475	Fencing & Gates - 16' Double Drive Gate - 1 5/8" Frame - 3" Gate Post -	\$		Allan Quality Fence
02475	Buildog Style Hinges Fencing & Gates - Dumpster Gates - EXCLUDED	\$	_	Excluded
02475	Fencing & Gates - Chain-link Detail on C14 is EXCLUDED - We have	Ť		
02475	included Standard Light Commercial Black Chain Link per qualification	\$		Excluded
	above.			
02500	Landscaping	\$		TriCounty Landscape
02500	Landscaping - SCOPE REVIEW - 80 LF of Root Barrier	\$		TriCounty Landscape
02505	Landscape Grading	\$	2,500.00	
02525 02550	Irrigation System Site Furnishings - Site Sign - ALLOWANCE - No Details	\$		TriCounty Landscape Allowance
	Site Furnishings - Flag Pole - 30 Ft Commercial Flagpole XESR30F61-SAT	Ψ		
02550	EH HD Flag Poles	\$	5,711.48	Dinkins
02550	Site Furnishings - Flag Pole - Concrete Foundation and Apron	\$	3,500.00	Wavecrest
02575	Sodding & Seeding			
02575	Bahai Sod at DRA	\$		Marion Rock
02575	Sod Replacement at Off Site Utility Install	\$		Marion Rock
02575	Bahia Sod	\$		TriCounty Landscape TriCounty Landscape
02575 02575	Scope Review - Additional Sod - ALLOWANCE St. Augustine	\$ \$		TriCounty Landscape
	Irrigation Well - 4" Irrigation Well with 1.5 HP Pump Drilled to 100' - Sand			
02675	Filter is EXCLUDED	\$	10,500.00	TriCounty Landscape
02675	Irrigation Well - BFP and Concrete - ALLOWANCE	\$	4,000.00	TBD
	Site Development Subtotal	\$ 1	,538,972.14	



MARION COUNTY FIRE STATION #11 - 24Q-055



MARION COUNTY FIRE STATION #11 - 24Q-055

Schedule of Values June 11, 2025

#	STRUCTURAL STEEL		VALUES	NOTES
05000	Metal Building Labor			
05000	Metal Building Erection	\$	70,000.00	
05000	Electric Seamer for Nucor LocSeam 360 Standing Seam Panel	\$	3,000.00	Trimak
05000	SCOPE REVIEW - Additional Mobilizations for Construction Sequencing	\$	10,000.00	Trimak
05000	SCOPE REVIEW - PEMB Pressure Cleaning	\$	2,500.00	Dinkins
05000	SCOPE REVIEW - Install Ceiling Liner Panels	\$	21,868.00	Trimak
05010	Metal Building Material - QUALIFICATION - Refer to Nucor Proposal for	s	222,214.00	Nucor
03010	additional Qualifications	φ	222,214.00	NECO
05010	Metal Building Material - VOLUNTARY ALTERNATE - Use Ceiling and	\$	(a)	Nucor
	Wall Liner Panels In-Lieu of Liner System Insulation - Included Metal Building Material - Insulation is Included - Liner System Insulation is			
05010	EXCLUDED	\$	-	Nucor
05010	Metal Building Material - Connections to CMU and Miscellaneous	\$	5,000.00	Nucor
00010	Fasteners	*	5,000,00	indexi
05010	Metal Building Material - SCOPE REVIEW - Revise Portal Frame Locations and Change Roof to LOC-Seam In-Lieu of CFR	\$	10.099.00	Nucor
	Metal Building Material - QUALIFICATION - Deflections for Spandrel Beam			
	Not Specified - Proposal Assumes The Spandrel Channel which supports			
05010	the top of the masonry wall must be attached to the wall at 4'-0" O.C.	\$		Nucor
	maximum. The design of this attachment is by others. Field drilling of the			
	channel for a bolted attachment will be required. The horizontal deflection limit of this spandrel channel is held to L/240 unless noted otherwise			*
	mint of this spandrer channel is held to L/240 unless hoted other wise			
	Anatos Dalla		7.050.00	Ainu
05015	Anchor Bolts	\$	7,650.00	Ajax
	Vinyl Bead Ceiling in Rms 125, 124A, 124, 123, 122, 130, 129, 127 -			
05250	ALLOWANCE is Included - No Specifications	\$	-	MEC Enterprises
05300	Metal Fabrication - Railings at Steps	\$	5,900.00	Hawkins
05300	Metal Fabrication - (18) Pipe Bollards - Included	\$		Hawkins
05300	Metal Fabrication - Bollard Covers	\$	3,200.00	Ideal Shield
	Structural Steel Subtotal	2	361,431.00	



MARION COUNTY FIRE STATION #11 - 24Q-055

Schedule of Values June 11, 2025

	June 11, 2025				
#	CARPENTRY & MILLWORK		VALUES	NOTES	
06000	Wood Framing Labor - Included	\$		MEC Enterprises	
06010	Wood Framing Material - Included	\$	-	MEC Enterprises	
06010	Wood Framing Material - Miscellaneous Rough Carpentry	\$		Manning Lumber	
06010	Wood Framing Material - Window Bucks - Furnish and Install	\$	1,800.00	TBD	
06200	Trusses	\$	52,378.81	Manning Truss	
06200	Trusses - QUALIFICATION - Per Manning Truss Additional Bearing Walls Will be Required - We Have EXCLUDED Additional Bearing Walls	\$	2	Manning Truss	
06200	Trusses - Truss Labor and Lumber Material	\$	109,153.00	MEC Enterprises	
06200	Trusses - Hardware	\$	5,000.00	Manning Lumber	
06350	Cabinets / Millwork	\$	43,672.59	Rainbow Cabinets	
06350	Cabinets / Millwork - 116 & 117 RR's Elevation 2/A702 - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - Elevation 2 & 4/A703 - Included	\$	· · · · ·	Rainbow Cabinets	
06350	Cabinets / Millwork - 115 ADA RR Elevation 3/A702 - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - Elevation 13/A703 - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - Elevations 3, 1 & 2/A701 - Included	\$	A X	Rainbow Cabinets	
06350	Cabinets / Millwork - Elevations 6 & 7/A701 - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - Elevations 4 & 5/A701 - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - QUALFICIATIONS:	\$	-	Rainbow Cabinets	
06350	Cabinets / Millwork - Plastic Laminate Architectural - Included	\$	-	Rainbow Cabinets	
06350	Cabinets / Millwork - Casework Level: Custom - Included	\$	-	Rainbow Cabinets	
06350	Cabinets / Millwork - Casework Construction: Frameless - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - Semi-Exposed Surfaces: White Liner - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - 3/4" Plywood Cabinets w/ 3/4" Plywood MDF -	\$		Rainbow Cabinets	
00000	Included Cabinets / Millwork - Door Type & Style: Slab, Flush Øverlay - Included	\$		Rainbow Cabinets	
06350			-	Rainbow Cabinets	
06350 06350	Cabinets / Millwork - Recessed KV #255 Standards - Included Cabinets / Millwork - KV #256 Metal Shelf Pins - Included	\$ \$		Rainbow Cabinets	
6350	3Cabinets / Millwork - /4" Plywood Shelves - Included	9 \$	S - 2	Rainbow Cabinets	
6350	Cabinets / Millwork - 4" Wire Pulls, Brushed Chrome Finish - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - 4 Wile Pulls, Brushed Chrome Pinish - Included Cabinets / Millwork - Blum 107 degree Self closing Hinges - Included	\$		Rainbow Cabinets	
06350	Cabinets / Millwork - KV TruTrak Drawer Guides - TT100 100lb - Included	\$	_	Rainbow Cabinets	
06350	Cabinets / Millwork - Full Extension Ball Bearing Slides - Included	\$	<i>2</i>	Rainbow Cabinets	
06350	Cabinets / Millwork - Rubber Stops - Included	\$	2	Rainbow Cabinets	
06350	Cabinets / Millwork - Standard matter finishes from Wilsonart & Formica are included for plastic laminate cabinetry Included	\$	-	Rainbow Cabinets	
06350	Cabinets / Millwork - Semi-exposed surfaces priced for white liner laminate.	\$	-	Rainbow Cabinets	
06350	- Included	\$	2	Excluded	
06350	AWI certification & labels - EXCLUDED FSC certification & labels - EXCLUDED	э \$		Excluded	
06350	NAUF materials - EXCLUDED	\$	2	Excluded	
06350	Cabinets / Millwork - ALLOWANCES:	\$	-	Rainbow Cabinets	
	Cabinets / Millwork - Cabinets in Classroom 131 - No Elevations Provided -	s	3,077.63	Rainbow Cabinets	
06350	Wall and Base Cabinets Cabinets / Millwork - Radio Charging Station Rm C600 - Laminate Top on				
06350	Wall Brackets Cabinets / Millwork - Radio Charging Staton in Corr C300 - Laminate Top	\$		Rainbow Cabinets	
06350	on Wall Brackets	\$	891,75	Rainbow Cabinets	
06350	Cabinets / Milwork - Lockers in Rm 110 - Plastic Laminate Lockers per Sections C/A701	\$	22,620.00	Rainbow Cabinets	
06350	Cabinets / Millwork - Stainless Steel Top - Details Unclear - Additional Allowance included to Extend Stainless Steel - Details to be Determined	\$	799.31	Rainbow Cabinets	
00050	during Submittal Review	•	500.00	Painbow Cabinata	
6350	Cabinets / Millwork - Modifications for Farmhouse Sink	\$		Rainbow Cabinets	
6350	Cabinets / Millwork - Steel Ledgers at Countertops	\$		Rainbow Cabinets	
6350	Cabinets / Millwork - Benches in Locker Room - No Details/Specifications	\$	6,000.73	Dinkins	
6350	Cabinets / Millwork - GMP REVIEW 5-15-25 - Add Solid Surface Countertps - Corian grades 1-2 & Wilsonart grades 1-4 are included for solid surface countertop alternates	\$	24,124.01	Rainbow Cabinets	
06450	Wood Trim Labor and Material - EXCLUDED - Geneal Note 6 on A201N is	\$	24	Evoluted	
06450	EXCLUDED	φ		Excluded	
06461	FRP Paneling - Mop Sink	\$	1,762.50	Dinkins	
06467	Window Sills - QUALIFICATION - Designer White Solid Surface Sills with	\$	4 560 00	Docs Restorations	
59401	Ear and Skirt In-Lieu of Wood Sills and Skirts Carpentry & Millwork Subtotal			2000 1100101010	
	Carpenta y a minwolk Subtola	ą	200,451.00		





MARION COUNTY FIRE STATION #11 - 24Q-055

#	ROOFING & WATERPROOFING	VALUES	NOTES
07000	Roofing Subcontract - QUALIFICATION - Alternate Panels - Berridge Double Z Lock and Mid State Quick-Stick High Temp 60 Mil Underlayment	\$ 117,000.00	Ocala Roofing
07000	Roofing Subcontract - Gutters Downspouts Soffits and Fascia - GMP REVIEW 5-15-25	\$ 16,895.00	Ocala Roofing
07000	Roofing Subcontract - ALLOWANCE - Exterior Ceilings - 50 SF Allowance	\$ 35,000.00	Dinkins
07000	Roofing Subcontract - Performance and Payment Bond	\$ 2,500.00	Ocala Roofing
07100	Insulation - Batt Insulation and Rigid Insulation in Drywall Partitions - Included	\$ -	MEC Enterprises
07100	Insulation - SCOPE REVIEW - Spray Insulation at Roof Deck - HEATLOK CLOSED CELL	\$ 51,104.68	American Residential Products
07100	Insulation - SCOPE REVIEW - Ignition Barrier - Fire shell F10E Ignition Barrier	\$ 12,965.40	American Residential Products
07100	Insulation - SCOPE REVIEW - Masonry Core Fill - CFI Core Fill	\$ 5,905.90	American Residential Products
07110	Firestopping	\$ 1,500.00	
07300	Waterproofing - Liquid Flashing at Openings	\$ 5,295.00	Lundman Group
07300	Waterproofing - SCOPE REVIEW - Wood Bucks at Windows - Liquid Flashing at Openings	\$ 3,600.00	Lundman Group
07300	Water Repellant Coating Interior/Exterior Slabs is EXCLUDED	\$ 1. A.	Excluded
07300	Waterproofing/Damproofing at Stucco or Brick Veneer is EXCLUDED	\$ 2.00	Excluded
07400	Silicone & Caulking Sidewalks, Concrete Apron, Hollow Metal Frames, Bollards, Brick and Masonry Control Joints	\$ 12,872.00	Lundman Group
07400	Silicone & Caulking - Exterior Slabs to Building	\$ 1,619.50	Lundman Group
07400	Silicone & Caulking - Concrete Apron Control Joints	\$ 10,342.50	Lundman Group
07400	Silicone & Caulking - Caulking Louvers	\$ 1,000.00	Lundman Group
07400	Silicone & Caulking - Miscellaneous Caulking	\$ 2,500.00	Lundman Group
07400	Silicone & Caulking - G-Seal is EXCLUDED	\$ 122	Excluded
	Roofing & Waterproofing Subtotal	\$ 280,099.98	



MARION COUNTY FIRE STATION #11 - 24Q-055

<u>Schedule of Values</u> June 11, 2025

# DOORS & Muscows Posice values			June 11, 2025			
00000 Doors ALHADKARY Package 110,145.05 Steve Hering 0000 Wood Dors - CALRFACTON - Wood Doors in App Big to HM. 5 Stocker Hering 0000 Mood Dors - CALRFACTON - Wood Doors in App Big to HM. 5 100.000 0000 Mood Doors - CALRFACTON - Wood Doors in App Big to HM. 5 100.000 00000 Mood Doors - CALRFACTON - Wood Doors in App Big to HM. 5 1.00.000 Steve Hering 00000 Mood Doors - ALFACTON - Wood Doors in App Big to HM. 5 1.00.000 Steve Hering 00000 Mood Doors - ALFACTON - Wood Doors in Like of 5 1.00.000 Steve Hering 00000 Mood Doors - ALFACTON - Mood Doors in Like of 5 1.00.000 Steve Hering 00000 Mood Doors - ALFACTON - Mood Doors - Mood Doors in Like of 5 42.30.000 Steve Hering 00000 Boors ALFACTON - Mood Doors - ALFACTON - Mood Door Herick of Steve Hering 5		#	DOORS & WINDOWS		VALUES	NOTES
09000 with Shuchard Composite Cores 5 - Solve heiming 09000 Add HM Window, Add Lean Glaring, Add Cores and Keying, Increase 5 1,005.70 09000 Wood Cores SCOPE REVEW - HM Frame for Pocket Doors In-Linu of Wood Cores 5 1,000.00 09000 Mood HM Add Flaw Merkers S 1,000.00 Steve Heining 09000 Doors & Landware per knase - Included S 1,000.00 Steve Heining 09000 Doors & Landware per knase - Included S 1,000.00 Steve Heining 09000 Doors & Landware per knase - Included S 42 Colling and Boin 09000 Doors & Landware per knase - Included S 42 Colling and Boin 09000 Instal associated hardware per knase - Included S 42 Colling and Boin 09000 Enternint Windows - 2010 Series Monized S 42 Colling and Boin 09000 Enternint Windows - 2010 Series Monized S 42 Colling and Boin 09000 Enternint Windows - 2010 Series Monized S 42 Colling and Boin 09000 Enternint Windows - 2010 Series Monized S 59/were Class 09000			Doors & Hardware Package	\$		
Gage to 14 Gar Frames and 16 ga boxs, Change at HM Don'ts 0 Steel Indust. J Steel Henry 00000 Wood Don's SCOPE REVIEW - HM Frame for Packet Don's In-Lieu of 1.000.00 Silver Henry 00000 Moder Medal - Bit Coating on HM Frames 1.000.00 Silver Henry 00000 Don's A Hardware Packases - Included 5 1.807.00 Silver Henry 00000 Trait All SC Kindo and HM Gori Raves - Included 5 1.807.00 Silver Henry 00000 Install associate Instalware per Hier dawing and schedule - Included 5 1.807.00 Silver Hand Son 00110 Silver Honore - Coll (Frames - Review - Included 5 1.807.00 Silver Hand Son 00110 Silver Honore - Coll (Frames - Review - Included 5 1.807.00 Silver Hand Son 00110 Silver Honore - Coll (Frames - Review - Included 5 1.807.00 Silver Hand Son 00110 Silver Honore - Silver Hand Son 5 1.807.00 Silver Hand Son 00110 Silver Hand Son 5 1.807.00 Silver Hand Son 00110 Silver Hand Son 5 1.000.00 Skyview Class 00110 Silver Hand Son 5 1.000.00 Skyview Class 00110 Silver Hand Son 5 1.000.00 Skyview Class <		08000	with Structural Composite Cores	\$	-	Steve Hering
Wood 00000 S 1,00000 Silver Handi 1,00000 Silver Handi 0,0000 00000 Door & Hardware Packase - Installation 0,0000 Silver Handi 0,0000 Silver Handi 0,0000 Silver Handi 0,0000 00000 Exist 40 SC wood and HM door Nawse - Included 0,0000 Silver Handi 0,0000 Silver Handi 0,0000 Silver Handi 0,0000 Silver Handi 0,0000 00000 Exist 40 SC wood and HM door Nawse - Included 0,0000 Silver Handi 0,0000 Silver Handi 0,00000 Silver Handi 0,00000		08000	Gage to 14 Ga Frames and 16 ga Doors. Change all HM Doors to Steel	\$	19,093.70	Steve Hering
00000 Hollow Metal - Bit Coaling on HM Frames \$ 1,000.00 Steve Heining 00000 Doors & Hardware Package - Installation 00000 S		08000		\$	1,000.00	Steve Hering
98000 Install ad SC wood and HM dorc kaves - Included \$ 16,7500 Stater and Sorie 98000 Install associated indrware per M downing and Schedule - Included \$ 1,2300 Stater and Sorie 98110 Storefront //Windows - Kawneer's IRS01 inpact rated storefront system, open for 1-5/16" glazing, for openings W4 \$ 1,2300.00 Styview Class 98110 Storefront //Windows - Stype and down with 10" bottom raits to meet W1660, W2(exclass) \$ 1,2300.00 Styview Class 98110 Storefront //Windows - Stype and Baled Shop Drawings and Calculator \$ 1,8200.00 Styview Class 98110 Storefront //Windows - Stype and Baled Shop Drawings and Calculator \$ 1,8200.00 Styview Class 98110 SCOPE REVEW - Increase Storefront Entrances and Strekgther to be 0" \$ 10000 Styview Class 98110 SCOPE REVEW - Increase Storefront Entrances and Strekgther to be 0" \$ 10000 Styview Class 98110 SCOPE REVEW - Increase Storefront Entrance and Strekgther \$ 10000 Styview Class 98110 SCOPE REVEW - Increase Storefront Entrance and Strekgther \$ 10000 Styview Class 98110 SCOPE REVEW - Increase Storefront Entrance and Strekgther \$ 10000 Styview Class 98110 Storefort // Moder Strekgther \$ 100000 Styview Class 98110 Storefort // Moder Strekgther \$ 100000 <td></td> <td>08000</td> <td></td> <td>\$</td> <td>1,600.00</td> <td>Steve Hering</td>		08000		\$	1,600.00	Steve Hering
00000 Install a SC unced and HM door haves - Included \$ 16.7500 BS Carler and Sories 00000 Install associated indrwings and aschedule - Included \$ 14.2300.00 Skyview Class 00110 Storefront / Windows - Kawneer's IRS01 impact rated storefront system, open for 1-5/16" glazing, for openings W4 \$ 14.2300.00 Skyview Class 00110 Storefront / Windows - And R force Anodzed \$ 16.500 Skyview Class 00110 Storefront / Windows - Skyview Class \$ 16.2000 Skyview Class 00110 Storefront / Windows - Skyview Class \$ 16.2000 Skyview Class 00110 Storefront / Windows - Skyview Class \$ 10.2000 Skyview Class 00110 Storefront / Windows - Skyview Class \$ 10.2000 Skyview Class 00110 SCOPE REVEW - Increase Storefront Entrance and Strategins to be 6' \$ 800,000 Skyview Class 00110 Storefront Entrance - 0.004.IFCATON - 14-advard ger Subcortrador \$ 10.2000 Skyview Class 00110 Storefront Entrance - 0.004.IFCATON - 14-advard ger Subcortrador \$ 10.7000 Skyview Class 00110 Storefront Entrance - 0.004.IFCATON - 14-advard ger Subcortrador \$ 10.7000 Skyview Class 00110 Storefront Mindows - Change Top Strateger Subcortrador \$ 10.7000 Skyview Class 00110 Storefront Min		08000	Doors & Hardware Package - Installation	\$	-	JS Carter and Sons
98110 Storefont / Windows - Kawneer's IRS01 impact rated storefont system, open for 1-S16" glazing, for openings W4 \$ 142,340.00 Skyview Glass Storefont / Windows - 2(3) wide site doors with 10" bottom rais to meet addition of the store wide site of 10 for openings marked Storefont / Windows - Store Store widdows (14) for openings marked Storefont / Windows - Store Store widdows (14) for openings marked Storefont / Windows - Store Store widdows (14) for openings marked Storefont / Windows - Store Store widdows (14) for openings marked Storefont / Windows - Store Store widdows (14) for openings marked Storefont / Windows - Store Store Widdows to Staling Egress - Drawing and Calculation - Store Store Widdows (14) for openings widdows (14) f		08000	Install 40 SC wood and HM door leaves - Included	\$		JS Carter and Sons
00110 open for 1-5/16" glazing, for openings W4 Starterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the doors with 10" bottom rais to meet ADA requirements Storterior IV Modows - 20 well as the door and door and the door and th		08000	Install associated hardware per the drawings and schedule - Included	\$	~	JS Carter and Sons
00110 ADA requirements 5 - Bryteev Class 00110 Storeton / Windows - 3410 Series windows (x16) for openings marked S - Skyteev Class 00110 Storeton / Windows - Stynes Windows to Shiding Egress - Drawings and Calculation - S Skyteev Class 00110 Storeton / Windows - Signed and Sealed Ship Drawings and Calculation - S Skyteev Class 00110 Storeton / Windows - Signed and Sealed Ship Drawings and Calculation - S Skyteev Class 00110 Storeton / Windows - Signed and Sealed Ship Drawing and Calculation - S Skyteev Class 00110 Storeton / Windows - Class Storeton Entrances and Skelepits to be 8' Storeton / Windows 00110 Storeton / Windows - Class Storeton Storeton Editor to be store to Market Storeton / Windows 00110 Storeton / Windows - Class Storeton Storeton Editor to Market Storeton / Windows 00110 Storeton / Windows - Class Storeton Storeton Editor to Market Storeton / Windows 00110 Storeton / Windows - Class Storeton Storeton Storeton Storeton Storeton / Windows Storeton / Windows 00110 Storeton / Windows - Class Storeton / Storeton / Windows Storeton / Windows Storeton / Windows 00110 Storeton / Windows - Classtoreton / Storeton / Windows Storeton / Windows <td></td> <td>08110</td> <td></td> <td>\$</td> <td>142,340.00</td> <td>Skyview Glass</td>		08110		\$	142,340.00	Skyview Glass
08110 Storeford / Windows - Jark Brozze Andolzad \$ Styreter (Windows - Jark Brozze Andolzad) 08110 Storeford / Windows - Jark Brozze Mindows (K) (Store priming market and Calculation - Styreter (Blazze Windows - Signed and Sealed Shop Drawings and Calculation - Storeford / Windows - Signed and Sealed Shop Drawings and Calculation - Storeford / Windows - Signed and Sealed Shop Drawings and Calculation - Storeford / Windows - Signed and Sealed Shop Drawings and Calculation - Storeford / Windows - Signed and Sealed Shop Drawings and Calculation - Storeford Fueld Store - Data (Blazze - Data) (Blaze - Storeford / Windows - Signed Storeford Fueld Store - Data) 08110 SCOPE REVIEW - Revise Windows to Silding Egress - Drawing Revision - Storeford Fueld Store - QUALFICATION - Hardware per Subcontrator 110.00 Styriew Glass 08110 Munited Coser, Electric esti dive pub hass - Juni Hardiss, Weather - Storeford Fueld Cover and Threshold Turum Turn on entencor, Keyed Calculated - Cyclinder on extension Fueld Cover and Threshold Turum - Curn on extension - Locked Calculated - Cyclinder on extension - Locked - Storeford -		08110		\$	-	Skyview Glass
98110 Storefront / Windows - 3410 Series windows (x18) for openings marked Winks, Wickexluded, Wicking, and Wicking, Wickexluded, Micking, and Calculation - Storefront / Windows - Signed and Sealed Shop Drawings and Calculation - Storefront / Windows - Signed and Sealed Shop Drawings and Calculation - Store PREVIEW - Increase Storefront Calcular (use Flores to Micking) Storefront / Signed in 34-25 00110 SCOPE REVIEW - Change Storefront Calcular (use Flores to Micking) Storefront / Signed in 34-25 Storefront Calcular (use Flores to Micking) 00110 SCOPE REVIEW - Change Storefront Calcular (use Flores to Micking) Storefront / Signed in 34-25 Storefront Calcular (use Flores to Micking) 00110 SCOPE REVIEW - Change Storefront Calcular (use Flores to Micking) Storefront / Windows Storefront / Signed Flores 00110 Micking Construction of Interpolatin Turnin turn on interpolatin Turnin turn on interpolatin Turnin turn on interpolatin Turnin turnin on interpolatin Turnin Store and Power supply Flored 4. Storefront / Windows 00110 Store 2 HS _1/4 ar _1/4 CaleATIN - 1-5/16 Overal 'K Poeral with Store and Storefront Calcular (use S		08110		\$		
00110 Startinol. Vivilex, Molexa, J. Walkey, Windows Start, and Saled Shep Drawings and Caleditation - \$ Skyview Glass 00110 SCOPE REVIEW, A Revise Windows to Silding Egress - Drawing Revision \$ (18.400.00) 00111 SCOPE REVIEW, Revise Windows to Silding Egress - Drawing Revision \$ (18.400.00) 00110 Scope Review, Change Storefron Glazing to Markonze to Mathin \$ 100.00 Skyview Glass 00110 Scope Review, Central Scorefron Glazing to Markonze to Mathin \$ 110.00 Skyview Glass 00110 Woundow Storefron Enrirance - OUALFICATION - Hardwarper Subcondroir \$ Skyview Glass 00110 Woundow Storefron Enrirance - OUALFICATION - Hardwarper Subcondroir \$ Skyview Glass 00110 Storefron Enrirance - OUALFICATION - Hardwarper Subcondroir \$ Skyview Glass 00110 Storefron Enrirance - OUALFICATION - Hordwarper Subcondroir \$ Skyview Glass 00110 Storefron Enrirance - OUALFICATION - Hordwarp Subcondroir \$ Skyview Glass 00110 Storefron Vice Enrirance - Storefron Enrirance - Storefron Enrirance - Storefron Glasing - Type G4 - OUALFICATION - Hordwarp Storefron Class \$ Skyview Glass 00110 Storefron Vice Enri			Storefront / Windows - 3410 Series windows (x18) for openings marked			
08110 SCOPE REVIEW - Revise Windows to Siking Egress - Drawing Revision (18.420 00), Skyview Glass 08110 SCOPE REVIEW - Change Storefront Entrances and Sidelights to be 0° \$ 900,00 Skyview Glass 08110 SCOPE REVIEW - Change Storefront Glazing to be Bronze to Match \$ 110.00 Skyview Glass 08110 Scope Review - CALLERCTATON - Hardwarmer Stucconstructor \$ 100.00 Skyview Glass 08110 Mounted Coster, Electric ceal divide pub hars, Pub Handias, Suffapo \$ Skyview Glass 08110 Mounted Coster, Electric ceal divide pub hars, Pub Handias, Suffapo \$ Skyview Glass 08110 Storeform Coster Figure 10 power transform Approxements Pub Handias, Suffapo \$ Skyview Glass 08110 Storeform 10 power transform Approxements Pub Handias, Suffapo \$ Skyview Glass 08110 Storeform 10 power transform Approxements Pub Handias, Suffapo \$ Skyview Glass 08110 Storeform 10 (Staring Tower Suffapo Handias, Yake Marker Start, Start Start Start, Start			W1(x6), W2(excluded), W3(x10), and W5(x2) Storefront / Windows - Signed and Sealed Shop Drawings and Calculation			
00110 issued by Rippol on 3-8-25 in Reduction Skytview Glass 00110 Issued by Rippol on 3-8-25 in Reduction Skytview Glass 00110 SCOPE REVIEW - Increase Storefront Glazing to be Bronze to Malch in Roduction Skytview Glass 00110 Monther Charge Storefront Glazing to be Bronze to Malch in Roduction Skytview Glass 00110 Mounted Charge, Electric exit device push bars, Pull hangles, Surfach in Roduction Skytview Glass 00110 Mounted Charge, EPTID power Transfor, and power surph - Included is Skytview Glass 00110 Storefort, EPTID power Transfor, and power surph - Included is Skytview Glass 00110 Storefort, EPTID power Transfor, and power surph - Included is Skytview Glass 00110 Storefort, Prog C4 - OULLIFICATION - 1-5716" overall: X" char with SB70 is Skytview Glass 00110 Glazing - Type G3 - OULFICATION - 1-5716" overall: X" char with SB70 is Skytview Glass 00110 Glazing - Type G3 - OULFICATION - 1-5716" overall: X" char with SB70 is Skytview Glass 00110 Glazing - Type G3 - OULFICATION - 1-5716" overall: X" char with SB70 is Skytview Glass 00110 Glazing - Type G3 - OULFICATION - 1-5716" overall: X" char with SB70 is Skytview Glass 00110 Glazing - Type G4 - OU		08110	EXCLUDED			Skyview Glass
08110 SCOPE REVIEW - Increase Storefront Entrances and Stickpits to be 9 5 000.00 Skyview Class 08110 SCOPE REVIEW - Change Storefront Entrance - QUALIFICATION - Hardware per Subcontractor Proposal - Specified Hardware is not PPA - But Hinges, Surfager 1 1 100.00 Skyview Class 08110 Mounted Closer, Electric ext device puts bars, Pult handles, Weather Stropping, Door Sweep, and Threshold Thuma, Tum origineior, Keyed Skyview Class 08110 S370 2F 1K, J.Y'air J.Y'air GA - QUALIFICATION - 1:7/16" overall X' branze with Included S Skyview Class 08110 S370 2F 1K, J.Y'air J.Y'		08110		\$	(18,809.00)	Skyview Glass
Windows StoreFront Entrance QUALIFICATION Hardware per Subcontractor Proposal Specified Hardware is not FPA Sutt Hanges, Sufface S Skyview Class 08110 Mounde Closer, Electric wil device public har, Publi handles, Weather S Skyview Class 08110 Mounde Closer, Electric wil device public, and power supply - Included Claing - Type Cd - QUALIFICATION - 1-7/16" overall: ½" bronze with SB70 at 2H S_1%" at 1%" clear HS_180 CLEAR SGP_1%" clear HS S Skyview Class 08110 SB70 at 2H S_1%" at 1%" clear HS_180 CLEAR SGP_1%" clear HS S Skyview Class 08110 Glazing Types G1 and G2 - Included S Skyview Class 08110 Glazing Types G1 and G2 - Included S Skyview Class 08110 Glazing Types G1 and G2 - Included S Skyview Class 08110 Glazing Types G1 and G2 - Included S Skyview Class 08110 Glazing Types G1 and G2 - Included S Skyview Class 08100 Quarter Door S 1075.007 Florida Door Solutions 08600 Glazing Streption 11 Windows - GMP REVIEW 515 42 - Revise to (3) Egress S 105.207		08110	SCOPE REVIEW - Increase Storefront Entrances and Sidelights to be 8'	\$	800,00	Skyview Glass
Storefront Entrance - QUALIFICATION - Hardware per Subcontractor08110Mounted Closer, Electric exit device push bars, Pult handles, Weather\$ <td></td> <td>08110</td> <td>° °</td> <td>\$</td> <td>110.00</td> <td>Skyview Glass</td>		08110	° °	\$	110.00	Skyview Glass
Cvincer on exterior, EPT10 power transfer, and power supply. Included Glazing - Type G5 - QUALE[CATION - 1/516 roward! X* clear with SB70 08110 82170, 27, 36°, air _ X* clear HS _ 180 CLEAR SGP _ X* clear With SB70 S Skyview Glass 08110 #2 HS _ 3/6° air _ X* clear HS _ 180 CLEAR SGP _ X* clear With SB70 S Skyview Glass 08110 Glazing Type G5 - noluded \$ S. Skyview Glass 08110 Glazing Type G1 and G2 - included \$ S. Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08110 Glazing Type G3 - noluded \$ 1,076.00 Skyview Glass 08600 Glazing Type G3 - noludea \$ 1,076.00 Skyview Glass 08600		08110	Storefront Entrance - QUALIFICATION - Hardware per Subcontractor Proposal - Specified Hardware is not FPA - Butt Hinges, Surface Mounted Closer, Electric exit device push bars, Pull handles, Weather	\$		Skyview Glass
Glazing - Type G5 - QUAL PICATION - 15/16" overall: X° clear With SB7008110#21 Sig 3/8" airX° clear HS_180 CLEAR SGP_X* clear HS_ Included\$-Skyview Glass08110Glazing Types G1 and G2 - Included\$1.076.00Skyview Glass08110Glazing Types G1 and G2 - Included\$1.076.00Skyview Glass08110Performance and Payment Bond\$3.765.51Skyview Glass08000Storefort / Windows - GMP REVIEW 5-15-25 - Revise to (3) Egress\$105,397.00Florida Door Solutions08600Garage Door\$105,397.00Florida Door SolutionsFlorida Door Solutions08600Garage Door\$105,397.00Florida Door Solutions08600Guap index 14 ⁴ ligh\$-Florida Door Solutions08600Clopay model 3718/3717 In-Lieu of Specified\$-Florida Door Solutions08600Takenor Slandard colors: While, Bronze, Gray, tan, Chocolate , Moch, or Charcoal.Florida Door Solutions-08600Thetior is While, steel backer.\$-Florida Door Solutions08600Thetior is While, steel backer.\$-Florida Door Solutions08600Wind Lead is W6 +36 psf with X' Impact, Lexan glazing in section #4 (24' x' indow size).Florida Door Solutions08600Thetior is Matons Interior to be Surface mounted NEMA 1 a buton station x' wind bacer Solutions-Florida Door Solutions08600'Courte stations Interior to be Surface mounted NEMA 1 a buton station x' Windo Boor Solutions<		08110	Cylinder on exterior, EPT10 power transfer, and power supply - Included Glazing - Type G4 - QUALIFICATION - 1-7/16" overall: ¼" bronze with SB70 #2 HS _ ½" air _ ¼" clear HS180 CLEAR SGP _ ¼" clear HS -	\$		Skyview Glass
08110Glazing Types G1 and G2 - Included\$-Skyview Glass08110Glazing - Borrowed Lite Glazing - 3/8" Tempered\$1,076.00Skyview Glass081010Performance and Payment Bond\$3,765.51Skyview Glass08600Garage Door\$(861.00)Skyview Glass08600GUALIFICATION - Clopay Model 3718/3717 In-Lieu of Specified\$-Florida Door Solutions08600Glopay model 3718/3717 In-Lieu of Specified\$-Florida Door Solutions08600(8) each 1/4 wide x 144 high\$-Florida Door Solutions08600(8) each 1/4 wide x 144 high\$-Florida Door Solutions08600'Exterior Standard colors: White, Bronze, Gray, tan, Chocolate , Mocha, or Charcoal.\$-Florida Door Solutions08600'Tracks to be 30" high filt with follow the 3:12 pitch.\$-Florida Door Solutions08600'Tracks to be 30" high filt with follow the 3:12 pitch.\$-Florida Door Solutions08600'Tracks to be 30" high filt with follow the 3:12 pitch.\$-Florida Door Solutions08600'Tracks to be 30" high filt with follow the 3:12 pitch.\$-Florida Door Solutions08600'Tracks to be 30" high filt with follow the 3:12 pitch.\$-Florida Door Solutions08600'Tracks to be 30" high filt with follow the 3:12 pitch.\$-Florida Door Solutions08600'Control stations: Interior to be Surface mounted NEMA 1 abuton station\$ <td< td=""><td></td><td>08110</td><td>Glazing - Type G5 - QUALIFICATION - 1-5/16" overall: 1" clear with SB70 #2 HS _ 3/8" air _ 1/4" clear HS180 CLEAR SGP _ 1/4" clear HS -</td><td>\$</td><td>-</td><td>Skyview Glass</td></td<>		08110	Glazing - Type G5 - QUALIFICATION - 1-5/16" overall: 1 " clear with SB70 #2 HS _ 3/8" air _ 1/4" clear HS180 CLEAR SGP _ 1/4" clear HS -	\$	-	Skyview Glass
08110Glazing - Borrowed Lite Glazing - 3/8" Tempered\$1,076.00Skyview Glass08110Performance and Payment Bond\$3,765.51Skyview Glass08100Storefront / Windows - GMP REVIEW 5-15-25 - Revise to (3) Egress\$(861.00)Skyview Glass08600Garage Door\$105,397.00Florida Door Solutions08600Guach 14 wide x 14 high\$>Florida Door Solutions08600Clopay model 3718/3717 Flush or Grooved Panel Design\$-Florida Door Solutions08600Clopay model 3718/3717 Flush or Grooved Panel Design\$-Florida Door Solutions08600Charcoal.Stell of wide x 14 high\$-Florida Door Solutions08600Clopay model 3718/3717 Flush or Grooved Panel Design\$-Florida Door Solutions08600Therior is White, steel backer.\$-Florida Door Solutions08600Therior is White, steel backer.\$-Florida Door Solutions08600Tuberior is White, steel backer.\$-Florida Door Solutions08600Stach X/H motor operators, single phase\$-Florida Door Solutions08600Overhead Door/ Lift master motors\$-Florida Door Solutions08600Verhead Door/ Lift master motors\$-Florida Door Solutions08600Verhead Door / Lift master motors\$-Florida Door Solutions08600Verhead Door / Lift master motors-Florida Door Solutions		08110		\$	2	Skyview Glass
Storefront / Windows - GMP REVIEW 5-15-25 - Revise to (3) Egress Windows \$ (861.00) Skyview Glass 08600 Garage Door 08600 Gull,EFICATION - Clopay-Model 3718/3717 In-Lieu of Specified 08600 \$ 105,397.00 Florida Door Solutions - Florida Door Solutions - Florida Door Solutions 08600 Clopay model 3718/3717 Flush or Grooved Panel Design 08600 \$ - Florida Door Solutions - Florida Door Solutions 08600 Clopay model 3718/3717 Flush or Grooved Panel Design 08600 \$ - Florida Door Solutions 08600 Therior is While, steel backer. \$ - Florida Door Solutions 08600 "Interior is While, steel backer. \$ - Florida Door Solutions 08600 "Interior is While, steel backer. \$ - Florida Door Solutions 08600 "Wind load is VK6 +36 psf with ½" Impact, Lexan glazing in section #4 (24" x 13" window size). \$ - Florida Door Solutions 08600 Overh ead Door/ Lift master motors \$ - Florida Door Solutions 08600 "Verhice Bentrament devices. Wired sensing edge and Nema 4X photo eyes, \$ - Florida Door Solutions 08600 "Verhice Bentrament devices. Wired sensing edge and Nema 4X photo eyes, \$ - Florida Door Solutions 08600 "Verhice Detector Loop Trequires site coordination* \$ - Florida Door Solutions </td <td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td>						-
WindowsClaft JulyStylew Glass08600Garage Door\$105,397.00Florida Door Solutions08600QUALIFICATION - Clopay-Model 3718/3717 In-Lieu of Specified\$-Florida Door Solutions08600(8) each 14' wide x 14' high\$-Florida Door Solutions-08600(8) each 14' wide x 14' high\$-Florida Door Solutions-08600(9) each 14' wide x 14' high\$-Florida Door Solutions-08600(16) each 14' wide x 14' high\$-Florida Door Solutions-08600Therior is White, steel backer.\$-Florida Door Solutions-08600Therior is White, steel backer.\$-Florida Door Solutions-08600Therior is Woh 30' bigh lift with follow the 3:12 pitch.\$-Florida Door Solutions08600(8) each ½ hp motor operators, single phase\$-Florida Door Solutions08600(8) each ½ hp motor operators, single phase\$-Florida Door Solutions08600'Dual monitored entrapment devices: Wired sensing edge and Nema 4X-Florida Door Solutions08600'Cohrol stations: Interior to be Surface mounted NEMA 1 3 button station-Florida Door Solutions08600'Vehicle Detector Loop "requires site coordination"\$-Florida Door Solutions08600'(16) 4. channel remotes with built in receivers\$-Florida Door Solutions08600'(16) 4. channel remotes with bui		08110		\$	3,765.51	Skyview Glass
08600QUAL/FICATION - Clopay Model 3718/3717 In-Lieu of Specified5Florida Door Solutions08600(8) each 14' wide x 14' high5Florida Door Solutions08600Clopay model 3718/3717 Flush or Grooved Panel Design5Florida Door Solutions08600Charcoal.5Florida Door Solutions08600Tracks to be 30' high lift with follow the 3:12 pitch.5Florida Door Solutions08600Tracks to be 30' high lift with follow the 3:12 pitch.5Florida Door Solutions08600Tracks to be 30' high lift with follow the 3:12 pitch.5Florida Door Solutions08600Wina load is W6 +36 psf with ½' Impact, Lexan glazing in section #4 (24' x 10'' window size).Florida Door Solutions08600(8) each ½ hp motor operators, single phase5Florida Door Solutions08600Control stations: Interior to be Surface mounted NEMA 1 3 button stationFlorida Door Solutions08600'Control stations: Interior to be Surface mounted NEMA 1 3 button stationFlorida Door Solutions08600'Control stations: Interior to be Surface mounted NEMA 1 3 button stationFlorida Door Solutions08600'Yehicle Detector Loop 'requires site coordination'Florida Door Solutions08600'Yehicle Detector Loop 'requires site coordination'S08600'Yehicle Detector Loop 'requires site coordination'S08600'Yehicle Detector Loop 'requires site coordination'S08600'Yehicle Detector Loop 'requires site coordination'S08600Yehicle Detector Loop 'require				\$	(861.00)	Skyview Glass
08600(B) each 14' wide x 14' high\$Florida Door Solutions08600Clopay model 3718/ 3717 Flush or Grooved Panel Design\$Florida Door Solutions08600Charcoal.\$Florida Door Solutions08600"hterior is White, steel backer.\$Florida Door Solutions08600"Interior is White, steel backer.\$Florida Door Solutions08600"Tracks to ba 30" high filt with follow the 3:12 pitch.\$Florida Door Solutions08600"Tracks to ba 30" high filt with follow the 3:12 pitch.\$Florida Door Solutions08600"Wind load is W6 +36 psf with ½" Impact, Lexan glazing in section #4 (24" x 12" window size).\$Florida Door Solutions08600(B) each ½ hp motor operators, single phase 00 currhead Door/ Lift master motors\$Florida Door Solutions08600"Our all monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$Florida Door Solutions08600"Control stations: Interior to be Surface mounted NEMA 1 3 button station 08600\$Florida Door Solutions08600"Vehicle Detector Loop" requires site coordination* 08600\$Florida Door Solutions08600"Vehicle Detector Loop" requires site coordination* Williams SW# color\$Florida Door Solutions08600Vehicle Detector Loop Solutions\$Florida Door Solutions08600"Vehicle Detector Loop" requires site coordination* Williams SW# color\$Florida Door Solutions08600*Vehicle Detector Loop Solutions\$Florida Door Sol		08600	Garage Door	\$	105,397.00	Florida Door Solutions
08600Clopay model 3718/ 3717 Flush or Grooved Panel Design "Exterior Standard colors: White, Bronze, Gray, tan, Chocolate, Mocha, or Charcoal.SFlorida Door Solutions08600"Exterior Standard colors: White, Bronze, Gray, tan, Chocolate, Mocha, or Charcoal.SFlorida Door Solutions08600"Interior is White, steel backer.SFlorida Door Solutions08600"Tracks to be 30" high lift with follow the 3:12 pitch.SFlorida Door Solutions08600"Tracks to be 30" high lift with follow the 3:12 pitch.SFlorida Door Solutions08600(8) each ½ hp motor operators, single phaseSFlorida Door Solutions08600(8) each ½ hp motor operators, single phaseSFlorida Door Solutions08600"Duer Image Tragment devices: Wired sensing edge and Nema 4X photo eyes,Florida Door Solutions08600"Control stations: Interior to be Surface mounted NEMA 1 3 button station 08600Florida Door Solutions08600"Vehicle Detector Loop "requires site coordination"Florida Door Solutions08600"Vehicle Detector Loop "requires site coordination"Florida Door Solutions08600"(16) 4 - channel remotes with built in receiversSFlorida Door Solutions08600Williams SW# colorSIforida Door Solutions08600Performance and Payment BondS1,962.4408600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDEDSEXCLUDED08600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDEDSPGoida Door Solutions08600					1.75	
08600"Exterior Standard colors: White, Bronze, Gray, tan, Chocolate , Mocha, or Charcoal.SFlorida Door Solutions08600"Interior is White, steel backer.SFlorida Door Solutions08600"Tracks to be 30" high lift with follow the 3:12 pitch.Florida Door Solutions08600"Wind load is W6 +36 psf with ½" Impact, Lexan glazing in section #4 (24" x 12" window size).Florida Door Solutions08600(8) each ½ hp motor operators, single phase Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,Florida Door Solutions08600"Control stations: Interior to be Surface mounted NEMA 1 3 button station 08600Florida Door Solutions08600"Control stations: Interior to be Surface mounted NEMA 1 3 button station 08600Florida Door Solutions08600"Control stations: Interior to be Surface mounted NEMA 1 3 button station 08600Florida Door Solutions08600"Control stations: Interior to be Red/ Green LED light Traffic Signals 08600Florida Door Solutions08600"(16) 4- channel remotes with built in receivers Williams SW# colorZ5,432.0008600Performance and Payment Bond1,962.4408600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDEDSEXCLUDED08600SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure\$ 9,600.00					7.	
Charcogi.Charcogi.Florida Door Solutions08600'Interfor is White, steel backer.\$Florida Door Solutions08600'Tracks to be 30° high lift with follow the 3:12 pitch.\$Florida Door Solutions08600'Wind load is W6 +36 psf with ¼' Impact, Lexan glazing in section #4 (24"\$Florida Door Solutions08600(8) each ½ hp motor operators, single phase\$Florida Door Solutions08600Overhead Door/ Lift master motors\$Florida Door Solutions08600'Dual monitored entrapment devices: Wired sensing edge and Nema 4X\$Florida Door Solutions08600'Control stations: Interior to be Surface mounted NEMA 1 3 button station\$Florida Door Solutions08600'Control stations: Interior to be Surface mounted NEMA 1 3 button station\$Florida Door Solutions08600'Vehicle Detector Loop 'requires site coordination*\$Florida Door Solutions08600''(4) exiting doors to get Red/ Green LED light Traffic SignalsFlorida Door Solutions08600''(4) exiting doors to get Red/ Green LED light Traffic SignalsFlorida Door Solutions08600''(4) exiting doors to get Red/ Green LED light Traffic Signals25,432.0008600Performance and Payment Bond\$1,962.4408600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED\$EXCLUDED08600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED\$9,600.0008600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED\$9,600.00			*Exterior Standard colors: White, Bronze, Gray, tan, Chocolate , Mocha, or			
08600'Tracks to be 30' high lift with follow the 3:12 pitch.\$-Florida Door Solutions08600'Wind load is W6 +36 psf with ¼' Impact, Lexan glazing in section #4 (24" x 12" window size).\$-Florida Door Solutions08600(8) each ½ hp motor operators, single phase 0 verhead Door/ Lift master motors *Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$-Florida Door Solutions08600''ourehead Door/ Lift master motors *Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$-Florida Door Solutions08600''Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$-Florida Door Solutions08600''Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$-Florida Door Solutions08600''Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$-Florida Door Solutions08600''Control Stations: Interior to be Surface mounted NEMA 1 3 button station 08600\$-Florida Door Solutions08600''(4) exiting doors to get Red/ Green LED light Traffic Signals 08600\$-Florida Door Solutions08600''(16) 4 - channel remotes with built in receivers 08600\$25,432.00Florida Door Solutions08600VolLUNTARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color\$25,432.00Florida Door Solutions08600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED\$\$EXCLUDED <td></td> <td></td> <td></td> <td>*</td> <td>-</td> <td></td>				*	-	
virtual bolicitations x 12" window size). s - Florida Door Solutions 08600 (8) each ½ hp motor operators, single phase s - Florida Door Solutions 08600 Overhead Door/ Lift master motors s - Florida Door Solutions 08600 Overhead Door/ Lift master motors s - Florida Door Solutions 08600 "Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes, s - Florida Door Solutions 08600 "Control stations: Interior to be Surface mounted NEMA 1 3 button station s - Florida Door Solutions 08600 "Control stations: Interior to be Surface mounted NEMA 1 3 button station s - Florida Door Solutions 08600 "Control stations: Interior to be Surface mounted NEMA 1 3 button station s - Florida Door Solutions 08600 "Vehicle Detector Loop "requires site coordination" s - Florida Door Solutions 08600 *(16) 4- channel remotes with built in receivers s - Florida Door Solutions 08600 *(16) 4- channel remotes with built in receivers s 25,432.00 Florida Door Solutions 08600			*Tracks to be 30" high lift with follow the 3:12 pitch.	₽ \$	-	
08600 08600(8) each ½ hp motor operators, single phase\$-Florida Door Solutions08600Overhead Door/ Lift master motors\$-Florida Door Solutions08600"Dual monitored entrapment devices: Wired sensing edge and Nema 4X photo eyes,\$-Florida Door Solutions08600"Control stations: Interior to be Surface mounted NEMA 1 3 button station Exterior to be Flush mounted NEMA 4 key switch\$-Florida Door Solutions08600"Vehicle Detector Loop *requires site coordination*\$-Florida Door Solutions08600"Vehicle Detector Loop *requires site coordination*\$-Florida Door Solutions08600"Vehicle Detector Loop *requires site coordination*\$-Florida Door Solutions08600"(16) 4- channel remotes with built in receivers\$-Florida Door Solutions08600VOLUNTARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color25,432.00Florida Door Solutions08600Performance and Payment Bond\$1,962.44Florida Door Solutions08600Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED\$EXCLUDED08600SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure\$9,600.00TBD		08600		\$	÷	Florida Door Solutions
08600 VOLUNI ARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated \$ 9,600.00 08600 TBD		08600		\$	÷	
08600 VOLUNI ARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated \$ 9,600.00 08600 TBD		08600		\$	(e)	Florida Door Solutions
08600 VOLUNI ARY ALTERNATE - Add Clopay's Colorbiast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure \$ 9,600.00		08600		\$	· *	Florida Door Solutions
08600 VOLUNI ARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure \$ 9,600.00		08600		\$	200	Florida Door Solutions
08600 VOLUNI ARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated \$ 9,600.00 08600 TBD					(*)	
08600 VOLUNI ARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure \$ 9,600.00					-	
08600 VOLUNIARY ALTERNATE - Add Clopay's Colorblast (any Sherwin Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ - EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure \$ 9,600.00					1948 1927	
Williams SW# color \$ 25,432.00 Florida Door Solutions 08600 Performance and Payment Bond \$ 1,962.44 Florida Door Solutions 08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ - EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated Installed in PEMB Structure \$ 9,600.00						
08600 Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED \$ - EXCLUDED 08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated \$ 9,600.00 08600 Installed in PEMB Structure \$ 9,600.00			Williams SW# color	·		
08600 SCOPE REVIEW - ALLOWANCE - Spring Pads - (24) 10"x12" Plated \$ 9,600.00 TBD Installed in PEMB Structure		08600	Performance and Payment Bond	\$	1,962.44	Florida Door Solutions
Installed in PEMB Structure \$ 9,600.00 TBD	•	08600	Hurricane Shutters - GMP REVIEW 5-15-25 - EXCLUDED	\$	(5)	EXCLUDED
		08600		\$	9,600.00	TBD
				\$	425,527.15	



MARION COUNTY FIRE STATION #11 - 24Q-055

Schedule of Values June 11, 2025

		June 11, 2025				
	#	INTERIOR / EXTERIOR FINISH ASSEMBLIES & FLOORING		VALUES	NOTES	
	09000	Stucco - EXCLUDED - See Alternates	\$. ALOLO	Excluded	
	09150 09150	Drywall Subcontract Drywall Subcontract - SCOPE REVIEW - Texture Drywall - EXCLUDED	\$ \$		MEC Enterprises EXCLUDED	
	09150	Drywall Subcontract - GMP REVIEW 5-15-25 - Texture Drywall - EXCLUDED	\$		EXCLUDED	
		Drywall Subcontract - SCOPE REVIEW - Fire Wall between Apparatus Bay and Living Quarters	\$	3,225.00	MEC Enterprises	
	09150	Drywall Subcontract - ALLOWANCE - Draft stopping - Plans Do Not Indicate Draft stopping	\$	3,000.00	MEC Enterprises	
	09150	Drywall Subcontract - Performance and Payment Bond	\$	4,706.84	MEC Enterprises	
	09200	Acoustical Ceiling - QUALIFICATION - 2X2X3/4" Armstrong School Zone Fine Fissure #1717 Tegular Edge Tile In-Lieu of Specified - Tile #1810 is EXCLUDED - Fire Guard Tiles are EXCLUDED	\$	41,997.00	L&D Ceilings	
	09200	Acoustical Ceiling - 15/16" Intermediate Duty Grid Typical and 15/16" Light Duty Aluminum Grid in Locker Room Only - Included	\$		L&D Ceilings	
	09200	Acoustical Ceilings - QUALIFICATION - Reflected Ceiling Plan Does Not Match Finish Schedule - Proposal Assumes We are to Follow the Reflected Ceiling Plan - Included	\$	÷	L&D Ceilings	
	09300	Painting Painting - Gyp Board and Block Walls & Ceilings using 1 Coat o <u>f P</u> rimer	\$	94,673.00	Lester Painting	
	09300	and 2 Coats of Acrylic Latex Finish (Pre Catalyzed Epoxy Where Required). Interior Wood Window & Door Casing using a Coat of Primer and 2 Coats of Semigloss Enamel Finish. Interior HM Window and Door Frames Caulked as Required a Coat of Primer and 2 Coats of Semigloss Enamel Finish. Sealed Concrete Prepared by Sweep/Vacuum Surface. Sealed Concrete Floors using Basic Sweep/Vacuum Prep, Application of Euclid Euco Diamond Hard Liquid Densifier/Sealer (No Concrete Sealer Specification Provided).	\$		Lester Painting	
,	09300	Painting Apply a Coat of Rust Inhibitive Primer and 2 Coats of Water based Alkyd Semigloss to Exposed Primary and Secondary Structural Steel in the Apparatus Bay and Fire Riser Room. ***Painting to be Completed Prior to Installation of Insulation, Roof Dack and Walls. Painting - Exterior HM Doors/Frames Caulked as Required a Coat of	\$	2	Lester Painting	
C	09300	Primer and 2 Coats of Semigloss Enamel Finish. Bollards using a Coat of Primer and 2 Coats of Semigloss Enamel Finish. Dumpster Enclosure CMU Walls using a Coat of Block Filler and 2 Coats of Exterior Acrylic Satin Finish.	\$	2	Lester Painting	
(09300	Painting - SCOPE REVIEW - Deduct Painting Wood Trim - Wood Trim is	\$	(5.843.00)	Lester Painting	
	09300	EXCLUDED Painting - Performance and Payment Bond	\$		Lester Painting	
	09300			2,040.13		
		Painting - GMP REVIEW 5-15-25 - Painting Dumpster Enclosure - Included			Lester Painting	
c	09500	Flooring Floor Tile - Furnish & Install Dal-Tile 12"x24" Linden Point #LP21 Grigio Floor Tile installed in a Straight Pattern with Bostik TrueColor Rapid Cure (Color TBD) Urethane Grout and Schluter Dilex-AHK Aluminum Satin	\$	-	Great Lakes	
٥	09500		\$	6,485.00	Great Lakes	
	9500	tile/lvt transitions to all restroom areas as specified per Room Finishes/Flooring Layout Plan Sheet A201D, A201N & A601 dated 12/11/2024. Price does not include waterproofing. Floor Tile - Furnish & Install Mapei Mapegard 2SM Crack Isolation Membrane to all restroom floor tile areas as specified per Room Finishes/Flooring Layout Plan Sheet A201D, A201N &	\$	852.00	Great Lakes	
		A601 dated 12/11/2024. Floor Tile - Furnish & Install a 3" Mud Bed to all recessed shower areas only prior to floor tile installation as specified				
0	19200	per Room Finishes/Flooring Layout Plan Sheet A101, A102, A201D, A201N & A601 dated 12/11/2024.	\$	1,815.00	Great Lakes	
a	9500	Wall Tile - Furnish & Install Dal-Tile 2"x2"(12"x24" Mounted) Linden Point Mosaic #LP21 Grigio Wall Tile installed in a Straight Pattern to all bathroom walls at 4' 4" AFF with Bostik TrueColor Rapid Cure (Color TBD) Urethane Grout and Schluter Rondec Aluminum Satin Bullnose Trim at all finished edges and Schluter Dilex-AHK Aluminum Satin Cove Base at all wall tile inside corners per Room Finishes/Flooring Layout Plan Sheet A201D, A201N A601, A702, A703 & A704 dated 12/11/2024.	\$	33,338.00	Great Lakes	



MARION COUNTY FIRE STATION #11 - 24Q-055

	MARION COUNTEFIRE STATIO		r I I * Z	40-033	
	Schedule of Values				
	June 11, 2025				
	Wall Tile - Showers - Furnish & Install Dal-Tile 2"x2"(12"x24" Mounted)				
	Linden Point Mosaic #LP21 Grigio Floor Tile installed				
	in a Straight Pattern to all shower floors(excluding 151 molded shower) with				
09500	Bostik TrueColor	\$	-	Great Lakes	
	Rapid Cure (Color TBD) Urethane Grout per Room Finishes/Flooring				
	Layout Plan Sheet A201D, A201N				
	A601, A702, A703 & A704 dated 12/11/2024, - Included				
	Wall Tile - Showers - Furnish & Install Mapei Aqua Defense Waterproofing				
	Membrane with Mapei Aqua Defense 6" Reinforcing				
09500	Fabric as necessary to all shower floors and walls only as specified per	\$	3,792.00	Great Lakes	
	Room Finishes/Flooring Layout Plan				
	Sheet A201D, A201N & A601 dated 12/11/2024.				
	Wall Tile - QUALIFICATION - Proposal Includes Wall Tile on All Walls in				
09500	Restrooms. Finish Schedule and Elevations are Unclear which Walls are to			Great Lakes	
	Receive Tile				
09500	Wall Tile - Crack Isolation Membrane and Waterproofing of Wall Tile is		•	Evoluded	
09200	EXCLUDED			Excluded	
					,
	LVT - Furnish & Install Shaw 6"x48" In The Grain #7004 Cotton Seed				
	Luxury Vinyl Plank to all areas as	4			
09500	specified per Room Finishes/Flooring Layout Plan Sheet A201D, A201N &	\$	29,165.00	Great Lakes	
	A601 dated 12/11/2024. Price				
	includes all transitions and normal floor prep as necessary.				
	Sport Flooring - Furnish & Install Amorim 3/8" Cork Composites Sport				
	Flooring #427 Blue Rolled Recycled Rubber				
09500	Flooring to 111 Fitness Room area only as specified per Room	S	2 409 00	Croat Lakas	
09200	Finishes/Flooring Layout Plan Sheet A201D,	\$	3,408.00	Great Lakes	
	A201N & A601 dated 12/11/2024. Price includes normal floor prep and all				
	transitions as necessary.				
09500				*	
	Vinyl Base - Furnish & Install 4" Mannington 1/8" Gauge Black Brown Vinyl				
09500	Cove Base to all areas as specified per	\$	3 430 00	Great Lakes	
03300	Room Finishes/Flooring Layout Plan Sheet A201D, A201N & A601 dated		0,400.00	Cicul Lakes	
	12/11/2024.				
09500	Waxing / Sealing Flooring is EXCLUDED	\$	<u> </u>	Excluded	
09500	SCOPE REVIEW - Moisture Testing	\$	1,500.00	Great Lakes	
09500	ALLOWANCE - Floor Prep	\$	2,500.00	Great Lakes	
00500	Flooring - VOLUNTARY ALTERNATE - Armor Tuff Flooring in Rm 125	\$	51 210 00	Armor Tuff	
09500	and 126	Φ	51,519.00	Armor Tuff	
09500	Grind or Etch floor if needed to ensure tile adhesion	\$	-	Armor Tuff	
09500	Level & Patch apparatus bay floor if necessary to eliminate any puddles	\$	-	Armor Tuff	
	Supply & Install 7 MM Armor Tuff Tiles in BLACK throughout apparatus			Armen T. W	
09500	bays	\$	-	Armor Tuff	
09500	Supply & Install 2-part adhesive in bays	\$	-	Armor Tuff	
09500	Supply & Install edging for bay doors	\$		Armor Tuff	
09500	Supply & Install edging in for walk through doors	\$		Armor Tuff	
09500	Supply & Install two back up line stripe in red in each bay	s	2	Armor Tuff	
09500	Fire Company Logo - (1) 38"x38" Logo - Included	S		Armor Tuff	
09500	Artwork Fee	\$		Armor Tuff	
09500	Work at Trench Drain	э S		Armor Tuff	
09300	Deduct Concrete Sealer at App Bay	Ф \$		Lester Painting	
09300				Lester Painting	
and the second s	Interior / Exterior Finish Assemblies & Flooring Subtotal	\$	417,604.03		



MARION COUNTY FIRE STATION #11 - 24Q-055

	5 dile 11, 2025				
#	ACCESSORIES		VALUES	NOTES	6
10000	Building Accessories Baby Box Material - Upfront Costs are Included - Annual Fees and Lease				
10000	Agreement are EXCLUDED	\$	16,239.00	Safe Haven	
10000	Baby Box Labor	\$	2,773.50	Dinkins	
10000	Baby Box Trim Material	\$	1,762.50		
10050	Knox Box	\$	1,292.50	Dinkins	
10100	Bath Accessories				
10100	Washroom Accessories - Furnish and Install	\$	6,252.20	United Sales	
10100	2 - 36" SS grab bars - Included	\$	-	United Sales	
10100	2 - 42" SS grab bars - Included	\$	-	United Sales	
10100	7 - 24X36 channel framed mirrors - Included	\$	Ξ.	United Sales	
10100	2 - sanitary napkin disposals - Included	\$	12	United Sales	
10100	7 - surface mount waste receptacles - Included	\$	A (* 1	United Sales	
10100	1 - shower rod with curtain - Included	\$	-	United Sales	
10100	Shower Accessories - Furnish and Install	\$	1,303.98	United Sales	
10100	4 - recessed soap dishes - Included	\$		United Sales	
10100 10100	12 - clothes/towel hooks - Included	\$	a (United Sales	
10100	All Other Accessories are EXCLUDED	\$	-	Excluded	
10200	Fire Extinguishers - (7) 10# Extinguisers	\$		American Fire	
10200	Fire Extinguishers - GMP REVIEW 5-15-25	\$	1,496,50	American Fire	
10300	Signs & Plaques - ALLOWANCE - Building Letters - "Fire Station 11" Signs	2	24,000.00	Allowance	
	(3) Locations	•			
10300	Signs & Plaques - ALLOWANCE - 911 Address	\$		Allowance	
10300	Signs & Plaques - ALLOWANCE - Maltese Cross	\$	-	Allowance	
10300 10300	Signs & Plaques - ALLOWANCE - Room Signage - (38) Room Signs	\$		Allowance	
10300	Signs & Plaques - ALLOWANCE - Life Safety Signage Signs & Plaques - ALLOWANCE - Bronze Plaque	\$ \$		Allowance Allowance	
	Lockers - Plastic Laminate Lockers in Rm. 110 Locker Room - See Cabinets and Millwork Lockers - Gear/Equipment Lockers - ALLOWANCE - (12) Salsbury Industries 24" Wide Vented Gear Metal Locker - 6 Feet High - 24 Inches Deep - Gray - Model: 72024GY-A Color: Gray	\$ \$	- 13,500.00	Excluded Dinkins	
	Accessories Subtotal	\$	79,120.18		
	LOW VOLTAGE SYSTEMS		VALUES	NOTES	
	Phone System - EXCLUDED	\$	-	Excluded	
	Security System - Video Access Control - EXCLUDED Computer Cabling - EXCLUDED	\$	-	Excluded Excluded	
11000	Low Voltage Systems Subtotal	\$		Excided	
	FURNITURE, FIXTURES, EQUIPMENT		VALUES	NOTES	
	Furnishings - EXCLUDED	\$	-	Excluded	
12100	Appliances - Refrigerators, Dishwasher, Ice Machine, Extractor, Etc. is EXCLUDED	\$		Excluded	
	Window Treatments - ALLOWANCE - Graber Solar Shades Standard Weave 5% and Blackout Roller Shades at Bunk Rooms	\$	8,544.10	Blinds-N-More	
	Accessories - EXCLUDED	\$	ý.	Excluded	
12600	Decorating - EXCLUDED	\$	-	Excluded	
	<u>Shelving</u>	\$	3,293,80	United Sales	
12000	Provide and install wire shelving in the three (3) pantry closets, each closet will have five (5) shelves each - Included	\$	-	United Sales	
		\$	-	United Sales	
	SCOPE REVIEW - (1) Row of helving in C500A	\$		United Sales	
12800	will have five (5) shelves each - Included Provide and install adjustable wire shelving in the two (2) DECON rooms, ea <mark>ch c</mark> loset will have five (5) shelves each - Included	\$	-	United Sales	



MARION COUNTY FIRE STATION #11 - 24Q-055

# MECHANICAL SYSTEMS 15100 Plumbing Subcontract 15100 Fixtures - Included	\$	VALUES	NOTES
15100 Fixtures - Included	\$	122 722 00	
	1 A A A A A A A A A A A A A A A A A A A	122,132.00	Southern Plumbing
	\$		Southern Plumbing
15100 Domestic water to be CPVC - Included	\$	5 2	Southern Plumbing
15100 Sanitary to be PVC - Included	\$	H	Southern Plumbing
15100 Hot water piping to be insulated - Included	\$		Southern Plumbing
15100 GI-1 - Included	\$ \$		Southern Plumbing
15100 Showers and Fiberglass Shower Enclosure with Accessories - Included			Southern Plumbing
15100 Gas piping - Included	\$		Southern Plumbing
15100 Condensate Piping - Included	\$	-	Southern Plumbing
15100 QUALIFICATION -Specification for Fixture S-1 is Unclear - ALLOWANG Farmhouse Sink Allowance	\$	250.00	Southern Plumbing
	\$	(250.00)	Southern Plumbing
15100 GMP REVIEW 5-15-25 - Delete Farmhouse Sink 15100 SCOPE REVIEW - Add Gas Water Heater GWH-1	э \$		Southern Plumbing
QUALIFICATION - Lint Interceptor is Specified on the Plumbing Sheets		8,770.00	Jourient Fullbing
15100 and the Civil Sheets - Proposal Includes Lint Interceptor per the Civil	\$		Excluded
Drawings	÷		Excidence
15100 Water Softener System - EXCLUDED	\$		Excluded
15100 Performance and Payment Bond	\$	3.287.55	Southern Plumbing
			, and a
15100 Solar Water Heater	\$	21,960.00	Solar Trek
15100 Provide site specific engineering Included	\$	-	Solar Trek
15100 Provide all solar materials as described by engineering - Included	\$	-	Solar Trek
Install all solar materials to include the solar tank, collectors, pump static	on,		
15100 plumbing to and from the collectors to the storage tank and all necessar	ry \$		Solar Trek
components as described by engineering - Included			
15100 Heat recovery at HVAC Equipment - EXCLUDED	\$	-	Solar Trek
15100 ALLOWANCE - Taxes	\$	1,537.20	Solar Trek
15300 HVAC System	\$	715,307.00	CCS Mechanical
HVAC Equipment — All equipment is Basis of Design, or an approved	\$	23	CCS Mechanical
alternate identified in the specifications - included			
15300 (3) DX Fan Coil Units - Included	\$	Z	CCS Mechanical
15300 (3) Air Cooled Heat Pumps - Included	\$	-	CCS Mechanical
15300 (1) Ductless Colling Only Split System DX - Included	\$		CCS Mechanical CCS Mechanical
15300 (3) Dehumidifiers - Included	\$ \$		CCS Mechanical
15300 (4) Infrared Unit Heaters - Included 15300 (1) Electric Unit Heater - Included	\$	1	CCS Mechanical
15300 (3) Ion Generators/Bi-Polar Ionization - Included	\$		CCS Mechanical
15300 (4) Gas Detection Systems - Included	Ψ S		CCS Mechanical
15300 Sheet Metal Ductwork with Insulation - Included	\$		CCS Mechanical
15300 HVAC Refrigerant Piping with Insulation - Included	\$		CCS Mechanical
15300 HVAC Condensate Piping with Insulation - Included	\$		CCS Mechanical
15300 Exhaust Fans - Included	\$		CCS Mechanical
15300 (3) HVLS Fans - Included	\$	(-	CCS Mechanical
15300 Gravity Intakes - Included	\$	1	CCS Mechanical
15300 Kitchen Hood With Fire Suppression System - Included	\$		CCS Mechanical
15300 Air Distribution and Dampers - Included	\$	244	CCS Mechanical
15300 Fire Safe for Our Work Only - Included	\$	12.	CCS Mechanical
15300 Smoke Detectors — Install Only - Included	\$	(a)	CCS Mechanical
15300 Louvers as Shown on Mechanical Plans - Included	\$	-	CCS Mechanical
15300 HVAC Building Control System — by Computrols - Included	\$	-	CCS Mechanical
15300 Test And Balance of HVAC System - Included	\$		CCS Mechanical
15300 HVAC Commissioning Assistance Only - Included	\$	(7 .)	CCS Mechanical
15300 Hoisting and Rigging - Included	\$:**	CCS Mechanical
15300 Daily Clean-Up + Included	\$	075	CCS Mechanical
15300 Submittals - Included	\$	5. 0 .)	CCS Mechanical
15300 Coordination Drawings for Our Work Only - Included	\$		CCS Mechanical
15300 Sales Tax - Included	\$	19 4 6	CCS Mechanical
15300 Dupont Flex wrap per M201 General Note 2 is EXCLUDED	\$	+	Excluded
15300 Ice Machine Condensing Unit is EXCLUDED	\$	144	Excluded
15300 Apparatus Bay Diesel Exhaust Ventilation System is EXCLUDED	\$		
15300 Delete EF-2 and SF-1 and Associated Ductwork	\$		CCS Mechanical
	\$		Excluded
15300 Duct Pressurization Testing is EXCLUDED	~		
15300 Duct Pressurization Testing is EXCLUDED 15300 Range Hood - ALLOWANCE - Install and Inspections	\$	2,500.00	IDD
15300 Duct Pressurization Testing is EXCLUDED	\$ \$	6,500.00	160



MARION COUNTY FIRE STATION #11 - 24Q-055

Schedule of Values June 11, 2025

15400	Fire Protection System	\$	72 325 00	Cox Fire Protection
15400	Provide and install a complete fire suppression system as indicated: One		12,020.00	
15400	(1) wet pipe sprinkler system shall be installed in the building, - Included	\$	-	Cox Fire Protection
15400	Design shall be prepared and provided in 2D CAD documents, - Included	\$	2	Cox Fire Protection
15400	QUALIFICATION - Per Subcontractor Designing to the Flows Specified on Sheet F201 cannot be achieved without adding a fire pump. System is designed per flow testing on sheet F010. If future municipal water provides flows specified on Sheet F201 a fire pump will be required in the future.			Cox Fire Protection
15400	Electronic sets of Cox Fire's drawings in accordance w/ 61G documents, hydraulic calculations, and product data shall be prepared by Cox Fire Protection and submitted to the buyer for approval - Included	\$	7.	Cox Fire Protection
15400	All threaded piping shall be schedule 40 black pipe and joined by threaded fittings. All grooved piping shall be schedule 10 black pipe and joined by grooved mechanical fittings. Welded outlets shall be used to join branch piping to the cross main piping - Included	\$		Cox Fire Protection
15400	All area's except as listed below – Provide a .10 GPM/Sqft for the most remote 1500 Sqft with a hose allowance of 100 GPM for the protection of light hazard occupancy. Head spacing shall not exceed 225 Sqft - Included	\$		Cox Fire Protection
15400	Mechanical, storage and janitors' rooms - Provide a .20 GPM/Sqft for the most remote 1500 Sqft with a hose allowance of 250 GPM for the protection of ordinary hazard occupancy. Head spacing shall not exceed 130 Sqft - Included	\$	-	Cox Fire Protection
15400	Finished ceiling areas - 1/2" pendent heads with a recessed escutcheon - Included	\$	-	Cox Fire Protection
15400	Covered entry - 1/2" dry pendent heads w/ recessed escutcheon - included	\$		Cox Fire Protection
15400	Exposed structure areas - 1/2" brass upright heads - Included	\$		Cox Fire Protection
15400	Sprinkler Room Valves - Shotgun type riser check valve - Included	\$	-	Cox Fire Protection
15400	Riser Control Valve - Butterfly valve with internal supervisory switch - Included	\$	¥.	Cox Fire Protection
15400	Drain Valves - Brass globe valves - Included Water Flor Alarm Device - One vane type shall be provided and installed at	\$) ►	Cox Fire Protection
15400	each riser. One (1) electric bell shall be provided and installed on the exterior wall at the riser location - Included	\$	ý A	Cox Fire Protection
15400	Attic protection is included within this proposal - Included			Cox Fire Protection
15400	Voluntary Alternate - Flexible Drops	\$	650.00	Cox Fire Protection
15400	Performance and Payment Bond	\$	1,765.00	Cox Fire Protection
15400	QUALIFICATION - No standpipes required per plans and specifications	\$	43	Cox Fire Protection
15400	CPVC and galvanized piping is not included within this proposal - EXCLUDED	\$	2	Excluded
15400	General note on sheet F201 stating size piping for an assumed flow of 50 psi static and 40 psi residual at 750 gpm, with consideration of this water supply the system will not be adequate within an ordinary hazard group two occupancy. System per this specified water supply is EXCLUDED	\$	ŝ	Excluded
15400	Fire Pump - EXCLUDED	\$	26	Excluded
	Mechanical Systems Subtotal	\$ 9		
			,	

 $\langle \rangle$



MARION COUNTY FIRE STATION #11 - 24Q-055

S

Schedule of Values June 11, 2025

	June 11, 2025				
#	ELECTRICAL SYSTEMS	VALUE	S	NOTES	
16100	Electrical Subcontract		2.00 Ciraco		
16100	Switchgear included.	\$	- Ciraco		
16100	Natural Gas Generator included.	\$	- Ciraco	1	
16100	Lighting included.	\$	- Ciraco		
16100	Site lighting included.	\$	- Ciraco		
16100	Site lighting - ALLOWANCE - Flag Pole Light	\$ 80	0,00 Ciraco		
16100	Wiring of devices included.	\$	- Ciraco		
16100	Stop and Go lights in apparatus bay included.	\$	- Ciraco		
16100	Phone/Data/TV/Access Control conduit stubs included.	\$	- Ciraco		
16100	Control conduit and wire for apparatus bay doors included.	\$	- Ciraco	r	
16100	Fire Alarm - SCOPE REVIEW - Deduct Fire Alarm	\$ (12,00 \$	0.00) Ciraco		
16100	Lightning protection included. Primary and Communication conduits included - QUALIFICATION -	Ф.	- Ciraco		
16100	Conduits as shown on Electrical Site Plan not Civil Utility Plan. Electrical	\$	- Ciraco		
10100	Site Plan and Civil Utility Plan Conflict	•	S Ollaco		
16100	Permit included.	\$	- Ciraco		
16600	Lightning Protection - Included Above	\$	- Ciraco		
16600	SCOPE REVIEW - Deduct Electrical for EF-2 and SF-1	\$ (2.50	0.00) Ciraco		
16600	SCOPE REVIEW - Add Circuits for Well and Lift Station		9.00 Ciraco		
16600	Performance and Payment Bond	\$ 15,11	2.28 Ciraco		
				N	
16110	Security System	C 40.20		Custome	
16110	Access Control Access Control There are 8 doors that are being controlled using the	\$ 40,39	2.00 Mid State F	re a Systems	
16110	Vanderbilt control system per Marion County specifications.	\$	 Mid State F 	ire & Systems	
16110	Aphone Doorbell System	\$ 3,68	9.00 Mid State F	ire & Systems	
	Access Control - SCOPE REVIEW - Material and Labor for Wiring Door				
16110	Hardware	\$ 8,00	0.00 TBD		
16120	Fire Alarm System	\$ 25,884	4.00 Mid State F	ire & Systems	
16120	Fire Alarm price is based on an addressable fire alarm system	\$	 Mid State F 	ire & Systems	
	manufactured by Honeywell Silent Knight. Fire Alarm price includes Engineer stamped fire alarm shop drawings,				
16120	submittals, closeouts and owner training.	\$	 Mid State F 	ire & Systems	
16120	Fire Alarm Dialer - EXCLUDED	\$	- Excluded		
16120	Fire Alarm Dialer - GMP REVIEW 5-15-25 - Cellular Dialer	\$ 1,472	2.00 Mid State F	ire & Systems	
16120	BDA Testing	\$ 2,50	0.00 Mid State F	ire & Systems	
16120	BDA System	\$ 28,000	0.00 Mid State F	ire & Systems	
16130	Audio Visual Lighting Systems - EXCLUDED	\$	- Excluded		
16140	Voice / Data	\$ 29,084	4.00 Mid State F	ire & Systems	
10140	Voice/Data/TV/WAP: Included is a wall rack, patch panels, wire				
16140	management, patch cords, UPS, testing with meter, cat 6A wiring per the	\$	 Mid State F 	ire & Systems	
	Marion County specifications.				
16140	Performance and Payment Bond		4.00 Mid State F	ire & Systems	
	Electrical Systems Subtota	ai \$ /45,62	0.28		
1	GENERAL CONDITIONS SUBTOTA	L \$ 410,919	9.21		
	SITE DEVELOPMENT SUBTOTA	L \$ 1,538,97	2.14		
			4.40		
	BUILDING SUBTOTA	L \$ 4,396,574	4.40		
#	MARION COUNTY	VALUE	s	NOTES	
	General Conditions & Site Development & Building Subtotal	\$ 6,346,46			
00099	CM Fee = 6%	\$ 380,78			
01200	Bonding	\$ 79,330			
01125	General Liability Insurance	\$ 126,929			
01016	Marion County Contingency	\$	- Excluded		
01015	CM Contingency	\$	 Excluded 		
01015	Deventione	\$	-		
01015	Rounding PROPOSED GMI				



MARION COUNTY FIRE STATION #11 - 24Q-055

Schedule of Values

	June 11, 2025				
#	ALTERNATES		VALUES	NOTES	
00001	Thin Brick Wainscotting with Stucco Above	\$		Exterior Finish Plastering	
00002	No Thin Brick. Stucco All Walls	\$	(128,191.42)	Exterior Finish Plastering	
00002	Increase Spray Insulation at Roof Deck to R38	\$	11,248.26	American Residential Products	
00003 00003	Delete Hurricane Shutters - Window Openings are Impact Rated Custom Colors on Bay Doors Facing Road Only	\$ \$	(12,716.00)	Florida Door Solutions Florida Door Solutions	
00004	Remove and Replace Unsuitable Soils - Unit Cost	\$	32.00	Marion Rock	
	Filter on Irrigation Well	\$	500.00	Tricounty Landscape	
	Skyliner Insulation In-Lieu of Metal Liner Panels				
	Deduct Metal Liner Panels - Material	\$	(15,636.00)		
	Deduct Metal Liner Panels - Labor	\$	(21,868.00)		
	Add Skyliner - Material Add Skyliner - Labor	\$	9,000.00		
	Net Savings	\$	7,000.0	<u>u</u>	
		Ψ	(21,304.00)		
	Alternate Flooring:				
	Furnish & Install Trinity 12"x12" Vidal (Color: TBD) Floor Tile installed in a				
	Straight Pattern with Bostik	14			
	TrueColor Rapid Cure (Color TBD) Urethane Grout and Schluter Dilex-AH Aluminum Satin Cove Base at	ĸ			
	all floor tile/wall tile transitions and Schluter Reno-U Aluminum Satin	\$	8,035.00	Great Lakes	
	Reducer at all floor tile/lvt transitions to all restroom areas as specified per Room Finishes/Flooring				
	Layout Plan Sheet A201D, A201N				
	& A601 dated 12/11/2024. Price does not include waterproofing Graniti Fiandre TLC New Stone Has Been Discontinued	¢		Great Lakes	
	Furnish & Install Trinity 6"x6" Nexus White Gloss Wall Tile installed in a	\$		Gleat Lakes	
	Straight Pattern to all bathroom				
	walls at 4' 4" AFF with Bostik TrueColor Rapid Cure (Color TBD) Urethane				
	Grout and Schluter Rondec	\$	28,794.00	Great Lakes	
	Aluminum Satin Bullnose Trim at all finished edges and Schluter Dilex-AH Aluminum Satin Cove Base	ĸ			
	at all wall tile inside corners per Room Finishes/Flooring Layout Plan				
	Furnish & Install Trinity 6"x6" Nexus White Gloss Wall Tile installed in a				
	Straight Pattern to all shower walls(excluding 151 molded shower) at 8' AFF with Bostik TrueColor Rapi	4			
	Cure (Color TBD) Urethane	\$	-	Great Lakes	
	Grout and Schluter Rondec Aluminum Satin Bullnose Trim at all finished				
	Furnish & Install Dal-Tile 2"x2"(12"x24" Mounted) Linden Point Mosaic #LP21 Grigio Floor Tile installed				
	in a Straight Pattern to all shower floors(excluding 151 molded shower) will	h \$	÷	Great Lakes	
	Bostik TrueColor				
	Rapid Cure (Color TBD) Urethane Grout Furnish & Install Mapei Mapegard 2SM Crack Isolation Membrane to all				
	restroom floor tile	\$	852.00	Great Lakes	
	Furnish & Install Shaw 6"x48" 20 mil Terrain II Sumac Luxury Vinyl Plank	\$	29,165.00	Great Lakes	
	Furnish & Install a 3" Mud Bed to all recessed shower areas	\$	1,815.00	Great Lakes	
	Furnish & Install Amorim 3/8" Cork Composites Sport Flooring #427 Blue	¢	2 408 00	Great Lakes	
	Rolled Recycled Rubber Flooring to 111, Fitness Room	Φ	3,406.00	Great Lakes	
	Furnish & Install 4" Mannington 1/8" Gauge Black Brown Vinyl Cove Base	\$	3 430 00	Great Lakes	
	Furnish & Install Mapei Aqua Defense Waterproofing Membrane with	*	0,100.00		
	Mapei Aqua Defense 6" Reinforcing	\$	3,792.00	Great Lakes	
	Fabric as necessary to all shower floors and walls only	¥	0,102.00		
	Deduct Base Bid Flooring	\$		Great Lakes	
	Net Savings	\$	(2,994.00)	Great Lakes	
00005	Silicone & Caulking - Deduct Concrete Apron Control Joints	\$	(10 342 50)	Lundman Group	
	ALTERNATES SUBTOTA		(10,042.00)	cananan oroup	
#	ALTERNATE SUBTOTAL	S	VALUES	NOTES	
	Total with Selected Alternates	æ	12.7		
	CM Fee = %6 Bonding	\$			
	General Liability Insurance	\$			
	Alternate Subtotals	\$			

PROJECT TOTAL \$6,933,513.82