

Marion County Sheriff's Office

Post Office Box 1987
Ocala, Florida 34478-1987

COPY

5/26/2026

RECEIPT # 57451

CASH RECEIPT

<u>Received From:</u>	<u>Payment Type</u>	<u>Reference #</u>	<u>Amount Received</u>
FLORIDA SHERIFF'S RISK MANAGEMENT	Check	0146096	14,686.36

Description:

VEH DAMAGE REIMBURSEMENT UNASSIGNED VEH # 59816 CASE # EV2026098166 / RASNICK VEH # 37537 CASE # EV2026098131

115-0000-000 208000.000 DUE TO BOCC

14686.36

FL Sheriffs Risk Mgmt Fund

To: Marion County S.O.

RECEIVED
SA 5.26.26

MAR1000

Check Number:

0000146096

Date:

05/19/2026

Claimant/Memo	Claim Number	Invoice No./Ref	Loss/Service Dates	Payment Code	Paid Amount
Marion EV2026098131 - B. Pompey Unit #37537	APHD20260104831				2010-\$14,300.00
Marion EV2026098166 - K. Sparkman Unit 59816	APHD20260104859	8270			2020-\$386.36

TOTALS:

\$14,686.36

WARNING - THIS CHECK IS PROTECTED BY SPECIAL SECURITY FEATURES

FL Sheriffs Risk Mgmt Fund
2750 Chancellorsville Drive
Tallahassee, FL 32312

Trulst
Tallahassee, FL 32317-2090

63-9138/2631

0000146096

DATE
05/19/2026

PAY Fourteen Thousand Six Hundred Eighty Six Dollars and 36 Cents



AMOUNT

\$14,686.36

TO THE
ORDER OF Marion County Sheriff's Office

VOID AFTER 90 DAY:

P.O. Box 1987
Ocala, FL 34478

SECURITY FEATURES INCLUDE MICROPRINTING • VOID PANTOGRAPH • ENDORSEMENT BACKER • BROWNSTAIN CHEMICAL REACTANT

FLORIDA SHERIFFS RISK MANAGEMENT FUND
Established 1978 *Protecting Those Who Protect Us*

RECEIVED
MAY 26 2026

May 19, 2026

VIA USPS MAIL

Marion County Sheriff's Office
P.O. Box 1987
Ocala, FL 34478

Re: Our File No.: EV2026098166
Unit.: 59816

Greetings,

This letter confirms that we are issuing a check to the Marion County Sheriff's Office as full and final payment for the windshield claim associated with EV2026098166. With this payment, the total windshield claims amount of \$386.36 is considered fully resolved, and our file is closed

In addition, payment for EV2026098131 is included with this check.

If you have any questions or need additional documentation, please feel free to contact us.

Sincerely,

Ken J. Sparkman
Liability Claims Paralegal

Enclosures: 1 check

Windshield
Veh: 59816 2020 Chevrolet Traverse LT
UNASSIGNED
Date 5-5-26
Dept # 2020

8270

Accurate Auto Glass LLC

9611 sw 155th st
Dunnellon Fl 34432
Florida Registration # MV-65212

352-245-4200

INVOICE DATE

I HAVE COMPARED THE GOODS RECEIVED TO THE DOCUMENT AND NOTE THE FOLLOWING TO BE ACCEPTABLE

Name: _____
Address: _____
City & State: _____
Zip Code: _____
Phone no.s: (H) _____

Name: Reynold David Standa
Address: _____
City & State: _____
Zip Code: _____
Phone no.s: _____
DATE: 5/7/26 SIGNATURE: [Signature]

AGENT	POLICY #	POLY CLAIM #	AUTHORIZED BY AGENT

VEHICLE INFORMATION				TAG #	DATE OF LOSS
YEAR	MAKE	MODEL	VEHICLE ID. #		

City	Inventory #	Description	List Price	Net Price	Amount
		Windshield Repair			386.36

LOCATION OF VEHICLE / COMMENTS
Received vehicle with broken windshield

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW, AND SIGN
 I understand that under state law I am entitled to a written estimate if my final bill will exceed \$150
 I request a written estimate
 I do not request a written estimate as long as the repair cost do not exceed \$ _____
 The shop may not exceed this amount without my written or oral approval
 I do not request a written estimate

Labor	
Sealants / Kit	
Moldings	
Other	
Misc. Materials & Supplies	
SUB TOTAL	
Sales Tax	
Sub Total Before Deductible	
Less Customer Deductible	
TOTAL	<u>386.37</u>

Signed _____ Date _____

CONSISTANT WITH FLORIDA MOTOR VEHICLE REPAIR ACT, F.S. 358.901, 358.9221, I HEREBY ACKNOWLEDGE RECEIPT OF WRITTEN ESTIMATE \$ _____

I WILL NOT ACCEPT WINDSHIELD REPAIR HAVING BEEN GIVEN THE ALTERNATIVE AND HAVING SEEN IT'S EFFECT. X

CASH CHECK CREDIT CARD

HAT / UNIT NO. _____ MILEAGE _____ INSTALLER'S NAME _____

Please Pay to **Accurate Auto Glass** →

FULL SETTLEMENT OF ALL LOSS UNDER YOUR POLICY DESCRIBED ABOVE AND UPON SUCH PAYMENT BEING MADE, ALL CLAIM (AND DEMAND) FOR LOSS AND DAMAGE DESCRIBED ABOVE SHALL BE THEREBY FOREVER DISCHARGED. IF FOR REASONS NOW UNKNOWN, MY POLICY DOES NOT COVER THIS CLAIM, I AGREE TO PAY THE FIRM LISTED ABOVE FOR THE REPAIRS

There will be a finance charge calculated at 1% per month on any outstanding balance carried from this invoice in excess of 30 days. In the event it becomes necessary for Accurate Auto Glass to institute any legal action for the collection of sums due under this invoice, then the purchaser agrees to pay all costs including all reasonable attorney fees incurred.

CUSTOMER SIGNATURE (X) _____ DATE INSTALLED _____

Memorandum

Date: 5/19/2026
To: Stacy Hall, Marion County Sheriff's Office
From: Brittany Pompey
Re: Unit #37537 Total Loss

The information contained in this communication is confidential and intended solely for the use of the addressee and may be subject to an attorney/client privilege and/or exempt from disclosure under the public records laws. Any unauthorized use, disclosure or copying is prohibited and may be unlawful. If you have received this communication in error, please contact the undersigned immediately.

Our Event #: EV2026098131
Check Amount: \$14,300.00

Please see the attached check.

*Trabs # 2605070144
Morgan Rasnick #6714
Veh: 37537 2020 Ford Int SUV
Date - 5.7.26
Dept - 2010*

Mail To:

Marion County Sheriff's Office
Attn: Stacy Hall
P.O. Box 1987
Ocala, FL 34478

Appraisers of Central Florida

JD Power Used Cars/Trucks

407-757-2376
aocf18@outlook.com

Vehicle Information

Vehicle: 2020 Ford Explorer Utility 4D Police AWD 3.3L V6
 Region: Eastern
 Period: May 11, 2026
 VIN: 1FM5K8ABOLGA18276
 Mileage: 70,439
 Weight: 0



JD Power Used Cars/Trucks Values

	Base	Mileage Adj.	Option Adj.	Adjusted Value
Clean Retail	\$15,575	\$1,150	\$75	\$16,800

Selected Options

Rear Parking Sensors

Trade-In/Loan \$75
 Retail \$75

Initial Amount: \$16,800.00
 Less Deductible: \$2,500.00

Ded - 2500.00

Total Amount FSRMF Pays:
 \$14,300.00

\$14,300.00

Payee: Marion CSO



ACF
 P.O. Box 622492, Orlando, FL 32862
 Office: (407) 757-2376
 aocf18@outlook.com

TOTAL LOSS
 Estimate ID
 27802137
 Original
 Claim Number
 EV2026098131

Not An Authorization For repair
 All supplement requests should be sent via email to
 AOCF18@outlook.com, including supporting documents.
 No Supplemental repairs are authorized without approval
 from the Insurance Company.

Owner
 Marion County SO
 690 NW 30th Ave.
 Ocala, FL 34475
 (352) 369-6763 (Work)

Appraiser
 Cannon Hamlin
 Classification
 Field

Florida Sheriffs Risk Management Fu

Loss Type Collision	Claim Number EV2026098131	Adjuster Brittany Pompey (850) 320-6904 (Work) brittany.pompey@fstrmf.org	Deductible \$2,500.00 - Not Waived
Loss Date 05/07/2026	Inspection Site Marion County SO 690 NW 30th Ave Ocala, FL 34475 (352) 369-6763 (Work)	Inspection Date 5/11/2026	

2020 Ford Police Interceptor Utility Fleet 4 Door Utility 3.3L 6 Cyl Gas Injected Base AWD

Exterior Color YZ (Oxford White)	License FL-ZVH70	VIN 1FM5K8AB0LGA18276	Condition Good
Drivable No	Odometer 70439	Production Date 06/2019	Mitchell Service Code 912181
Primary Point of Impact Rear (6)	Secondary Point(s) of Impact Right Rear Corner (5), Left Rear Corner (7)		

Options

Air Conditioning	All Wheel Drive	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)	Auto Air Condition
Automatic Headlights	Auxiliary Input	Bluetooth Wireless Connectivity	Cloth Seat	Cruise Control
Driver Seat With Power Lumbar Support	Driver-Front Air Bag	Dual A/C	Electric Defogger	Electronic Stability Control
First Row Bucket Seat	Left-Curtain Air Bag	MP3 Player	Passenger-Front Air Bag	Power Door Locks
Power Driver Seat	Power Remote Mirror	Power Steering	Power Windows	Privacy Glass
Rear Bench Seat	Rear Gate Wiper	Rear Spoiler	Rearview Camera	Second Row Side Airbag With Head Protection

Options

Side Airbags Steering Wheel Mounted Tilt Steering Wheel Tire Pressure Monitoring Traction Control/Electronic
 Trailer Hitch Audio Control Trip Computer System

Marion County SO | 2020 Ford Police Interceptor Utility Fleet

Parts Profile
ACF Florida
 Parts Profile Version
20.0

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
Exhaust									
1	202133 Rear Exhaust Muffler	Remove / Replace	Body	0.0	New	L1MZ 5230 E	1	\$1,961.94	Yes
2	201925 R Exhaust Muffler Heat Shield	Remove / Replace	Body	0.3#	New	L1MZ 78112B28 A	1	\$175.28	Yes
3	201926 L Exhaust Muffler Heat Shield	Remove / Replace	Body	0.3#	New	L1MZ 78112B28 B	1	\$137.52	Yes
Rocker / Pillars / Floor									
4	201235 R Frt Rocker Scuff Plate	Remove / Install	Body	0.3r	Existing				
5	201236 L Frt Rocker Scuff Plate	Remove / Install	Body	0.3r	Existing				
6	201241 R Frt Door Opening Weatherstrip	Remove / Install	Body	0.4r	Existing				
7	201242 L Frt Door Opening Weatherstrip	Remove / Install	Body	0.4r	Existing				
8	201243 R Upr Ctr Pillar Trim Panel	Remove / Install	Body	0.7r#	Existing				
9	201244 L Upr Ctr Pillar Trim Panel	Remove / Install	Body	0.7r#	Existing				
10	201253 R Lwr Ctr Pillar Trim Panel	Remove / Install	Body	INCr	Existing				
11	201229 L Lwr Ctr Pillar Trim Panel	Remove / Install	Body	INCr	Existing				
12	201263 R Rear Rocker Scuff Plate	Remove / Install	Body	INCr	Existing				
13	201230 L Rear Rocker Scuff Plate	Remove / Install	Body	INCr	Existing				
14	201275 R Rear Door Opening Weatherstrip	Remove / Install	Body	INCr	Existing				
15	201276 L Rear Door Opening Weatherstrip	Remove / Install	Body	INCr	Existing				
Front Door									
16	200629 R Frt Door Assembly	Remove / Install	Body	0.7	Existing				
17	200630 L Frt Door Assembly	Remove / Install	Body	0.7	Existing				
Rear Door									
18	200649 R Rear Door Outside	Blend	Refinish	1.2 C	Existing				
19	200650 L Rear Door Outside	Blend	Refinish	1.2 C	Existing				
20	200655 R Rear Door Assembly	Remove / Install	Body	0.7	Existing				
21	200656 L Rear Door Assembly	Remove / Install	Body	0.7	Existing				

Line #	Description	LABOR			PART					
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax	
22	200659 R Rear Otr Door Belt Moulding	Remove / Install	Body	0.3	Existing					
23	200660 L Rear Otr Door Belt Moulding	Remove / Install	Body	0.3	Existing					
24	200661 R Rear Door Trim Panel	Remove / Install	Body	INC	Existing					
25	200662 L Rear Door Trim Panel	Remove / Install	Body	INC	Existing					
26	200663 R Rear Door Frame Mldg	Remove / Install	Body	0.6#	Existing					
27	200664 L Rear Door Frame Mldg	Remove / Install	Body	0.6#	Existing					
28	201728 R Rear Otr Door Handle	Remove / Install	Body	0.3	Existing					
29	201729 L Rear Otr Door Handle	Remove / Install	Body	0.3	Existing					
Quarter Panel										
30	200677 L Fuel Door	Blend	Refinish	INC# C	Existing					
31	200785 R Quarter Outer Panel	Remove / Replace	Body	23.2	New	NB5Z 78278A92 A	1	\$1,363.97	Yes	
32	AUTO R Quarter Panel Outside	Refinish Only	Refinish	2.4 C						
33	AUTO R Quarter Panel Edge	Refinish Only	Refinish	0.5 C						
34	AUTO R Add For Pillar	Refinish Only	Refinish	0.5 C						
35	AUTO R Add To R&I/R&R Side Curtain Air Bags-M	Remove / Replace	Mechanical	0.8						
36	200791 L Quarter Outer Panel	Remove / Replace	Body	23.7	New	NB5Z 78278A93 A	1	\$1,363.97	Yes	
37	AUTO L Quarter Panel Outside	Refinish Only	Refinish	2.0 C						
38	AUTO L Quarter Panel Edge	Refinish Only	Refinish	0.5 C						
39	AUTO L Add For Pillar	Refinish Only	Refinish	0.5 C						
40	AUTO L Add To R&I/R&R Side Curtain Air Bags-M	Remove / Replace	Mechanical	0.8						
41	202130 R Quarter Rear Wheelhouse Liner	Remove / Replace	Body	INC	New	MB5Z 78278B50 A	1	\$253.58	Yes	
42	202131 L Quarter Rear Wheelhouse Liner	Remove / Replace	Body	INC	New	MB5Z 78278B51 A	1	\$253.58	Yes	
43	200688 R Quarter Panel Moulding	Remove / Install	Body	INC#	Existing					
44	201059 L Quarter Moulding	Remove / Replace	Body	INC#	New	LB5Z 78291A09 AA	1	\$86.07	Yes	
45	201084 R Quarter Wheel Opening Mldg	Remove / Replace	Body	INC	New	LB5Z 7829038 AA	1	\$120.37	Yes	
46	201085 L Quarter Wheel Opening Mldg	Remove / Replace	Body	INC	New	LB5Z 7829039 AA	1	\$120.42	Yes	
47	200692 R Lwr Quarter Trim Panel	Remove / Install	Body	INC#	Existing					
48	201095 L Lwr Quarter Trim Panel	Remove / Replace	Body	INC#	New	LB5Z 7831013 CC	1	\$458.67	Yes	
49	201102 R Frt Upr Quarter Trim Panel	Remove / Install	Body	INC#	Existing					

Line #	Description	LABOR			PART					
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax	
50	201103 L Frt Upr Quarter Trim Panel	Remove / Install	Body	INCr#	Existing					
51	201106 R Rear Upr Quarter Trim Panel	Remove / Install	Body	INCr	Existing					
52	201107 L Rear Upr Quarter Trim Panel	Remove / Install	Body	INCr	Existing					
Quarter Glass										
53	200694 R Quarter Glass	Remove / Install	Glass	0.3#	Existing					
54	200456 L Qtr Glass Stationary	Remove / Replace	Glass	1.5#	New	LB5Z 7829701 B	1	\$340.68	Yes	
Liftgate										
55	200490 Liftgate Shell	Remove / Replace	Body	6.7	New	LB5Z 7840010 A	1	\$1,002.07	Yes	
56	AUTO Liftgate Outside	Refinish Only	Refinish	2.2 C						
57	AUTO Add For Liftgate Inside	Refinish Only	Refinish	1.3 C						
58	200849 Liftgate Spoiler	Remove / Install	Body	INC#	Existing					
59	200850 Liftgate Moulding	Remove / Install	Body	INC#	Existing					
60	200564 Inr Liftgate Moulding	Remove / Replace	Body	INC#	New	LB5Z 7842512 BA	1	\$755.97	Yes	
61	200522 Liftgate Adhesive Emblem	Remove / Replace	Body	0.1	New	LB5Z 9942528 A	1	\$32.72	Yes	
62	200523 Liftgate Adhesive Nameplate	Remove / Replace	Body	0.1	New	LB5Z 7842528 A	1	\$28.82	Yes	
63	200507 Liftgate Adhesive Nameplate	Remove / Replace	Body	0.1	New	LB5Z 7842528 C	1	\$30.00	Yes	
64	200851 Lwr Liftgate Trim Panel	Remove / Install	Body	INC#	Existing					
65	200853 R Liftgate Trim Panel	Remove / Install	Body	INC#	Existing					
66	200854 L Liftgate Trim Panel	Remove / Install	Body	INC#	Existing					
67	200852 Upr Liftgate Trim Panel	Remove / Install	Body	INC	Existing					
Rear Body										
68	200740 Rear Body Panel (HSS)	Remove / Replace	Body	7.4#	New	LB5Z 7840320 A	1	\$155.68	Yes	
69	AUTO Rear Body Panel	Refinish Only	Refinish	1.6 C						
70	AUTO Add For Edge & Inside	Refinish Only	Refinish	1.0						
71	200741 Rear Body Inner Panel	Remove / Replace	Body	7.2#	New	LB5Z 7840320 B	1	\$396.15	Yes	
72	200742 Rear Body Rear Floor Pan	Remove / Replace	Body	29.3#	New	L1MZ 7811215 A	1	\$1,545.27	Yes	
Rear Lamps										
73	200963 R Rear Combination Lamp Assembly	Remove / Replace	Body	INC#	Qual Recycled Part		1	\$443.50*	Yes	
74	900501 LKQ 1-800-541-3011									
75	200964 L Rear Combination Lamp Assembly	Remove / Replace	Body	INC#	Qual Recycled Part		1	\$516.50*	Yes	
76	900501 LKQ 1-800-541-3011									

Line #		Description	LABOR			PART					
			Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax	
77	AUTO	L Lwr Quarter Trim Panel	Remove / Install	Body	INC#						
Rear Bumper											
78	AUTO	Rear Bumper Cover Assy	Overhaul	Body	1.4#	Existing					
79	200797	Rear Upr Bumper Cover	Remove / Replace	Body	INC#	New	LB5Z 17810 BCPTM	1	\$322.07	Yes	
80	AUTO	R Rear Combination Lamp	Remove / Install	Body	INC#						
81	AUTO	L Rear Combination Lamp	Remove / Install	Body	INC#						
82	AUTO	Rear Upr Bumper Cover	Refinish Only	Refinish	2.5 C						
83	202205	Rear Bumper Step Pad Set	Remove / Replace	Body	0.0	New	LB5Z 17B807 A	1	\$100.00	Yes	
84	200806	R Rear Bumper Bracket	Remove / Replace	Body	INC#	New	LB5Z 17D942 C	1	\$39.62	Yes	
85	AUTO	Rear Bumper Cover	Remove / Install	Body	INC#						
86	200807	L Rear Bumper Bracket	Remove / Replace	Body	INC#	New	LB5Z 17D943 C	1	\$40.73	Yes	
87	200812	Rear Upr Bumper Isolator	Remove / Replace	Body	INC#	New	LB5Z 17E855 D	1	\$125.30	Yes	
88	202204	Rear Bumper Reinf/Hitch	Remove / Replace	Body	0.8#	New	MB5Z 17D826 B	1	\$1,051.02	Yes	
Additional Costs & Materials											
89	AUTO	Paint/Materials	Additional Cost						\$716.40	Yes	
90	936012	Hazardous Waste Disposal	Additional Cost						\$3.50*		
91	936016	Weld Thru Primer	Additional Cost						\$15.00*		
Additional Operations											
92	AUTO	Clear Coat	Additional Operation	Refinish	2.5*				\$0.00		
93	931127	Pre Repair Scan	Additional Operation	Mechanical	0.5*				\$0.00		
94	931128	Post Repair Scan	Additional Operation	Mechanical	0.5*				\$0.00		
95	933018	Mask For Overspray	Additional Operation	Refinish	0.2*				\$10.00*		
96	933005	Restore Corrosion Protection	Additional Operation	Body	0.2*				\$10.00*		
97	933006	Frame/Rack Set Up	Additional Operation	Frame	2.0*				\$0.00		
98	933035	Unibody Pull	Additional Operation	Frame	2.0*				\$0.00		
Special / Manual Entry											
99	900500	Glass Kit (Each Panel)	Remove / Replace	Glass*	0.0*	Aftermarket New		1	\$25.00*		
100	900500	Seam Sealer	Remove / Replace	Body*	0.0*	Aftermarket New		1	\$25.00*		
101	900501	Labor Inc Per P-Pages									
102	900500	Drill and Install Strobe Lamp	Additional Labor	Body*	0.5*	Existing		0			
103	900500	Strobe Lamp	Remove / Install	Body*	0.5*	Existing		0			

Line #	Description	LABOR			PART				
		Operation	Type	Total Units	Type	Number	Qty	Total Price	Tax
104	900500 Rear Seat Cage Divider	Remove / Install	Body*	2.5*	Existing		0		
105	900500 One Piece Rear Seat	Remove / Install	Body*	2.5*	Existing		0		
106	900500 Rear Vault	Remove / Install	Body*	4.0*	Existing		0		
107	900500 Police Decal Qtr Panel	Remove / Replace	Body*	0.0*	New	ORDER FROM DEALER	1	\$55.00*	
108	900500 Police Decal Rear Gate	Remove / Replace	Body*	0.0*	New	ORDER FROM DEALER	1	\$55.00*	

* Judgment Item
 C Included in Clear Coat Calculation
 T Included in Two Tone Calculation
 A Included in Clear Coat and Two Tone Calculation
 # Labor Note Applies
 r CEG R&R Time Used for this Labor Operation
 d Discontinued by Manufacturer
 [] Verify the part number and price before ordering

Disclaimer: This estimate has been prepared based on the use of crash parts supplied by a source other than the manufacturer of your motor vehicle. The aftermarket crash parts used in the preparation of this estimate are warranted by the manufacturer or distributor of such parts, rather than the manufacturer of your vehicle.

Disclaimer: Recycled part pricing may represent either actual pricing (the price at which the recycler is willing to sell the part for in its existing condition) or undamaged pricing (the price at which the recycler would sell the part if it was in undamaged condition). If you are unsure, please contact the automotive recycler.

Estimate Totals

Labor	Units	Rate	Sublet	Add'l Amount	Totals
Body Labor	118.8	\$54.00		\$10.00	\$6,425.20
Refinish Labor	20.1	\$54.00		\$10.00	\$1,095.40
Glass Labor	1.8	\$54.00			\$97.20
Frame Labor	4.0	\$54.00			\$216.00
Mechanical Labor	2.6	\$85.00			\$221.00
Total Labor	147.3				\$8,054.80
				Taxable	\$8,054.80
				Tax 0.0000%	\$0.00
				Non-Taxable	\$0.00
				Pre-Tax Discount 0.00%	\$0.00
				Labor Total	\$8,054.80
Parts		Amount			
Taxable Parts		\$13,221.47			\$13,221.47
				Parts Adjustments	\$192.00
				Tax 0.0000%	\$0.00
				Non-Taxable	\$160.00
				Pre-Tax Discount 0.00%	\$0.00
				Parts Total	\$13,573.47
Costs		Amount			
Paint Materials		\$716.40			\$716.40
Shop Materials		\$0.00			\$0.00
Other Additional Costs		\$18.50			\$18.50

Estimate Totals

Paint Materials:		Taxable	\$716.40
	- Refinish Units: 19.9 units	Tax 0.0000%	\$0.00
	- Rate: \$36.00	Non-Taxable	\$18.50
	- Rate Max: 99.9 units	Pre-Tax Discount 0.00%	\$0.00
	- Additional Rate: \$0.00	Costs Total	\$734.90
Gross Totals	Amount		
Gross Total	\$22,363.17		\$22,363.17
Adjustments		Taxable	\$22,184.67
	Deductible	Tax	\$0.00
	Total Customer	Non-Taxable	\$178.50
	Responsibility	Pre-Tax Discount 0.00%	\$0.00
		Gross Total	\$22,363.17
			-\$2,500.00
			-\$2,500.00
		Net Estimate Total	\$19,863.17

*****Notice*****

This appraisal is subject to the complete review and approval by the assigning insurance company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. The insurance company listed has the right to accept or reject any part or all of this appraisal or make any changes they feel necessary.

"Failure to use the insurance proceeds in accordance with the security agreement, if any, could be a violation of \diamond 812.014, Florida Statutes. If you have any questions, contact your lending institution." "Any person who knowingly and with intent to injure, defraud, or deceive any insurer files a statement of claim or an application containing any false, incomplete, or misleading information is guilty of a felony of the third degree." "This paragraph shall not apply to reinsurance contracts, reinsurance

agreements, or reinsurance claims transactions.

Disclaimer: Any person who knowingly and with intent to injure, defraud, or deceive any insurer files a statement of claim or an application containing any false, incomplete, or misleading information is guilty of a felony of the third degree.