

CD-PLUS REPORT - Code Case Images

REF KEY 699835
IMAGE DATE 2/6/2014

IMAGE DESCRIPTION
unsafe structure
2285 NW 65th Pl
photo by J Ball
case # 583492JB



REF KEY 699835
IMAGE DATE 7/18/2014

IMAGE DESCRIPTION
contractor removed unsafe structure
2285 NW 65th Pl
photo by J Ball
case # 583492JB

